

| | |
|------------------------|---|
| NO. OF COPIES RECEIVED | 3 |
| DISTRIBUTION | |
| SANTA FE | / |
| FILE | / |
| U.S.G.S. | |
| LAND OFFICE | |
| OPERATOR | / |

RECEIVED

NEW MEXICO OIL CONSERVATION COMMISSION

MAY 27 1969

O. C. C.
ARTESIA, OFFICE

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

| |
|--|
| 5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/> |
| 5. State Oil & Gas Lease No. OG-4760 |
| 7. Unit Agreement Name |
| 8. Farm or Lease Name Sinclair "6" State |
| 9. Well No. 1 |
| 10. Field and Pool, or Wildcat Undes. Buffalo Valley |
| 12. County Chaves |

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

| |
|---|
| 1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry hole |
| 2. Name of Operator Ard Drilling Company |
| 3. Address of Operator c/o Oil Reports and Gas Services, Box 763, Hobbs, New Mexico |
| 4. Location of Well UNIT LETTER E , 1645.8 FEET FROM THE North LINE AND 990 FEET FROM THE West LINE, SECTION 6 TOWNSHIP 15S RANGE 28E NMPM. |
| 15. Elevation (Show whether DF, RT, GR, etc.) 3543 KB |

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JQB ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged and abandoned 4/23/69 as follows:

**Set 15 sack plug across liner slots 8235-8494.
Cut and pulled 3 1/2" casing from 4496.
Set 40 sack plug across 5 1/2" casing stub.
Set 40 sack plug at 3200.
Set 50 sack plug across 8 5/8 shoe at 1844.
Cut and pulled 8 5/8" casing from 1196.
Set 50 sack plug across 8 5/8" casing stub.
Set 65 sack plug across 13 3/8" shoe at 355.
Set 10 sack plug at surface with regulation marker.
Heavy mud between all plugs.**

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

| | | |
|-------------------------------------|--------------------------------------|---------------------|
| SIGNED <u><i>H. L. Smith</i></u> | TITLE <u>Agent</u> | DATE <u>5/26/69</u> |
| APPROVED BY <u><i>R. J. Ham</i></u> | TITLE <u>Oil & Gas Inspector</u> | DATE <u>5/26/69</u> |
| CONDITIONS OF APPROVAL, IF ANY: | | |