

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103

Revised March 23, 1999

OIL CONSERVATION DIVISION

2040 South Pacheco

Santa Fe, NM 87505

WELL API NO.	30-005-60117
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No.	10417-4
7. Lease Name or Unit Agreement Name	Double L Queen Unit Tract 15
	Fed Agree 8910160560
8. Well No.	1
9. Pool name or Wildcat	Double L Queen

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well ☐ Gas Well ☐ Other WTW ☐	
2. Name of Operator	Saga Petroleum LLC
3. Address of Operator	415 W Wall, Suite 1900 Midland, TX 79701
4. Well Location	Unit Letter <u>H</u> : 1980 feet from the <u>N</u> line and 330 feet from the <u>E</u> line Section <u>12</u> Township <u>15S</u> Range <u>29E</u> NMPM County <u>CHAVES</u>
10. Elevation (Show whether DR, RKB, RT, GR, etc.)	<u>3883' GR</u>

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐ OTHER: ☐	SUBSEQUENT REPORT OF: REMEDIAL WORK ☐ ALTERING CASING ☐ COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐ CASING TEST AND CEMENT JOBS ☐ OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work). SEE RULE 1103. For Multiple Completions: Attach diagram of proposed completion or recompletion.

Intent to P&A this SI WTW
MIRU, POOH w/rods, NU BOP, POOH w/tbg (5-1/2" 15.5# csg @ 1986' w/300 sx)
Set CIBP @ 1950' w/35' cmt on top
RIH, circ well w/9.8# mud
POOH to 1300', spot 100' cmt plug, perf 5-1/2" csg @ 1300', squeeze 100' cmt plug inside & outside 5-1/2" csg, tag
POOH to 390', spot 100' cmt plug - perf & squeeze @ 392' - fill annulus w/cmt - tag plug
(8-5/8" 20# csg @ 420' w/232 sx) 420'
Perf 5-1/2" csg @ 50', circ cmt to surface
Cut off WH, install dry hole marker

* Brine Gel between all cement plugs.

Notific M.M.O.C.O. to witness Plugging Operations.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bonnie Husband TITLE Production Analyst DATE 03/23/2001

Type or print name Bonnie Husband

Telephone No. (915) 684-4293

(This space for State use)

APPROVED BY Mike Sweet TITLE Envtl. Eng. Sp. I DATE 2/27/2001

Conditions of approval, if any:

