1. Circulate hole full of good mud.  2. Set 35 sx. cement plug 8450'-8350' 35 sx. cement plug 7035'-6935' 35 sx. cement plug 5270'-5170' 35 sx. cement plug 3115'-3015' 35 sx. cement plug 1755'-1655' 50 sx. cement plug across 8 5/8" stub 65 sx. cement plug 380'-280' 10 sx. cement plug 10'- surface  3. Install regulation marker  4. Clean location.	DATE 6-11-75
<pre>2. Set 35 sx. cement plug 8450'-8350'</pre>	
<pre>2. Set 35 sx. cement plug 8450'-8350'</pre>	
2. Set 35 sx. cement plug 8450'-8350' 35 sx. cement plug 7035'-6935' 35 sx. cement plug 5270'-5170' 35 sx. cement plug 3115'-3015' 35 sx. cement plug 1755'-1655' 50 sx. cement plug across 8 5/8" stub 65 sx. cement plug 380'- 280' 10 sx. cement plug 10'- surface	
2. Set 35 sx. cement plug 8450'-8350' 35 sx. cement plug 7035'-6935' 35 sx. cement plug 5270'-5170' 35 sx. cement plug 3115'-3015' 35 sx. cement plug 1755'-1655' 50 sx. cement plug across 8 5/8" stub 65 sx. cement plug 380'- 280'	
2. Set 35 sx. cement plug 8450'-8350' 35 sx. cement plug 7035'-6935' 35 sx. cement plug 5270'-5170' 35 sx. cement plug 3115'-3015' 35 sx. cement plug 1755'-1655' 50 sx. cement plug across 8 5/8" stub	
2. Set 35 sx. cement plug 8450'-8350' 35 sx. cement plug 7035'-6935' 35 sx. cement plug 5270'-5170' 35 sx. cement plug 3115'-3015'	
2. Set 35 sx. cement plug 8450'-8350' 35 sx. cement plug 7035'-6935' 35 sx. cement plug 5270'-5170'	
2. Set 35 sx. cement plug 8450'-8350' 35 sx. cement plug 7035'-6935'	
2. Set 35 sx. cement plug 8450'-8350'	
1. Circulate noie full of good mud.	
1 Circumlate had cons	
Mr. W. A. Gressett, Artesia OCC, to plug and abandon as follows:	5-10-75, Irom
Drilled 7 7/8" hole from 1710' to 8820'. Received verbal permission	6-10-75 from
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1103.	stimated date of starting any proposed
OTHER	
CHANGE PLANS CASING TEST AND CEMENT JOB	
TEMPORARILY ABANDON COMMENCE DRILLING OPNS.  PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CENERAL LOR	PLUG AND ABANDONMENT
PERFORM REMEDIAL WORK PLUG AND ABANDON X REMEDIAL WORK	ALTERING CASING
SUBSEQUENT	REPORT OF:
Check Appropriate Box To Indicate Nature of Notice, Report or Oth	
3584' GR - 3596' RKB	Chaves
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
THE West LINE, SECTION 7 TOWNSHIP 15-South RANGE 28-East NMPM.	
	Buffalo Valley Penn.
UNIT LETTER M 990' FEET FROM THE SOUTH LINE AND 990' FEET FROM	10. Field and Pool, or Wildcat
P. O. Box 2126, Roswell, New Mexico 88201	1
3. Address of Operator	Blackmar State Com. 9. Well No.
2. Name of Operator  Read & Stevens, Inc.	8. Farm or Lease Name
OIL GAS WELL OTHER. Dry Hole ARTESIA, OFFICE	7. Unit Agreement Name
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)  1.	
SUNDRY NOTICES AND REPORTS ON WELLS	
	5. State Oil & Gas Lease No. K-6844
OPERATOR	State XX Fee
LAND OFFICE (') RECEIVED	5a. Indicate Type of Lease
U.S.G.S.  LAND OFFICE  RECEIVED	Effective 1-1-65
FILE U.S.G.S.	
U.S.G.S.	Form C-103 Supersedes Old C-102 and C-103