		Form C-103
DISTRIBUTION	-	Supersedes Old
SANTA FE	EW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103
FILE		Effective 1-1-65
U.S.G.S.	RECEIVED	5a. Indicate Type of Lease
OPERATOR /	JUN 2 1975	State X Fee
	JUN & 1973	5, State Oil & Gas Lease No.
		К-5110
SUNDRY NOTICE	ES AND REPORTS ON WELLS	
UTE "APPLICATION FOR PERM	AIT -" (FORM C-101) FOR SUCH PROPOSALATESIA. OFFICE	<u></u>
01L - 6AS -		7., Unit Agreement Name
	Dry	-
2. Name of Operator	****	8. Farm or Lease Name
Read & Stevens, Inc. V	·	Harris "16" State
. Address of Operator		9. Well No.
P. O. Box 2126, Roswell, New M	Mexico 88201	2
Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER J 1980	EET FROM THE SOUTH LINE AND 1980 FEET FROM	Undesignated
••••••••••••••••••••••••••••••••••••••	EET FROM THE FEET FROM	ATTITITITITITITITI
East 16	TOWNSHIP 15-South RANGE 29-East	VIIIIIIIIIIIIIIIIIIIIII
LINE, SECTION	TOWNSHIP TO DOUGH RANGE TO BASE NMPM.	XIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII
	5. Elevation (Show whether DF, RT, GR, etc.)	12. County
	3846.4' GR -3848 DF	
Chark Appropriat		Chaves
NOTICE OF INTENTION	te Box To Indicate Nature of Notice, Report or Oth	
NOTICE OF INTENTION	SUBSEQUENT	REPORT OF:
·····		· · · · · · · · · · · · · · · · · · ·
ERFORM REMEDIAL WORK	PLUG AND ABANDON X REMEDIAL WORK	ALTERING CASING
EMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
ULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	
	OTHER	
OTHER		
	early state all pertinent details, and give pertinent dates, including	
Drilled 10" hole from 300' to a scum of oil per hour. Recei	1920'. At 1814', bailed 18 gals. formatived verbal permission from Mr. W. A. Gre	tion water with
Drilled 10" hole from 300' to	1920'. At 1814', bailed 18 gals. formatived verbal permission from Mr. W. A. Gre	tion water with
Drilled 10" hole from 300' to a scum of oil per hour. Recei	1920'. At 1814', bailed 18 gals. formatived verbal permission from Mr. W. A. Gre to plug well as follows:	tion water with
Drilled 10" hole from 300' to a scum of oil per hour. Recei to plug and abandon. Propose	1920'. At 1814', bailed 18 gals. formatived verbal permission from Mr. W. A. Gre to plug well as follows:	tion water with
Drilled 10" hole from 300' to a scum of oil per hour. Recei to plug and abandon. Propose	1920'. At 1814', bailed 18 gals. formatived verbal permission from Mr. W. A. Gre to plug well as follows: nud.	tion water with
Drilled 10" hole from 300' to a scum of oil per hour. Recei to plug and abandon. Propose 1. Fill hole with good m	1920'. At 1814', bailed 18 gals. formatived verbal permission from Mr. W. A. Greto plug well as follows: nud.	tion water with
Drilled 10" hole from 300' to a scum of oil per hour. Recei to plug and abandon. Propose 1. Fill hole with good m 2. Set 35 sx. cement plu	1920'. At 1814', bailed 18 gals. formatived verbal permission from Mr. W. A. Greto plug well as follows: nud. g 1840-1740' g 1075- 975'	tion water with
Drilled 10" hole from 300' to a scum of oil per hour. Recei to plug and abandon. Propose 1. Fill hole with good m 2. Set 35 sx. cement plu 35 sx. cement plu	1920'. At 1814', bailed 18 gals. formatived verbal permission from Mr. W. A. Grato plug well as follows: nud. g 1840-1740' g 1075- 975' g 350- 250'	tion water with
Drilled 10" hole from 300' to a scum of oil per hour. Recei to plug and abandon. Propose 1. Fill hole with good m 2. Set 35 sx. cement plu 35 sx. cement plu 10 sx. cement plu	1920'. At 1814', bailed 18 gals. formatived verbal permission from Mr. W. A. Greato plug well as follows: nud. g 1840-1740' g 1075- 975' g 350- 250' g 10-surface	tion water with
Drilled 10" hole from 300' to a scum of oil per hour. Recei to plug and abandon. Propose 1. Fill hole with good m 2. Set 35 sx. cement plu 35 sx. cement plu 35 sx. cement plu	1920'. At 1814', bailed 18 gals. formatived verbal permission from Mr. W. A. Greato plug well as follows: nud. g 1840-1740' g 1075- 975' g 350- 250' g 10-surface	tion water with
Drilled 10" hole from 300' to a scum of oil per hour. Recei to plug and abandon. Propose 1. Fill hole with good m 2. Set 35 sx. cement plu 35 sx. cement plu 10 sx. cement plu	1920'. At 1814', bailed 18 gals. formatived verbal permission from Mr. W. A. Greato plug well as follows: nud. g 1840-1740' g 1075- 975' g 350- 250' g 10-surface	tion water with
Drilled 10" hole from 300' to a scum of oil per hour. Recei to plug and abandon. Propose 1. Fill hole with good m 2. Set 35 sx. cement plu 35 sx. cement plu 10 sx. cement plu	1920'. At 1814', bailed 18 gals. formatived verbal permission from Mr. W. A. Greato plug well as follows: nud. g 1840-1740' g 1075- 975' g 350- 250' g 10-surface	tion water with
Drilled 10" hole from 300' to a scum of oil per hour. Recei to plug and abandon. Propose 1. Fill hole with good m 2. Set 35 sx. cement plu 35 sx. cement plu 10 sx. cement plu 3. Install regulation mat	1920'. At 1814', bailed 18 gals. formatived verbal permission from Mr. W. A. Greato plug well as follows: nud. g 1840-1740' g 1075- 975' g 350- 250' g 10-surface	tion water with
Drilled 10" hole from 300' to a scum of oil per hour. Recei to plug and abandon. Propose 1. Fill hole with good m 2. Set 35 sx. cement plu 35 sx. cement plu 10 sx. cement plu 3. Install regulation mat	1920'. At 1814', bailed 18 gals. formatived verbal permission from Mr. W. A. Greato plug well as follows: nud. g 1840-1740' g 1075- 975' g 350- 250' g 10-surface	tion water with
Drilled 10" hole from 300' to a scum of oil per hour. Recei to plug and abandon. Propose 1. Fill hole with good m 2. Set 35 sx. cement plu 35 sx. cement plu 10 sx. cement plu 3. Install regulation mat	1920'. At 1814', bailed 18 gals. formatived verbal permission from Mr. W. A. Greato plug well as follows: nud. g 1840-1740' g 1075- 975' g 350- 250' g 10-surface	tion water with
Drilled 10" hole from 300' to a scum of oil per hour. Recei to plug and abandon. Propose 1. Fill hole with good m 2. Set 35 sx. cement plu 35 sx. cement plu 10 sx. cement plu 3. Install regulation mat 4. Clean location.	1920'. At 1814', bailed 18 gals. formatived verbal permission from Mr. W. A. Greato plug well as follows: nud. g 1840-1740' g 1075- 975' g 350- 250' g 10-surface rker.	tion water with
Drilled 10" hole from 300' to a scum of oil per hour. Recei to plug and abandon. Propose 1. Fill hole with good m 2. Set 35 sx. cement plu 35 sx. cement plu 10 sx. cement plu 3. Install regulation mat 4. Clean location.	1920'. At 1814', bailed 18 gals. formatived verbal permission from Mr. W. A. Greato plug well as follows: nud. g 1840-1740' g 1075- 975' g 350- 250' g 10-surface	tion water with
Drilled 10" hole from 300' to a scum of oil per hour. Recei to plug and abandon. Propose 1. Fill hole with good m 2. Set 35 sx. cement plu 35 sx. cement plu 10 sx. cement plu 3. Install regulation mat 4. Clean location.	1920'. At 1814', bailed 18 gals. formatived verbal permission from Mr. W. A. Greato plug well as follows: nud. g 1840-1740' g 1075- 975' g 350- 250' g 10-surface rker.	tion water with
Drilled 10" hole from 300' to a scum of oil per hour. Recei to plug and abandon. Propose 1. Fill hole with good m 2. Set 35 sx. cement plu 35 sx. cement plu 35 sx. cement plu 10 sx. cement plu 3. Install regulation mat 4. Clean location.	1920'. At 1814', bailed 18 gals. formatived verbal permission from Mr. W. A. Greato plug well as follows: and. Mg 1840-1740' Mg 1075- 975' Mg 350- 250' Mg 10-surface rker. and complete to the best of my knowledge and belief.	tion water with essett, 5-22-75,
Drilled 10" hole from 300' to a scum of oil per hour. Recei to plug and abandon. Propose 1. Fill hole with good m 2. Set 35 sx. cement plu 35 sx. cement plu 35 sx. cement plu 10 sx. cement plu 3. Install regulation mat 4. Clean location.	1920'. At 1814', bailed 18 gals. formatived verbal permission from Mr. W. A. Greato plug well as follows: nud. g 1840-1740' g 1075- 975' g 350- 250' g 10-surface rker.	tion water with
Drilled 10" hole from 300' to a scum of oil per hour. Recei to plug and abandon. Propose 1. Fill hole with good m 2. Set 35 sx. cement plu 35 sx. cement plu 35 sx. cement plu 10 sx. cement plu 3. Install regulation mat 4. Clean location.	1920'. At 1814', bailed 18 gals. formatived verbal permission from Mr. W. A. Greato plug well as follows: Mud. Mg 1840-1740' Mg 1075- 975' Mg 350- 250' Mg 10-surface rker. and complete to the best of my knowledge and belief. Mutrix Agent	tion water with essett, 5-22-75,
Drilled 10" hole from 300' to a scum of oil per hour. Recei to plug and abandon. Propose 1. Fill hole with good m 2. Set 35 sx. cement plu 35 sx. cement plu 35 sx. cement plu 10 sx. cement plu 3. Install regulation mat 4. Clean location.	1920'. At 1814', bailed 18 gals. formatived verbal permission from Mr. W. A. Greato plug well as follows: Mud. Mg 1840-1740' Mg 1075- 975' Mg 350- 250' Mg 10-surface rker. and complete to the best of my knowledge and belief. MINE Agent SUPERVISOR, DISTRICT 11	tion water with essett, 5-22-75, DATE <u>5-28-75</u> .JUN 2 1975
Drilled 10" hole from 300' to a scum of oil per hour. Recei to plug and abandon. Propose 1. Fill hole with good m 2. Set 35 sx. cement plu 35 sx. cement plu 35 sx. cement plu 10 sx. cement plu 3. Install regulation mat 4. Clean location.	1920'. At 1814', bailed 18 gals. formatived verbal permission from Mr. W. A. Greato plug well as follows: Mud. Mg 1840-1740' Mg 1075- 975' Mg 350- 250' Mg 10-surface rker. and complete to the best of my knowledge and belief. Mutrix Agent	tion water with essett, 5-22-75,
Drilled 10" hole from 300' to a scum of oil per hour. Recei to plug and abandon. Propose 1. Fill hole with good m 2. Set 35 sx. cement plu 35 sx. cement plu 35 sx. cement plu 10 sx. cement plu 3. Install regulation mat 4. Clean location.	1920'. At 1814', bailed 18 gals. formatived verbal permission from Mr. W. A. Greato plug well as follows: Mud. Mg 1840-1740' Mg 1075- 975' Mg 350- 250' Mg 10-surface rker. and complete to the best of my knowledge and belief. MINE Agent SUPERVISOR, DISTRICT 11	tion water with essett, 5-22-75, DATE <u>5-28-75</u> .JUN 2 1975
Drilled 10" hole from 300' to a scum of oil per hour. Recei to plug and abandon. Propose 1. Fill hole with good m 2. Set 35 sx. cement plu 35 sx. cement plu 35 sx. cement plu 10 sx. cement plu 3. Install regulation mat 4. Clean location.	1920'. At 1814', bailed 18 gals. formatived verbal permission from Mr. W. A. Greato plug well as follows: Mud. Mg 1840-1740' Mg 1075- 975' Mg 350- 250' Mg 10-surface rker. and complete to the best of my knowledge and belief. MINE Agent SUPERVISOR, DISTRICT 11	tion water with essett, 5-22-75, DATE <u>5-28-75</u> .JUN 2 1975
Drilled 10" hole from 300' to a scum of oil per hour. Recei to plug and abandon. Propose 1. Fill hole with good m 2. Set 35 sx. cement plu 35 sx. cement plu 35 sx. cement plu 10 sx. cement plu 3. Install regulation mat 4. Clean location.	1920'. At 1814', bailed 18 gals. formatived verbal permission from Mr. W. A. Greato plug well as follows: Mud. Mg 1840-1740' Mg 1075- 975' Mg 350- 250' Mg 10-surface rker. and complete to the best of my knowledge and belief. MINE Agent SUPERVISOR, DISTRICT 11	tion water with essett, 5-22-75, DATE <u>5-28-75</u> .JUN 2 1975
Drilled 10" hole from 300' to a scum of oil per hour. Recei to plug and abandon. Propose 1. Fill hole with good m 2. Set 35 sx. cement plu 35 sx. cement plu 10 sx. cement plu 3. Install regulation mat 4. Clean location.	1920'. At 1814', bailed 18 gals. formatived verbal permission from Mr. W. A. Greato plug well as follows: Mud. Mg 1840-1740' Mg 1075- 975' Mg 350- 250' Mg 10-surface rker. and complete to the best of my knowledge and belief. MINE Agent SUPERVISOR, DISTRICT 11	tion water with essett, 5-22-75, DATE <u>5-28-75</u> JUN 2 1975