	3	•	Form C-103
1). OF COPIES RECEIVED	 -	·	Supersedes Old
DISTRIBUTION		TON COUNTERION	C-102' and C-103 Effective 1-1-65
SANTA FE	NEW MEXICO OIL CONSE		-9
FILE		SECEIVE	5a. Indicate Type a. Lease
U.S.G.\$.	4		State X Fee
LAND OFFICE	4	JUN 2 1975	5. State Oil & Gas Lease No.
OPERATOR	1	0011 2 1070	K-5110
CANADA	NA NOTICES AND DEPORTS ON	WELLS O C C	
SUNDI (DO NOT USE THIS FORM FOR PR USE "APPLICAT	RY NOTICES AND REPORTS ON OPERALS TO DRILL OR TO DEEPEN OR PLUG BY TION FOR PERMIT —" (FORM C-101) FOR SUCH	ACK TO A DIFFERENT RESERVOIR.	7. Unit Agreement Name
OIL GAS WELL WELL	other- Dry	No.	-
2. Name of Operator			8. Farm or Lease Name
Read & Stevens, Inc.			Harris "16" State
3. Address of Operator			9. Well No.
P. O. Box 2126, Roswe	11, New Mexico 88201		2
4. Location of Well		1000	10. Field and Pool, or Wildcat
UNIT LETTER	980 FEET FROM THE South	LINE ANDFEET	Undesignated
THE East LINE, SECTION 16 TOWNSHIP 15-South RANGE 29-East NMPP		MPM. (
			12. County
	15. Elevation (Show whether		Chaves
	3946.4' GR - 384 Appropriate Box To Indicate N		
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER	PLUG AND ABANDON	REMEDIAL WORK COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB OTHER	ALTERING CASING PLUG AND ABANDONMENT
PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed (CHANGE PLANS	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB OTHER	i - i
OTHER 17. Describe Proposed or Completed (work) SEE RULE 1 103.	CHANGE PLANS Operations (Clearly state all pertinent det	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB OTHER ails, and give pertinent dates, inc.	PLUG AND ABANDONMENT
OTHER 17. Describe Proposed or Completed (work) SEE RULE 1 103.	CHANGE PLANS	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB OTHER ails, and give pertinent dates, inc.	PLUG AND ABANDONMENT
OTHER 17. Describe Proposed or Completed (work) SEE RULE 1 fo3. TD 1920 sh. & anhy.	CHANGE PLANS Operations (Clearly state all pertinent det	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB OTHER ails, and give pertinent dates, inc.	PLUG AND ABANDONMENT
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed (work) SEE RULE 1 fos. TD 1920 sh. & anhy. 1. Filled hole	CHANGE PLANS Operations (Clearly state all pertinent det Plugged and abandoned w with good mud.	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB OTHER ails, and give pertinent dates, inc.	PLUG AND ABANDONMENT
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed (work) SEE RULE 1 fos. TD 1920 sh. & anhy. 1. Filled hole 2. Set 35 sx. (CHANGE PLANS Operations (Clearly state all pertinent det Plugged and abandoned w with good mud. cement plug 1840'-1740'	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB OTHER ails, and give pertinent dates, inc.	PLUG AND ABANDONMENT
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed (work) SEE RULE 1703. TD 1920' sh. & anhy. 1. Filled hole 2. Set 35 sx. (35 sx. (CHANGE PLANS Operations (Clearly state all pertinent det Plugged and abandoned w with good mud. cement plug 1840'-1740' cement plug 1075'- 975'	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB OTHER ails, and give pertinent dates, inc.	PLUG AND ABANDONMENT
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed (work) SEE RULE 1 103. TD 1920' sh. & anhy. 1. Filled hole 2. Set 35 sx. (35 sx. (35 sx. (35 sx. (CHANGE PLANS Operations (Clearly state all pertinent det Plugged and abandoned w with good mud. cement plug 1840'-1740'	commence drilling opns. casing test and cement Jqb other ails, and give pertinent dates, income cell as follows:	PLUG AND ABANDONMENT
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed (work) SEE RULE 1 fos. TD 1920 sh. & anhy. 1. Filled hole 2. Set 35 sx. (35 sx. (10 sx. (Plugged and abandoned w with good mud. cement plug 1840'-1740' cement plug 1075'- 975' cement plug 350'- 250' cement plug 10'-surface	commence drilling opns. casing test and cement Jqb other ails, and give pertinent dates, income cell as follows:	PLUG AND ABANDONMENT
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed (work) SEE RULE 1 fos. TD 1920' sh. & anhy. 1. Filled hole 2. Set 35 sx. (35 sx. (10 sx. (35	Plugged and abandoned w with good mud. cement plug 1840'-1740' cement plug 1075'- 975' cement plug 350'- 250' cement plug 10'-surface egulation marker.	commence drilling opns. casing test and cement JQB other ails, and give pertinent dates, inc. cell as follows:	PLUG AND ABANDONMENT
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed (work) SEE RULE 1703. TD 1920' sh. & anhy. 1. Filled hole 2. Set 35 sx. (35 sx. (10 sx. (4. Will notify	Plugged and abandoned w with good mud. cement plug 1840'-1740' cement plug 1075'- 975' cement plug 350'- 250' cement plug 10'-surface egulation marker. when location is cleaned	commence drilling opns. casing test and cement JQB other ails, and give pertinent dates, inc. cell as follows:	PLUG AND ABANDONMENT
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed (work) SEE RULE 1703. TD 1920' sh. & anhy. 1. Filled hole 2. Set 35 sx. (35 sx. (10 sx. (4. Will notify	Plugged and abandoned w with good mud. cement plug 1840'-1740' cement plug 1075'- 975' cement plug 350'- 250' cement plug 10'-surface egulation marker. when location is cleaned	commence drilling opns. casing test and cement JQB other ails, and give pertinent dates, inc. cell as follows:	PLUG AND ABANDONMENT
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed (work) SEE RULE 1703. TD 1920' sh. & anhy. 1. Filled hole 2. Set 35 sx. (35 sx. (10 sx. (4. Will notify	Plugged and abandoned w with good mud. cement plug 1840'-1740' cement plug 1075'- 975' cement plug 350'- 250' cement plug 10'-surface egulation marker.	commence drilling opns. casing test and cement JQB other ails, and give pertinent dates, inc. cell as follows:	PLUG AND ABANDONMENT
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed of Completed (work) SEE RULE 1703. TD 1920' sh. & anhy. 1. Filled hole 2. Set 35 sx. (35 sx. (10 sx. (4. Will notify	Plugged and abandoned w with good mud. cement plug 1840'-1740' cement plug 1075'- 975' cement plug 350'- 250' cement plug 10'-surface egulation marker. when location is cleaned	commence drilling opns. casing test and cement JQB other ails, and give pertinent dates, inc. cell as follows:	PLUG AND ABANDONMENT
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed of Completed (work) SEE RULE 1703. TD 1920' sh. & anhy. 1. Filled hole 2. Set 35 sx. (35 sx. (10 sx. (4. Will notify	Plugged and abandoned w with good mud. cement plug 1840'-1740' cement plug 1075'- 975' cement plug 350'- 250' cement plug 10'-surface egulation marker. when location is cleaned	commence drilling opns. casing test and cement JQB other ails, and give pertinent dates, inc. cell as follows:	PLUG AND ABANDONMENT
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed (work) SEE RULE 1703. TD 1920' sh. & anhy. 1. Filled hole 2. Set 35 sx. (35 sx. (10 sx. (4. Will notify	Plugged and abandoned w with good mud. cement plug 1840'-1740' cement plug 1075'- 975' cement plug 350'- 250' cement plug 10'-surface egulation marker. when location is cleaned	commence drilling opns. casing test and cement JQB other ails, and give pertinent dates, inc. cell as follows:	PLUG AND ABANDONMENT

Agent

5-28-75