

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-005-60784

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No. K-6772

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☐ OTHER ☐ Injection

2. Name of Operator
Nadel and Gussman Permian, L.L.C.

3. Address of Operator
3200 First National Tower, Tulsa, OK 74103

4. Well Location
Unit Letter B : 1155 Feet From The North Line and 2145 Feet From The East Line
Section 24 Township 14S Range 29E NMPM Chaves County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3809' G.L.

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- See NMOCD letter from Mike Stubblefield, March 31, 1997, ref. MIT of captioned well.
- N&G RU and tested well, found slow leak in casing between 965-977', 05/06/97.
- Called Mr. Brian Arrant (SP?) for permission to set and cap CIBP and for procedure to plug as follows:
 - CIBP above perfs capped w/35' cement, fill casing or hole w/10 ppg 25# gel/bbl mud.
 - 100' plug at base of salt, 1090 ft., tag same (OK if cmt inside 4½" pipe) notify NMOCD to witness.
 - 100' plug 50' below to 50' above base of surface pipe at 410 ft., tag. Notify NMOCD to witness.
 - min 10 sk plug at surface (fill 33' to 3' min)
- Restore surface.
- Abandonment will be complete, file forms.

After setting CIBP, operator WO approval of NMOCD to get bids to plug.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Wayne K. Taylor TITLE Engineer DATE 5/8/97
TYPE OR PRINT NAME Wayne K. Taylor TELEPHONE NO. 918/583-3333

(This space for State Use) ORIGINAL SIGNED BY TIM W. GUM
DISTRICT SUPERVISOR

MAY 27 1997

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: