

Form 3160-5
(November 1983)
(Formerly 9-331)

NEW MEXICO CONS. COMMISSION
Drawer DD
Artesia, NM 88210
SUBMIT IN TRIPLICATE*
UNITED STATES
DEPARTMENT OF THE INTERIOR (Other Instructions on re-
verse side)
BUREAU OF LAND MANAGEMENT

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

45F

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to
a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals.)

1. OIL ☐ GAS ☐
WELL ☐ WELL ☐ OTHER ☒ Dry Hole

2. NAME OF OPERATOR
Read & Stevens, Inc. ✓

3. ADDRESS OF OPERATOR
P.O. Box 1518, Roswell, NM 88201

4. LOCATION OF WELL (Report location clearly and in accordance with State
requirements.* See also space 17 below.)
At surface

1980' FNL and 660' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3515' GR

5. LEASE DESIGNATION AND SERIAL NO.
NM-18826

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
DIAMOND FEDERAL

9. WELL NO.
1

10. FIELD AND POOL, OR WILDCAT
Undesignated Diamond Mound

11. SEC. T., R., M., OR BLK. AND
SURVEY OR AREA
Sec. 33-15S-27E

12. COUNTY OR PARISH
Chaves

13. STATE
NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐ PULL OR ALTER CASING ☐
FRACTURE TREAT ☐ MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☒ ABANDON* ☒
REPAIR WELL ☐ CHANGE PLANS ☐
(Other) ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐ REPAIRING WELL ☐
FRACTURE TREATMENT ☐ ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐ ABANDONMENT* ☐
(Other) ☐
(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including
estimated date of starting any proposed work. If well is directionally drilled give subsurface locations and measured
and true vertical depths for all markers and zones pertinent to this work.)*

- 1). Notify BLM @ 624-1790 before starting plugging operations.
- 2). Set CIBP @ 7250', dump 35' cmt on top of CIBP.
- 3). Circ hole w/salt gel mud.
- 4). Cut csg @ \pm 5000', pull csg, spot 100' plug half in and half out of csg string, 45sx Class "C" cmt, wait 4hrs and tag plug.
- 5). Spot 100' plug, 45sx Class "C" cmt, 2550'-2650', Top of Glorieta.
- 6). Spot 200' plug, 80sx Class "C" cmt, 1600'-1800', across 8 5/8" csg shoe at 1780'.
- 7). Test csg @ 100psi for 30mins.
- 8). Perf 1460'-1475', 15', 4 shots/' , Premier Sand.
- 9). Swab test and acidize w/2000gals, if necessary.

Verbal approval given by Armando Lopez, BLM - Roswell, 622-9042.

I hereby certify that the foregoing is true and correct

SIGNED B. Stubbs

TITLE Drilling & Production Manager

DATE 7/19/85

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED
PETER W. CHESTER
DATE

JUL 29 1985

BUREAU OF LAND MANAGEMENT
ROSWELL RESOURCE AREA

*See Instructions on Reverse Side