

NM OIL CONS. COMMISSION  
Drawer DD  
Artesia, NM 88210

clsf

Form 9-331  
Dec. 1973

RECEIVED BY  
JUN 03 1985  
O.C.D.  
UNITED STATES  
DEPARTMENT OF THE INTERIOR  
ARTESIA OFFICE  
GEOLOGICAL SURVEY

Form Approved.  
Budget Bureau No. 42-R1424

### SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☐ other ☒ Dry & abandoned

2. NAME OF OPERATOR  
Harper Oil Company ✓

3. ADDRESS OF OPERATOR  
904 Hightower Bldg., Oklahoma City, OK 73102

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 330' FSL & 990' FWL  
AT TOP PROD. INTERVAL: Same  
AT TOTAL DEPTH: Same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:	SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF <input type="checkbox"/>	<input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	<input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE <input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES <input type="checkbox"/>	<input type="checkbox"/>
ABANDON* <input type="checkbox"/>	<input checked="" type="checkbox"/>
(other) <input type="checkbox"/>	<input type="checkbox"/>

5. LEASE  
36605

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME  
Lucky 13 Federal

9. WELL NO.  
1

10. FIELD OR WILDCAT NAME  
Wildcat

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
Sec. 19-15S-22E

12. COUNTY OR PARISH  
Chaves

13. STATE  
NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)  
GL 4224.4'

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

11-7-84 WOO. TD 4250'. Reached TD @ 11:30 AM 11-6-84. Circ. & cond. hole. Made short trip, TIH. Circ. & cond. hole. POH. RU Schlumberger. Ran logs, POH. RD WL. TIH.

11-8-84 WOO. Circ. hole. Set 40 sx plug @ 3965'-3865'. LD DP. Set 50 sx plug @ 1085'-960'. TOH. ND BOP. Clean out wellhead. TIH. Tagged plug @ 960'. POH. LD DP. Set 60' plug to surface. Released rig @ 7:30 PM 11-7-84. P & A FINAL REPORT.

Reason for abandonment: Dry

Post TD-2  
2-8-85  
P & A

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Operations Manager DATE 11-30-84

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

APPROVED  
PETER W. CHESTER

MAY 30 1985

BUREAU OF LAND MANAGEMENT  
ROSSELL RESOURCE AREA