

NM OIL CONS. COMMISSION

Drawer DD

Artesia, NM 88210

Form 3-533
(May 1963)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other Instructions on Re-
verse side)

RECEIVED BY

AUG 18 1987

O. C. D.
ARTESIA, OFFICE

Form approved.
Budget Bureau No. 42-R1424.
LEASE DENOTATION AND SERIAL NO.

NM-25638

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different location. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☐ OTHER ☒ Dry Hole	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR McClellan Oil Corporation ✓	8. FARM OR LEASE NAME Clarkyle Fed.
3. ADDRESS OF OPERATOR P.O. Drawer 730, Roswell, NM 88202	9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 660' FNL & 1980' FEL	10. FIELD AND POOL, OR WILDCAT Wildcat - 51A
11. PERMIT NO.	11. SEC., T., R., W., OR BLK. AND HURVEY OR AREA
15. ELEVATIONS (Show whether OF, AT, OR, etc.) 3921' G.L.	12. COUNTY OR PARISH Chaves
	13. STATE NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
(Other)

PULL OR ALTER CASING
MULTIPLE COMPLETION
ABANDON*
CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING
(Other)

REPAIRING WELL
ALTERING CASING
ABANDONMENT*

X

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1/22/86: Plugged and abandoned well by setting tubing at 3500' with 2-3/8" tubing and loading hole with salt mud at 10 p.p.g. Set 35 sx Class C plug at 3500'. Set 25 sx plug from 1600'-1950' inside 4-1/2" casing. Set 25 sx plug from 300' to 500'. Pumped 50 sx cement down 4-1/2 - 8-5/8 bradenhead and displaced to 350'. Set 10 sx plug at surface. Installed dry hole marker. Will clean and rip location after pits dry.

18. I hereby certify that the foregoing is true and correct

SIGNED

Paul R. Lyndale

TITLE Operations Manager

DATE 1/23/86

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED
PETER W. CHESTER
DATE

AUG 11 1987

BUREAU OF LAND MANAGEMENT
ROSWELL RESOURCE AREA

*See Instructions on Reverse Side