Form 9-331 Drawer DD	Form Approved.
Form 9-331 Dec. 1973 UNITED STATESArtosia, NM 88210	Budget Bureau No. 42–R1424
UNITED STATESATURAT	5. LEASE
DEPARTMENT OF THE INTERIOR	NM 57256
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plus back to different reservoir, Use Form 9-331-C for such proposals.) RECEIVED	7. UNIT AGREEMENT NAME
reservoir, use form 9-331-C for such proposals.) KECEIVED	-
1. oil gas well I well other	Read-Federal 9. WELL NO.
2. NAME OF OPERATOR AUG 28 '87	
Dalport Oil Corporation	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR O. C. D.	Wildcat CHAVES-Q-ASSOC.
3471 InterFirst One, Dallas, Teras, 08102	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA 22-14S-29E
below.) AT SURFACE: 1650' FS & WL	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: Same	Chaves NM
AT TOTAL DEPTH: Same	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REPAIR WELL	(NOTE: Report results of multiple completion or zone change on Form 9–330.)
ABANDON* X 4 X (other)	to all postioned details, and give postions to the
— · •	directionally drilled, give subsurface locations and
(other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statistic including estimated date of starting any proposed work. If well is of the starting any proposed work of the starting any proposed work of the starting any proposed work.	directionally drilled, give subsurface locations and ent to this work.)*
(other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly star including estimated date of starting any proposed work. If well is o measured and true vertical depths for ell merkers and zones pertine	directionally drilled, give subsurface locations and ent to this work.)*
<pre>(other)</pre>	directionally drilled, give subsurface locations and ent to this work.)*
(other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stating including estimated date of starting any proposed work. If well is a measured and true vertical depths for all markers and zones pertine TD 1805', verbal approval to plug given by	directionally drilled, give subsurface locations and ent to this work.)* Peter Chester on 8-11-87.
<pre>(other)</pre>	directionally drilled, give subsurface locations and ent to this work.)* Peter Chester on 8-11-87. e at 185') 3:00 a.m. on 8-12-87. Juill clean
<pre>(other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statisticulding estimated date of starting any proposed work. If well is of measured and true vertical depths for ell morkers and zones pertine TD 1805', verbal approval to plug given by Halliburton plugged as follows: 1800 - 1700 100 foot plug (T.D.) 230 - 130 100 foot (across surface shoe tagged plug Surface - 50 foot plug. Finished plugging</pre>	directionally drilled, give subsurface locations and ent to this work.)* Peter Chester on 8-11-87. e at 185') 3:00 a.m. on 8-12-87. Mill clean arker.
<pre>(other)</pre>	directionally drilled, give subsurface locations and ent to this work.)* Peter Chester on 8-11-87. e at 185') 3:00 a.m. on 8-12-87. Mill clean arker.
<pre>(other)</pre>	directionally drilled, give subsurface locations and ent to this work.)* Peter Chester on 8-11-87. e at 185') 3:00 a.m. on 8-12-87. Mill clean arker. Set @Ft Post F 9-25
<pre>(other)</pre>	directionally drilled, give subsurface locations and ent to this work.)* Peter Chester on 8-11-87. at 185') 3:00 a.m. on 8-12-87. MINICO Set @Ft. 7-25 DATE flice use)
<pre>(other)</pre>	directionally drilled, give subsurface locations and ent to this work.)* Peter Chester on 8-11-87. e at 185') 3:00 a.m. on 8-12-87. Mill clean marker. Set @Ft 
<pre>(other)</pre>	directionally drilled, give subsurface locations and ent to this work.)* Peter Chester on 8-11-87. e at 185') 3:00 a.m. on 8-12-87. Mill clean marker. Set @Ft 
<pre>(other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly star including estimated date of starting any proposed work. If well is o measured and true vertical depths for all merkers and zones pertine TD 1805', verbal approval to plug given by Halliburton plugged as follows: 1800 - 1700 100 foot plug (T.D.) 230 - 130 100 foot (across surface shoe tagged plug Surface - 50 foot plug. Finished plugging location, level pits, and erect 4' steel ma Subsurface Safety Valve: Manu. and Type 18. I hereby certify that the foregoing is true and correct SIGNED</pre>	directionally drilled, give subsurface locations and ent to this work.)* Peter Chester on 8-11-87. at 185') 3:00 a.m. on 8-12-87. Jacker. DATE
<pre>(other)</pre>	directionally drilled, give subsurface locations and ent to this work.)* Peter Chester on 8-11-87. e at 185') 3:00 a.m. on 8-12-87. Mill clean marker. Set @Ft 
<pre>(other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly star including estimated date of starting any proposed work. If well is o measured and true vertical depths for all merkers and zones pertine TD 1805', verbal approval to plug given by Halliburton plugged as follows: 1800 - 1700 100 foot plug (T.D.) 230 - 130 100 foot (across surface shoe tagged plug Surface - 50 foot plug. Finished plugging location, level pits, and erect 4' steel ma Subsurface Safety Valve: Manu. and Type 18. I hereby certify that the foregoing is true and correct SIGNED</pre>	directionally drilled, give subsurface locations and ent to this work.)* Peter Chester on 8-11-87. at 185') 3:00 a.m. on 8-12-87. Jacker. DATE MEXUAL Set @ MEXUAL Set @ MEXUAL MEXUAL Set @ MEXUAL MEXUAL Set @ MEXUAL MEXUAL Set @ MEXUAL MEXUAL Set @ MEXUAL MEXUAL Set @ MEXUAL MEXUAL Set @ MEXUAL Set @ MEXUAL Set @ MEXUAL MEXUAL Set @ MEXUAL MEXUAL Set @ MEXUAL Set @ MEXUAL Set @ MEXUAL MEXUAL Set @ MEXUAL MEXUAL Set @ MEXUAL M