(This space for State Use) (This space for State Use)				0126
PD. Bar 190, 1666, KM 88240 F.O. Box 2088 DESTRICLI Santa Fe, New Mexico 87504-2088 SIDERCELI Santa Fe, New Mexico 87504-2088 SUBSPECTI Santa Fe, New Mexico 87504-2088 SUBSPECTI Sub 018 cut Later, NM 88210 SUNDARY NOTICES AND REPORTS ON WELLS	to Appropriate	•••••••••••••••••••••••••••••••••••••••		<i>.</i>
PD. Dream DD. Antexi, DM 88210 State W DISTRICT III State MA Antex, NM 87410 DO NO USE THE FORM FOR PROPOSALS TO DUPLL OR TO DEFFER QECENTED.X TOA State W & Constraints on the state of t	DI <u>STRICT 1</u> P.O. Box 1980, Hobbs, NM 88240	P.O. Box 208	3	WELL API NO.
DISTRICTURE 6. Saie OR 6 On Lear No. IDESTRICTURE SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM ACH PHODOSALS TO ENTLL OR TO DEFERSE GEODEDED X TO A IDEFERSION USE AND REPORTS ON WELLS (DO NOT USE THIS FORM ACH PHODOSALS TO ENTLL OR TO DEFERSE GEODEDED X TO A (DO NOT USE THIS FORM ACH PHODOSALS TO ENTLL OR TO DEFERSE GEODEDED X TO A (DO NOT USE THIS FORM CONTROLOGIES ON WELLS (DO NOT USE THIS FORM CONTROLOGIES ON WELLS) (DO NOT USE THIS FORM CONTROLOGIES ON THE CONT	DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088			5. Indicate Type of Lease
(DO NOT USE THIS FORM FOR PROPOSALS TO DEPLICE NO FOR EXAMPLE 1. Lesse Name or Unit Agreement Name 1. Type of Weil (FORM C-101) FOR SUCH PROPOSALS) 1. Lesse Name or Unit Agreement Name 2. Name of Openator C. C. D. 8. Well No. 2. Name of Openator C. C. D. 8. Well No. 3. Addess of Openator C. C. D. 8. Well No. 3. Addess of Openator Diamond Mound/Atoxa/Atug/ 4. Weil Location Diamond Mound/Atoxa/Atug/ 4. Weil Location Unit Letter _ L. : 1980 - Feet From The South Liae and	DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No.
Owner FED UP UP State "ET" 2 Name of Operator C. C. D. 8. Well No. 3 Address of Operator C. C. D. 8. Well No. 3 Address of Operator 9. Pool name of Wildest 2 3 Makes of Operator 9. Pool name of Wildest 2 4. Woll Location 1. 1980. Feel From The South Line and 660. Feel From The West Line 6. Construction 1. 1980. Feel From The South Line and 660. Feel From The West Line 6. Construction 15. SouthRame: 27 East NNIM Chaves Common 7. Operating 15. SouthRame: 27 East NNIM Chaves Common Common 9. Pool name of Wildest 10. Elevation (Motion of Motion of Moti	(DO NOT USE THIS FORM FOR PF DIFFERENT RESE	ROPOSALS TO DRILL OR TO DEEPEN (ERVOIR. USE "APPLICATION FOR PER	RECENTED CK TO A	7. Lease Name or Unit Agreement Name
2. Name of Operator C. C. D. B. Well No. 3. Addres of Operator BOI S. Fillmore Suite 450 Amarillo, Tx 79101 Bimmond Mound/Toca/it/b2/ 4. Well Location BOI S. Fillmore Suite 450 Amarillo, Tx 79101 Diamond Mound/Toca/it/b2/ 4. Well Location Usit Letter _ L : 1980. Feet From The South Line and 660. Feet From The West Line SouthRange 27 East NAME 5. Section 36 Tearchigh 15 SouthRange 27 East NAME NAME of Other Data 3. NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING PULL OR ALTER CASING COMMENCE DRILLING OPNS X PLUG AND ABANDON PULL OR ALTER CASING COMMENCE DRILLING OPNS X PLUG AND ABANDON 12. Decide Proposed or Completed Openators (Clearly state all perioder data, ord pro primeri data, including estimated data of stating any proposed were to all the stating of the state of stating any proposed were to all the state of the		1	FEB 02 '89	
Foran Oil Company/ 2 1 Address of Opentod 9. Pool name of Wides 21 Address of Opentod 9. Pool name of Wides 23 Address of Opentod 9. Pool name of Wides 24 Weil Location 1980 Feet From The South Lise and 660 Feet From The West Line 25 Weil Leaston 10 Exciting (Kay show the MERE RT, GR, er.) 3598.'9 GR Comp 10 Exciting (Kay show the MERE RT, GR, er.) 26 Weil Leaston 10 Exciting (Kay show the MERE RT, GR, er.) 3598.'9 GR NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS Commence Defluting GANNA PLUG AND ABANDON PULL OR ALTER CASING Commence Defluting OPNS PLUG AND ABANDON CHANGE PLANS PLUG AND ABANDON PULL OR ALTER CASING Commence Defluting OPNS PLUG AND ABANDON CASING TEST AND CEMENT JOB X PLUG AND ABANDONIMENT PULL OR ALTER CASING Commence Opentions (Clearly state all perinters data), and give perinters data: including aximing any properted Work) SEE RULE 1003. Moved in and rigged up rotary tools and spudded well with 17 1/2" hole at 12:45 PM MST, 1-5-89. Drill to a depth of 350' with no loss of circulation. Run 9 joints, 354' of 13 3/8", 48# H-40 ST&C Rg-3 casing. Texas pattern guide shoe @ 350', Insert float @ 310'.		j Office	C. C. D	
801 S. Fillmore Suite 450 Amarillo, Tx 79101 Diamond Mound/ATox(4/10)(2) 4. Well Location Line Letter L : 1980 Feet From The South Line and 660 Feet From The West Line Section 36 Feet From The South The South Response 27 East NMTM Chaves County 10. Elevation (Show whether D), REB, RT, GR, etc.) South Response 27 East NMTM Chaves County 10. Elevation (Show whether D), REB, RT, GR, etc.) 3598.4 GR The Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PEEFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK Altering CASING PULL OR ALTER CASING CHANGE PLANS COMMENCE DRILLING OPNS. X PLUG AND ABANDON PULL OR ALTER CASING CHANGE PLANS OTHER. OTHER. OTHER. 12. Describe Proposed or Completed Operations (Clearly state all periversi desite, and give perimeral date. Including estimated date of starting any proposed work) SEE RULE 1103. Moved in and rigged up rotary tools and spudded well with 17 1/2". Nole at 12:45 PM MST, 1-5-89. Drill to a depth of 350' with no loss of circulation. Run 9 joints, 354' of 13 3/8", 48# H-40 STAC Rg-3 casing. Texas pattern guide shoe 6 350', Insert float 6 310'. Cemented with 350 sx Class "C" + 2% CaCl2. Circulated 50 sx. to the pit. Witnessed by NNOCD Mike Stubblefield. NOC for 12 hours and test casing to 600# for 30 min. with no pressure drop. Theely cody bad be information shows is the and complete to theter of my how bette end held. <tr< td=""><td>Foran Oil C</td><td>ompany</td><td></td><td></td></tr<>	Foran Oil C	ompany		
4. Weil Location Unit Letter Lie 2010 Lie 2010 <td>•</td> <td>moro Suito 450 Amari'</td> <td>10 Tx 79101</td> <td></td>	•	moro Suito 450 Amari'	10 Tx 79101	
Section 36 Township 15 South Range 27 East NNTM Chaves County 10. Elevation (Skow where DF, RRB, RF, GR, ec.) 3598/% (GR 3598/% (GR	4. Well Location			
Sector 3598.º GR 10. Elevation (Show warther D', RKB, RT, GR, etc.) 3598.º GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING COMMENCE DRILLING OPNS. OTHER: OTHER: COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT REMEDIAL WORK ALTERING CASING OTHER: OTHER: Commence Drilling or Drive of Completed Operations. (Clearly state all perinent details, and give perinent date: incluling estimated date of storing any proposed work) SEE RULE 1103. Moved in and rigged up rotary tools and spudded well with 17 1/2" hole at 12:45 PM MST, 1-5-89. Drill to a depth of 350' with no loss of circulation. Run 9 joints, 354' of 13 3/8", 48# H-40 ST&C Rg-3 casing. Texas pattern guide shoe @ 350', Insert float @ 310'. Cemented with 350 sx Class "C" + 2% CaCl2. Circulated 50 sx. to the pit. Witnessed by NMOCD Mike Stubblefield. WOC for 12 hours and test casing to 600# for 30 min. with no pressure drop. Mike Agent Thereby certing that the information showe is type and camptete to the best of my know ketge and heid.	Unit Letter <u>L</u> : <u>19</u>	80 Feet From The South	Line and 660	Feet From The West Line
1 Discrition (Know whether DF, RKB, RT, GR, etc.) 3598,4 GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PEEFORM REMEDIAL WORK PLUG AND ABANDON ITEMPORARILY ABANDON CHANGE PLANS OTHER: COMMENCE DRILLING OPNS. IL OR ALTER CASING OTHER: OTHER: OTHER: I2. Describe Proposed or Complated Operations (Clearly state all perinent detable, and give perinent dates, including estimated date of stating any proposed Work SEE RULE 1103. Moved in and rigged up rotary tools and spudded well with 17.1/2" hole at 12:45 PM MST, 1-5-89. Drill to a depth of 13 3/8", 48# H-40 ST&C Rg-3 casing. Texas pattern guide shoe @ 350", Insert float @ 310". Cemented with 350 sx Class "C" + 2% CaCl2. Circulated 50 sx. to the pit. Witnessed by NMOCD Mike Stubblefield. WOC for 12 hours and test casing to 600# for 30 min. with no pressure drop. The drop remote the study and test of my how kete and hold. storature H. E. Gene Lee The drop remote the study of Such and the store of the study of Such and test of the study of the	Section 36	Tourship 15 South _{Rat}	ng 27 East	NMFM Chaves County
II. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT OTHER: OTHER: OTHER: COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT 12. Describe Proposed or Completed Operations (Clearly state all perinent deals, and give perinent date: including estimated date of starting any proposed work) SEE RULE 1103. Moved in and rigged up rotary tools and spudded well with 17 1/2" hole at 12:45 PM MST, 1-5-89. Drill to a depth of 350' with no loss of circulation. Run 9 joints, 354' of 13 3/8'', 48# H-40 ST&C Rg-3 casing. Texas pattern guide shoe @ 350', Insert float @ 310'. Cemented with 350 sx Class "C" + 2% CaCl2. Circulated 50 sx. to the pit. Witnessed by NMOCD Mike Stubblefield. WOC for 12 hours and test casing to 600# for 30 min. with no pressure drop. Intervert NAME H. E. Gene Lee THE MER MARE THE MARE THE MARE THE PART AND CHEENER TO 50 START AND CHEENER TO 622-73 (This space for Start Use) Original Signed DY Mike Start DY 100 PART AND		10. Elevation (Show whether I	DF, RKB, RT, GR, etc.)	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT OTHER: OTHER: COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT 12. Describe Proposed or Completed Operations (Clearly state all perimeri dates, including estimated date of starting any proposed work) SEE RULE 1103. Moved in and rigged up rotary tools and spudded well with 17 1/2" hole at 12:45 PM MST, 1-5-89. Drill to a depth of 350' with no loss of circulation. Run 9 joints, 354' of 13 3/8'', 48# H-40 ST&C Rg-3 casing. Texas pattern guide shoe @ 350', Insert float @ 310'. Cemented with 350 sx Class "C" + 2% CaCl2. Circulated 50 sx. to the pit. Witnessed by NMOCD Mike Stubblefield. WOC for 12 hours and test casing to 600# for 30 min. with no pressure drop. Interview drop. Character of Starter H. E. Gene Lee Witness for Start Use) Original Signed P Original Signed P Mike Witness Mite Witness				
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING CASING TEST AND CEMENT JOB X PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB X OTHER: OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, including estimated date of starting any proposed work) SEE RULE 1103. Moved in and rigged up rotary tools and spudded well with 17 1/2" hole at 12:45 PM MST, 1-5-89. Drill to a depth of 350' with no loss of circulation. Run 9 joints, 354' of 13 3/8", 48# H-40 ST&C Rg-3 casing. Texas pattern guide shoe @ 350', Insert float @ 310'. Cemented with 350 sx Class "C" + 2% CaCl2. Circulated 50 sx. to the pit. Witnessed by NMOCD Mike Stubblefield. WOC for 12 hours and test casing to 600# for 30 min. with no pressure drop. I hereby certify that the information above in type and complete to the best of my howledge and belief. storarter M. E. Gene Lee THE Agent THE OR FRINT NAME H. E. Gene Lee TELETHENE NO. 622-73 (This space for State Uke) Criginal Signed P Mike YMILTER				
PERFORMENCE IN INCLUE TO THE INSTITUTE OF THE INFORMATION ADDATES PLUG AND ABANDON PULL OR ALTER CASING CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING Commence DRILLING OPNS. PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. Commence DRILLING OPNS. PLUG AND ABANDONMENT Commence DRILLING OPNS. Commence DRILLING OPNS. PLUG AND ABANDONMENT Commence DRILLING OPNS. Commence DRILLING OPNS. PLUG AND ABANDONMENT Commence DRILLING OPNS. Commence DRILLING OPNS. PLUG AND ABANDONMENT Commence DRILLING OPNS. Commence DRILLING OPNS. PLUG AND ABANDONMENT Commence DRILLING OPNS. Commence DRILLING OPNS. PLUG AND ABANDONMENT Commence DRILLING OPNS. Commence DRILLING OPNS. PLUG AND ABANDONMENT Commence DRILLING OPNS. Commence DRILLING OPNS. PLUG AND ABANDONMENT Commence DRILLING OPNS. Commence DRILLING OPNS. Commence DRILLING OPNS. PLUG AND ABANDONMENT Commence DRILLING OPNS. Commence DRILLING OPNS. Commence DRILLING OPNS. Commence DRILLING OPNS. Commence DRILLING OPNS.		ITENTION TO:	506	
Interformation block Image: Consider to the best of my know kedge and held. PULL OR ALTER CASING Image: Casing TEST AND CEMENT JOB Image: Casing on proposed OTHER: Image: Clearly state all periment details, and give periment dates, including estimated date of starting ony proposed Work SEE RULE 1103. Moved in and rigged up rotary tools and spudded well with 17 1/2" hole at 12:45 PM MST, 1-5-89. Drill to a depth of 350' with no loss of circulation. Run 9 joints, 354' of 13 3/8", 48# H-40 ST&C Rg-3 casing. Texas pattern guide shoe @ 350', Insert float @ 310'. Cemented with 350 sx Class "C" + 2% CaCl2. Circulated 50 sx. to the pit. Witnessed by NMOCD Mike Stubblefield. WOC for 12 hours and test casing to 600# for 30 min. with no pressure drop. Interpreted for the information above is the and complete to the best of my know kedge and held. SIGNATURE M. E. Gene Lee THE Agent THE Agent THE ON FIRENT NAME H. E. Gene Lee		PLUG AND ABANDON	REMEDIAL WORK	
OTHER:		CHANGE PLANS	COMMENCE DRILLIN	G OPNS. X PLUG AND ABANDONMENT
OTHER:	PULL OR ALTER CASING		CASING TEST AND C	EMENT JOB X
work) SEE RULE 1103. Moved in and rigged up rotary tools and spudded well with 17 1/2" hole at 12:45 PM MST, 1-5-89. Drill to a depth of 350' with no loss of circulation. Run 9 joints, 354' of 13 3/8", 48# H-40 ST&C Rg-3 casing. Texas pattern guide shoe @ 350', Insert float @ 310'. Cemented with 350 sx Class "C" + 2% CaCl2. Circulated 50 sx. to the pit. Witnessed by NMOCD Mike Stubblefield. WOC for 12 hours and test casing to 600# for 30 min. with no pressure drop. Ihreey cetify that the information above is type and complete to the best of my knowledge and belief. SKONATURE Image: Additional complete to the best of my knowledge and belief. SKONATURE Image: Additional complete to the best of my knowledge and belief. SKONATURE Image: Additional complete to the best of my knowledge and belief. SKONATURE Image: Additional complete to the best of my knowledge and belief. SKONATURE Image: Additional complete to the best of my knowledge and belief. SKONATURE Image: Additional complete to the best of my knowledge and belief. SKONATURE Image: Additional complete to the best of my knowledge and belief. SKONATURE Image: Additional complete to the best of my knowledge and belief. SKONATURE Image: Additional complete to the be	OTHER:			
17 1/2" hole at 12:45 PM MST, 1-5-89. Drill to a depth of 350' with no loss of circulation. Run 9 joints, 354' of 13 3/8", 48# H-40 ST&C Rg-3 casing. Texas pattern guide shoe @ 350', Insert float @ 310'. Cemented with 350 sx Class "C" + 2% CaCl2. Circulated 50 sx. to the pit. Witnessed by NMOCD Mike Stubblefield. WOC for 12 hours and test casing to 600# for 30 min. with no pressure drop. I hereby certify that the information above is type and complete to the best of my know kdge and helid. SIGNATURE III. Mike Weillierer THE Agent Date 1-7-89 Mike Weillierer THE FEB U 9 198		rations (Clearly state all pertinent details, an	d give pertinent dates, inclu	uding estimated date of starting any proposed
SX. to the pit. Witnessed by NMOCD Mike Stubblefield. WOC for 12 hours and test casing to 600# for 30 min. with no pressure drop. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE	17 1/2" hol of 350' wit of 13 3/8"	e at 12:45 PM MST, 1- th no loss of circul , 48# H-40 ST&C Rg	-5-89. Drill ation. Run -3 casing.	. to a depth 9 joints, 354'
SIGNATURE	sx. to the WOC for 12	pit. Witnessed by hours and test casin	7 NMOCD Mike	Stubblefield.
SIGNATURE		the and complete to the best of my know lefter and	belief	
TYPE OR PRINT NAME H. E. Gene Lee TELEPHONE NO. 622-73 (This space for State Use) Original Signed DY Mike Williemst THE	1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -			DATE
(This space for State Use) Original Signed by Mike Williams The Date	-			<u> 111394кме но. 622-735</u> 5
Original Signed by FEB 0 9 198				
ATTROVED BY DATE DATE	Origir			FEB 0 9 1989
	AITROVED BYMI	CO WHILE TT	NE	DATE