

11/15/84 8:40 AM 110 90 20.1

The summary on this page is for the condition of the well on above date.

Section	Top of Section	Bottom of Section	Thickness	Remarks
No. 1, from	100.0	90.0	10.0	
No. 2, from	90.0	80.0	10.0	
No. 3, from	80.0	70.0	10.0	
No. 4, from	70.0	60.0	10.0	
No. 5, from	60.0	50.0	10.0	
No. 6, from	50.0	40.0	10.0	
No. 7, from	40.0	30.0	10.0	
No. 8, from	30.0	20.0	10.0	
No. 9, from	20.0	10.0	10.0	
No. 10, from	10.0	0.0	10.0	

It is of the greatest importance to have a complete history of the well. Please state in detail the dates of redrilling, together with the reasons for the work and its results. If there were any changes made in the casing, state fully, and if any casing was "sidetracked" or left in the well, give its size and location. If the well has been dynamited, give date, size, position, and number of shots. If plugs or bridges were put in to test for water, state kind of material used, position, and results of pumping or bailing.

U. S. GOVERNMENT PRINTING OFFICE 16-50084-1

[illegible]