ENERGY AND MINERALS DEPARTMENT	IL CONSERVATION DIVISIO.	Form C-103
SANTA FE	SANTA FE, NEW MEXICO 87501	Revised 10-14-71
U.S.G.S.	JUL 2 2 1987	Sa. Indicate Type of Lease State X Fee
DPERATOR	O. C. D.	5. State Oil & Gas Lease No.
	ARTESIA, OFFICE	
SUNDRY NO SUNDRY NO PROPOSALS USE THIS FORM FOR PROPOSALS USE THIS PORT OF THE PROPERTY OF THE	TICES AND REPORTS ON WELLS TO DRILL ON TO DEEPEN ON PLUG BACK TO A DIFFERENT RESERVOIR. FERMIT (FORM C-10): FOR BUCK PROPOSALS:	
1.		7. Unit Agreement Name
OIL GAS WELL OTI	HER. Injection	RLPSU Flood 8. Farm or Lease Name
Kersey & Company		RLPSU-Tract 9
J. Address of Operator		9. Well No.
P.O. Box 316, Artesia, NM 88211-0316		Thompson 1
4. Location of Well		10. Field and Pool, or Wildcat Red Lake-Q-G-SA
UNIT LETTER _ A , 1650	FEET FROM THE SOUTH LINE AND 2310 FE	THE LOOM THE
THE West LINE, SECTION	20 TOWNSHIP 17S RANGE 28E	NMPM.
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County Eddy
Check Appro	priate Box To Indicate Nature of Notice, Report	or Other Date
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CABING	PLUG AND ABANDON X REMEDIAL WORK COMMENCE DRILLING OPNS. CHANGE PLANS CASING TEST AND CEMENT JQB OTHER	QUENT REPORT OF: ALTERING CASING PLUG AND ABANDONMENT
OTHER		
17. Describe Proposed or Completed Operation work; SEE RULE 1103.	s (Clearly state all pertinent details, and give pertinent dates, in	ncluding estimated date of starting any proposed
2. Perfomate 7" 3. Spot 7" plug 4. Perforate 600 5. Spot 100' plu 6. Surface plug	in and our of 7" casing O' ug in and out of 7" and marker sing cemented with 100 sacks Nowify NAM J.C.C. invalidations	
2. Perfomate 7" 3. Spot 7" plug 4. Perforate 600 5. Spot 100' plu 6. Surface plug	750 in and our of 7" casing 0' ug in and out of 7" and marker sing cemented with 100 sacks Nowify N.M. J.C.C. invalidations	
2. Perforate 7" 3. Spot 7" plug 4. Perforate 600 5. Spot 100' plu 6. Surface plug 7. NOTE: 7" cas	in and our of 7" casing O' ug in and out of 7" and marker sing cemented with 100 sacks	
2. Perforate 7" 3. Spot 7" plug 4. Perforate 600 5. Spot 100' plu 6. Surface plug 7. NOTE: 7" cas	in and our of 7" casing o' ug in and out of 7" and marker sing cemented with 100 sacks Notify N.M. J.C.C. into Fricant Plugging le true and complete to the best of my knowledge and belief.	