

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

JUL 22

O. C. D.

ARTESIA, OFFICE

Form C-103
Revised 10-78

5a. Indicate Type of Lease

State ☒

Fee ☐

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>Injection</u>	7. Unit Agreement Name <u>RLPSU Flood</u>
2. Name of Operator <u>Kersey & Company</u>	8. Farm or Lease Name <u>RLPSU-Tract 9</u>
3. Address of Operator <u>P.O. Box 316, Artesia, NM 88211-0316</u>	9. Well No. <u>Thompson 2</u>
4. Location of Well UNIT LETTER <u>L</u> <u>1650</u> FEET FROM THE <u>South</u> LINE AND <u>990</u> FEET FROM THE <u>West</u> LINE, SECTION <u>20</u> TOWNSHIP <u>17S</u> RANGE <u>28E</u> NMPM.	10. Field and Pool, or Wildcat <u>Red Lake-Q-G-SA</u>
15. Elevation (Show whether DF, RT, GR, etc.)	12. County <u>Eddy</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Spot 100' plug 1841-1941 - Load hole w/mud
2. Perforate 1250
3. Spot 100' plug in and out of casing
4. Perforate 600'
5. 100' plug in, and out of casing
6. Surface plug and marker
7. NOTE: 7" casing cemented with 100 sacks.

Notify N.M.C.C. in sufficient time to witness

Plugging

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Naved Kersey TITLE Co-Owner DATE 7-17-87

APPROVED BY Mike Williams TITLE OIL AND GAS INSPECTOR DATE JUL 23 1987

CONDITIONS OF APPROVAL, IF ANY: