

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

CLSF
CP

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

RECEIVED

MAR - 2 1995

WELL API NO.

Lease Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

B-1111

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT
(FORM C-101) FOR SUCH PROPOSALS.)

Lease Name or Unit Agreement Name

Collier State

1. Type of Well:

OIL
WELL ☐

GAS
WELL ☐

OTHER SWD

2. Name of Operator

Marbob Energy Corporation

8. Well No.

3 SWD

3. Address of Operator

P. O. Box 227, Artesia, NM 88210

9. Pool name or Wildcat

4. Well Location

Unit Letter G : 2310 Feet From The North Line and 2310 Feet From The East Line

Section 22 Township 17S Range 28E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

REMEDIAL WORK ☐

ALTERING CASING ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

PULL OR ALTER CASING ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

(1) Set 35 sxs cement plug from 1975' to 50' inside 7" casing shoe at 1717'. This plug will also cover the 4 1/2" casing shoe at ~~1853~~ ¹⁹¹⁵'. This plug will be tagged.

(2) Load hole w/ mud.

(3) Set 25 sxs cement plug accross old perforations at 1450'.

(4) Perforate 4 1/2" and 7" casing at 8 5/8 shoe at ~~550~~ ⁶⁰⁰ attempt to sqz 100' cmt plug between 4 1/2" & 7" csg leaving 100' cmt plug inside 4 1/2" csg

(5) Perforate 4 1/2" & 7" & 8 5/8" csg @ 60', circ cmt to surface between 4 1/2" & 7" csg and 7" and 8 5/8" csg and 8 5/8" open hole leaving 4 1/2" csg full.
Set P&A marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Robin Smith

Production Clerk

DATE 3/2/95

TYPE OR PRINT NAME

TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY TIM W. GUM
DISTRICT II SUPERVISOR

MAR 03 1995

APPROVED BY _____ TITLE _____

DATE _____

CONDITIONS OF APPROVAL, IF ANY: