

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

OIL CONSERVATION DIVISION
RECEIVED BY P. O. BOX 2088
SANTA FE, NEW MEXICO 87501
APR -4 1985
O. C. D.
ARTESIA, OFFICE

WIW

Form C-103
Revised 10-1-7

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
2. Name of Operator Marbob Energy Corporation ✓	5. State Oil & Gas Lease No. B-1111
3. Address of Operator P.O. Drawer 217, Artesia, N.M. 88210	7. Unit Agreement Name
4. Location of Well UNIT LETTER L 2310 FEET FROM THE South LINE AND 330 FEET FROM THE West LINE, SECTION 22 TOWNSHIP 17S RANGE 28E NMPM.	8. Farm or Lease Name Collier St.
	9. Well No. 4
	10. Field and Pool, or Wildcat Red Lake On Grbg SA
15. Elevation (Show whether DF, RT, GR, etc.)	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to plug and abandon as follows: Set plug from TD to 1500' (50 sax), tag plug @ 1560'; set plug @ 1500-1100' (30 sax); set plug from 1100-700' (30 sax); perforate at 550', circulate cement to surface, set dry hole marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Charles J. Lucella TITLE Production Clerk

DATE 3/25/85

APPROVED BY Mike Williams TITLE OIL AND GAS INSPECTOR

DATE APR 9 1985

CONDITIONS OF APPROVAL, IF ANY: