| NO. OF COPIES RECEIVED  | Form C-103   |
|---|--|
| DISTRIBUTION  | Supersedes Old   |
| RE REWINEX ODELL CONSERVATION COMMISSION  | C-102 and C-103  |
| FILE IV.  | Effective 1-1-65   |
| U.S.G.S.  | 5a. Indicate Type of Lease   |
| JUL 9 1971  | State X Fee  |
| OPERATOR  | 5. State Oil & Gas Lease No.   |
|   | 5. State Off & Gds Ledse No.   |
| SUNDRY NOTICES'AND TERORTS ON WELLS   |  |
| USE "APPLICATION FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.<br>USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.) | ΔΗΗΗΗΗΗΗΗΗΗΗΗΗ   |
| 1.<br>OIL X GAS WELL OTHER-   | 7. Unit Agreement Name   |
| 2. Name of Operator   | 8. Farm or Lease Name  |
| Atlantic Richfield Company  | M. Yates   |
| P. O. Box 1978, Roswell, New Mexico 88201   | 9. Well No.  |
| 4. Location of Well   | 4  |
|   | 10. Field and Pool, or Wildcat   |
| UNIT LETTER J 1650 FEET FROM THE South 1650   | Artesia-Grayburg   |
| THE East LINE, SECTION 33 TOWNSHIP 17-S RANGE 28-E  | $\boldsymbol{\chi} = \boldsymbol{\chi} = $ |
|   |  |
| 15. Elevation (Show whether DF, RT, GR, etc.)   | 12. County   |
| AIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII  | Eddy   |
| Check Appropriate Box To Indicate Nature of Notice, Report or Oth   | er Data  |
|   | REPORT OF:   |
| PERFORM REMEDIAL WORK   |  |
|   | ALTERING CASING  |
| COMMENCE DRILLING OPNS.   | PLUG AND ABANDONMENT   |
|   |  |
| OTHER   |  |
|   |  |
| 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1103.                    | estimated date of starting any proposed  |
| This well was last produced on 10/31/70 when pumping w  | unit foiled  |
|   |  |
| It was averaging 1 BOPD, no water. It is no longer ed   |  |
| to produce and no remedial possibilities exist. We pr   | ropose to P & A  |
| as follows:   |  |
|   |  |
| 1. Set 30 sx cement from 1842' to 1942' (7" shoe @ 18   | 39 <b>2').</b>   |
| <ol><li>Shoot off &amp; pull 7" casing from free point.</li></ol>   |  |
| 3. Set 30 sx cement in & out of 7" stub.  |  |
| 4. Set 30 sx cement across 8¼" shoe @ 509'.   |  |
| 5. Place IO sx cement in top of well.   |  |
|   |  |
| 9#/gal gel mud will be left between all cement plugs.   | at arging  |
| will remain intact. Dry hole marker will be installed   |  |
|   | Location   |
| will be cleared & levelled.   |  |
|   |  |
|   |  |
| 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.  |  |
|   |  |
| SIGNED O.D. Metches Dist. Drlg. Supervisor  | 7/7/71   |
|   |  |
| 11 P GARDENT OIL AND GAS INSPECTOR  | Hell and Arrive  |
| APPROVED BY U. U. Aressett TITLE  | DATE JUL 8 1 19/1  |
| CONDITIONS OF APPROVAL, IF ANY:   |  |

•