NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON
Governor

Joanna Prukop Cabinet Secretary Lori Wrotenbery
Director
Oil Conservation Division

and the place of the expression of the Philips of The process that there is no to be the same than the same

31-Jan-03

BP AMERICA PRODUCTION COMPANY

PO BOX 22048 TULSA OK 74121-

Dear Operator:

The following test(s) were performed on the listed dates on the following well(s) shown below in the test detail section.

The test(s) indicates that the well or wells failed to meet mechanical integrity standards of the New Mexico Oil Conservation Division. To comply with guidelines established by the U.S. Environmental Protection Agency, the well must be shut-in immediately until it is successfully repaired. The test detail section which follows indicates preliminary findings and/or probable causes of the failure. This determination is based on a test of your well or facility by an inspector employed by the Oil Conservation Division. Additional testing during the repair operation may be necessary to properly identify the nature of the well failure.

Please notify the proper district office of the Division in writing, at least 48 hours prior to the date and time that repairs will be attempted so that such operations may be witnessed by a field representative.

MECHANICAL INTEGRITY TEST DETAIL SECTION

EMPIRE ABO UNIT 032A

30-015-01694-00-00

Temporarily Abandoned Oil (Producing) H-33-17S-28E

Actual PSI:

Test Date: 1/29/2003 1:29:17 PM Permitted Injection PSI:

Test Reason: TA Status Test Test Result: F Repair Due: 5/4/2003

Test Type: Std. Annulus Pres. Test FAIL TYPE: Casing FAIL CAUSE:

Comments on MIT: Well would not pressure-up.

Thank you for your prompt attention to this matter and your efforts in helping to protect our ground water Sincerely.

Artesia OCD District Office

Note: Pressure Tests are performed prior to initial injection, after repairs and otherwise, every 5 years; Bradenhead Tests are performed annually. Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data. "Failure Type" and "Failure Cause" and any Comments are not to be interpreted as a diagnosis of the condition of the wellbore. Additional testing should be conducted by the operator to accurately determine the nature of the actual failure. * Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas,

Oil Conservation Division * 1301 W. Grand * Artesia, New Mexico 88210 Phone: 505-748-1283 * Fax: 505-748-9720 * http://www.emnrd.state.nm.us