

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	/
FILE	/
U.S.G.S.	
LAND OFFICE	
OPERATOR	/

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

JAN 29 1979

O. C. C.

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
B-2071

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name Empire Abo Pressure Maintenance Project
2. Name of Operator Atlantic Richfield Company	8. Farm or Lease Name Empire Abo Unit "H"
3. Address of Operator Box 1710, Hobbs, New Mexico 88240	9. Well No. 34
4. Location of Well UNIT LETTER <u>N</u> <u>1650</u> FEET FROM THE <u>West</u> LINE AND <u>973</u> FEET FROM THE <u>South</u> LINE, SECTION <u>34</u> TOWNSHIP <u>17S</u> RANGE <u>28E</u> NMPM.	10. Field and Pool, or Wildcat Empire Abo
15. Elevation (Show whether DF, RT, GR, etc.) 3659' GR	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Squeeze, Recomplete Lower in Abo	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rig up, kill well, install BOP & POH w/compl assy.
2. RIH w/retr, set retr @ 6100'. Squeeze perfs 6136-49' w/LWL cmt. WOC.
3. DO to 6300', circ hole & run CBL 6300-4300'.
4. Perforate Abo 6280-6290' w/2 JSPF.
5. Treat perfs 6280-90' w/150 gals 15% HCL-LSTNE-FE acid, 2000 gals gelled CaCl wtr, 1000 gals gelled LC, 1500 gals HCL-LSTNE-FE acid.
6. Swab test, run compl assy & return to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Adon Lane TITLE Dist. Drlg. Supt. DATE 1/26/79

APPROVED BY W. A. Gussitt TITLE SUPERVISOR, DISTRICT II DATE JAN 30 1979

CONDITIONS OF APPROVAL, IF ANY: