

| | |
|------------------------|---|
| NO. OF COPIES RECEIVED | 3 |
| DISTRIBUTION | |
| SANTA FE | 1 |
| FILE | 1 |
| U.S.G.S. | |
| LAND OFFICE | |
| OPERATOR | 1 |

RECEIVED
MAY 12 1972
 NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
 Supersedes Old
 C-102 and C-103
 Effective 1-1-65

O. C. C.
ARTESIA, OFFICE

| |
|--|
| 5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/> |
| 5. State Oil & Gas Lease No. E 8889 |

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
 USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

| | |
|---|--|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/> | 7. Unit Agreement Name |
| 2. Name of Operator Sun Oil Company | 8. Farm or Lease Name Moab State |
| 3. Address of Operator P O Box 2880 Dallas, Texas 75201 | 9. Well No. 1 |
| 4. Location of Well UNIT LETTER J , 1980 FEET FROM THE South LINE AND 1980 FEET FROM THE East LINE, SECTION 16 TOWNSHIP 16S RANGE 29E NMPM. | 10. Field and Pool, or Wildcat High Lonesome Q |
| 15. Elevation (Show whether DF, RT, GR, etc.) | 12. County Eddy |

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
 NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

| | | | |
|--|---|--|--|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> | PLUG AND ABANDONMENT <input checked="" type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | OTHER <input type="checkbox"/> | CASING TEST AND CEMENT JOBS <input type="checkbox"/> | |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set 30 Sock cement plug over perforations, cut off 5 1/4" casing at 1360' and set 25 sock cement plug at cut off point, set 25 sock cement plug at base of surface casing and 10 sock cement plug at surface with mud between all plugs. Set dry hole worker and cleaned up surface filling oil pits.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED B. N. Muncy, Jr. TITLE Bookkeeper DATE 5/11/82

APPROVED BY Debra Mermis TITLE LAND GAS INSPECTOR DATE 5-14-72

CONDITIONS OF APPROVAL, IF ANY: