

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TR
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

LC-037777(B)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

RECEIVED

2. NAME OF OPERATOR

Marbob Energy Corporation

3. ADDRESS OF OPERATOR

P.O. Drawer 217, Artesia, N.M. 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

MAY 22 '89
O.C.D.
ARTESIA, OFFICE

1650 FSL 2310 FWL

7. UNIT AGREEMENT NAME

Forest Pool Unit

8. FARM OR LEASE NAME

Forest Pool Unit

9. WELL NO.

15

10. FIELD AND POOL, OR WILDCAT

Square Lake Grbg SA

11. SEC., T., R., M., OR BLE. AND
SURVEY OR AREA

Sec. 34-T16S-R29E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3628' DF

12. COUNTY OR PARISH

Eddy

13. STATE

N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

We propose to plug & abandon as follows:

2000' in open hole 535
Set SV rtmr @ ~~top~~ 7" csg and sqz w/100 sx cmt. Leave
50' cmt on top SV rtmr. Set 100' plug @ 1300-1200',
perf csg @ 830' and try to break circulation, circ
cmt to surface. If cannot circ cmt, will perf csg @
335' and try again. Install dry hole marker and clean
location.

RECEIVED
MAY 4 10 30 AM '89

18. I hereby certify that the foregoing is true and correct

SIGNED

Rhonda Nelson

TITLE Production Clerk

DATE 5/2/89

(This space for Federal or State office use)

APPROVED BY

Shirley J. Smith

FOR: CHIEF, ARTESIA OFFICE
TITLE

DATE 5-19-89

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side