

N. M. O. C. C. COPY
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIP
(Other instruction
verse side)E
reForm approved.
Budget Bureau No. 42-R1434.
Copy to S. F.

5. LEASE DESIGNATION AND SERIAL NO.

LC-068888

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)1. WELL ☒ GAS ☐
WELL ☒ WELL ☐ OTHER

2. NAME OF OPERATOR

FEATHERSTONE FARMS, LTD. *The E. Featherstone*

3. ADDRESS OF OPERATOR

239 Petroleum Building, Roswell, New Mexico 88201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

660' FNL and 1980' FEL Sec. 31, T 16S, R 30E, NMPM

14. PERMIT NO.

15. ELEVATIONS (Show whether DT, RT, GR, etc.)

3717' GR.

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal "A"

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

SQUARE LAKE

11. SEC., T., R., M., OR BLK. AND
SUEVEY OR AR.

Section 31,

T 16S, R 30E, N.M.P.M.

12. COUNTY OR PARISH

13. STATE

Eddy

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☒CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)

Spudded: 4-27-59

Completed: 5-5-59

Casing: 8-5/8" set 492' and cemented with 75 sacks. Calculated top cement
178'.
5-1/2" set 2903' and cemented with 60 sacks. Calculated top cement
2100'.

Producing zone: Premier section 2770' to 2806' - perforated 4 shots per foot.

Intend to Plug and Abandon as follows:

Cut and pull 5-1/2" casing and spot -

120' cement plug (15 sacks) over perfs 2850' to 2730'.

100' cement plug (18 sacks) 5-1/2" stub estimated 2000', 50' in
5-1/2" and 50' out 5-1/2". If below red sand base at 2075' will
cover red sand with 100' cement plug.

100' cement plug (23 sacks) base salt 1750' to 1650'.

100' cement plug (27 sacks) base 8-5/8" 542' to 442'.

Will pull 8-5/8" and spot cement plug in 8-5/8" stub.

20' cement plug (10 sacks) at surface and set 4-1/2" marker pipe
4' above surface.

(Cement to be furnished and pumped by Dowell.)

RECEIVED

MAR 13 1969

18. I hereby certify that the foregoing is true and correct

SIGNED

Charles W. Hicks
(Charles W. Hicks)

TITLE

General Manager

DATE

O. C. C.

ARTESIA OFFICE

5-10-69

(This space for Federal or State office use)

APPROVED BY

COMMITTEE OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side