

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Injection Well		RECEIVED BY MAR 10 1986 O. C. D. ARTESIA, OFFICE	7. Unit Agreement Name
2. Name of Operator Walsh and Watts, Inc. ✓			8. Farm or Lease Name N. Square Lake Prem. Unit
3. Address of Operator 1111 Seventh Street, Wichita Falls, Texas 76301			9. Well No. 20
4. Location of Well UNIT LETTER B, 660 FEET FROM THE North LINE AND 1980 FEET FROM THE East LINE, SECTION 8 TOWNSHIP 16-S RANGE 31-E NMPM.			10. Field and Pool, or Wildcat N. Square Lake G-SA
15. Elevation (Show whether DF, RT, GR, etc.) 4052' GL 4063' KB		12. County Eddy	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
FULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Preparing to plug and abandon former injection well. Plan to start procedures 3-17-86.

- Set CIBP at 3300'. Cap with 50' cement.
- Load hole with mud. Cut off casing at 2000'+. Spot 100' cement; plug 50' in and out of 4 1/2" casing. WOC and tag plug.
- Spot 40 Sx. cement from 1800-1900'.
- Spot 40 Sx. cement from 1200-1300'.
- Spot 50 Sx. cement from 265' to 165'. WOC and tag.
- Circulate cement from 50' to surface and cap with marker.

Note: This well drilled and completed by Leonard Oil Co. as the Midwest #1 on June 1, 1961. Converted to water injection by Shell Oil as North Square Lake Premier Unit #20 on 8-13-66.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Alfred B. Guinn TITLE Vice-President DATE March 7, 1986

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

3a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐ GAS WELL ☐ OTHER- ☒ Injection Well
Name of Operator
Walsh and Watts, Inc. ✓
Address of Operator
1111 Seventh Street, Wichita Falls, Texas 76301
Location of Well
UNIT LETTER B 660 FEET FROM THE North LINE AND 1980 FEET FROM
THE East LINE, SECTION 8 TOWNSHIP 16-S RANGE 31-E NMPM.

RECEIVED BY

MAR 10 1986

O. C. D.

ARTESIA, OFFICE

7. Unit Agreement Name
8. Farm or Lease Name
N. Square Lake Prem. Unit
9. Well No.
20
10. Field and Pool, or Wildcat
N. Square Lake G-SA
12. County
Eddy

15. Elevation (Show whether DF, RT, GR, etc.)

4052' GL 4063' KB

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐
OTHER ☐

REMEDIATION WORK ☐
COMMENCE DRILLING OPERATIONS ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐
OTHER ☐

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Preparing to plug and abandon former injection well. Plan to start procedures 3-17-86.

1. Set CIBP at 3300'. Cap with 50' cement.
2. Load hole with mud. Cut off casing at 2000'+. Spot 100' cement plug 50' in and out of 4 1/2" casing. WOC and tag plug.
3. Spot 40 Sx. cement from 1800-1900'.
4. Spot 40 Sx. cement from 1200-1300'.
5. Spot 50 Sx. cement from 265' to 165'. WOC and tag.
6. Circulate cement from 50' to surface and cap with marker.

Note: This well drilled and completed by Leonard Oil Co. as the Midwest #1 on June 1, 1961. Converted to water injection by Shell Oil as North Square Lake Premier Unit #20 on 8-13-66.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Alfred B. Guinn TITLE Vice-President DATE March 7, 1986

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: