

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-015-04834
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Aghorn Operating Inc.		6. State Oil & Gas Lease No. NM 026418
3. Address of Operator P O Box 12663		7. Lease Name or Unit Agreement Name: North East Square Lake
4. Well Location Unit Letter C : 660 feet from the North line and 1980 feet from the West line Section 10 Township 16S Range 31E NMPM County Eddy		8. Well No. 10
10. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. Pool name or Wildcat NE Square Lake

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Well is presently T&A'd.  
RIH and tag CIBP @ 3600'. Dump 3 sz. class "C" cmt. on top. ← 25 sz plug @ 2100' - T<sub>25</sub>  
RIH & spot 50 sz. class "C" cmt. @ 1600 to 1400. - T<sub>29</sub>  
RIH w/ 4 1/2 packer, sqz. 50 sz. class "C" cmt. in hole in casing @ 881'. - leave 100' of cmt. in csq.  
Perf. 4 1/2 csq. @ 300 and sqz. 60 sz class "C" cmt. between 4 1/2 & 8 5/8 csq.  
Spot 10 sz. surface plug. 250' - leave 100' of cmt. in csq. T<sub>29</sub>  
Cut off well head and install dry hole marker.

Notify OCD 24 hrs. prior to any work done

Salt gel mud consisting of 10#  
Brine W/25# of gel per bbl  
must be placed between each plug

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Fredy Gilman TITLE President DATE 6/6/02

Type or print name Fredy Gilman  
(This space for State use)

Telephone No. 915-350-0804

APPROVED BY [Signature] TITLE Wild Sep ID DATE JUN 7 2002  
Conditions of approval, if any: