

Anadarko Petroleum Corporation  
Sundry Notice  
Baxter A #2  
Page 2

8. Perforated 4 squeeze holes at 50' and circulated cement down 5½" csg and up 8 5/8" casing. This is surface plug.
9. Cut off casing and anchors. Set P&A marker. Cleaned location. Will do surface restoration after receiving orders from BLM.