

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OFFICE FOR NUMBER
OF COPIES REQUIRED
(Other Instructions
verse side)

Modified Form No.
NMOG-3160-4

5. LEASE DESIGNATION AND SERIAL NO.

LC-060476

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Valentine

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Square Lake

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 27-T16S-R31E

12. COUNTY OR PARISH

Eddy

13. STATE

N.M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR
Marbob Energy Corporation

3a. Area Code & Phone No.
(505) 748-3303

3. ADDRESS OF OPERATOR
P. O. Drawer 217, Artesia, NM 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

660 FSL 660 FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, CR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETION

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANE

(Other)

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

SUBSEQUENT REPORT OF:

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

2-5-90 We propose to plug and abandon as follows:

1. Set cmt plug at 3635-3320 (Tag)
2. Set cmt plug at 2950-2800
3. Perf csg at 1850 and squeeze perf w/75sx cmt. (Tag)
4. Perf csg at 800' and squeeze perf w/75 sx Cmt. (Tag)
5. Set 15sx plug at surface
6. Install dry hole marker
7. Clean location
8. NOTIFY BLM PRIOR TO COMMENCING P&A
9. PLACE DRILLING MUD OF A MINIMUM 9 PPG Wt. BETWEEN PLUGS.
10. CEMENT A MINIMUM OF TOP 50' OF ALL ANNULUS.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Production Clerk

DATE 2-5-90

(This space for Federal or State office use)

APPROVED BY Signed by Adam G. Smith

TITLE

DATE 2-14-90

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

COMPANY Marbob
LEASE & WELL NO. Valentine Fed #1
FORMATION _____
COUNTY & STATE Eddy



Robert C. Chase
Completion Supervisor

(505) 748-3303

P.O. Drawer 217
Artesia, N.M.
88211-0217

8 5/8" @ 249' c/w 50sx

T. salt 849'
B. salt 1805'

Set cmt Plug @ 3635-3320 (Tag)
Set cmt Plug @ 2950-2800'
Perf csq @ 1850 squeeze perf w/75sx (Tag)
Perf csq @ 800' squeeze perf w/75sx (Tag)
Set 15sx Plug @ surface. Install
key hole marker above location

7" @ 3370' c/w 100sx

shot open Hole @ 3490-3590
w/255 Qts

TD 3635'

MARBOB ENERGY CORPORATION
VALENTINE 1
SEC 27 T16S R31E 660FSL 660FUL

=====

WELL HISTORY

=====

PBTD: 3635'

TD: 3635'

SP Csg: 8 5/8" @ 349' C/w 50sx

LS Csg: 7" @ 3370' C/w 100sx

T SALT: 347' S/O 2494-3514
S/O 3548-62

B SALT: 1205' S/O 3583-90

PERFS: OPEN HOLE 3370-3635

=====

COMPLETION REPORT

=====

7-25-45 Shot open hole w/255 Qts Nitro from 3490-3570

=====

WELL REPORT

=====

11-21-58 Proposed to deepen well 120-130 to Iovington sand and frac
w/40000 gals oil and 40000# sand. Whether it was done is
a good question.

2-5-90 Propose to plug and abandon as follows:

1. Set cmt plug at 3635-3320 (Tag)
2. Set cmt plug at 2950-2800
3. Perf csg at 1850 and squeeze perf w/75sx cmt. (tag)
4. Perf csg at 800' and squeeze perf w/75sx Cmt (tag)
5. Set 15sx plug at surface
6. Install dry hole marker
7. Clean location