

UNITED STATES DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.
LC-060548

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☐ SI - WIW JUN 7 9 1982
2. NAME OF OPERATOR O. C. D.
NEWMONT OIL COMPANY
3. ADDRESS OF OPERATOR ARTESIA OFFICE
P. O. BOX 1305, ARTESIA, NEW MEXICO 88210

7. UNIT AGREEMENT NAME
Square Lake Flood (East)

8. FARM OR LEASE NAME

Johnson A

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Square Lake (G. SA)

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

33-16S-31E

LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660' FNL & 1980 FWL of Sec. 33.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3974' GLM

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☒
☐
☐

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐
☐
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

☐
☐
☐
☐
☐


(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

We propose to plug and abandon the above well as follows:

1. Pull tubing and packer
2. Set bridge plug near casing seat and cap with 25 sack cement plug.
3. Perforate at base of salt and squeeze with 50 sacks cement leaving 100' plug in casing.
4. Perforate at top of salt and squeeze with 50 sacks cement leaving 100' plug in casing.
5. Set 15 sack cement plug at surface down surface and production casing.
6. Erect permanent well marker.

Note: (a). Your office will be notified 24 hrs. prior to operations.
(b). All plugs will be tagged
(c). Hole will be loaded between all plugs with 100' mud
(d). We do not plan to pull any casing.



18. I hereby certify that the foregoing is true and correct

SIGNED

Robert J. McLaughlin

TITLE

Area Manager

DATE

6/10/82

(This space for Federal or State Approval)

APPROVED

APPROVED BY (Sig.) PETER W. CHESTER
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

JUN 17 1982

FOR

JAMES A. GILLHAM
DISTRICT SUPERVISOR

*See Instructions on Reverse Side