SUNDRY	NOTICES AND REPORTS or proposals to drill or to deepen or plu APPLICATION FOR PERMIT—" for such	ON WELLS	LC-029438A 6. IF INDIAN, ALLOTTEE N/A	OR TRIBE NAME		
		KELLIVEU	7. UNIT AGREEMENT NAM	£		
			N/A			
2. NAME OF OPERATOR			8. FARM OR LEASE NAME			
SDX RESOURCES, INC.			Carper Johnson A			
ADDRESS OF OPERATOR			9. WBLL NO.			
P. O. Box 5061	2					
P. O. Box 5061 Midland, TX 79704-5061 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)			10. FIELD AND POOL, OR WILDCAT			
At surface	Grayburg Jackson					
Unit H Sec. 35	11. SEC., T., B., M., OR BLK. AND SURVEY OR AREA					
$R^{31E} 1980 FNL E 1000 FFL.$			Sec. 35 T16S R31E			
4. PERMIT NO. 15. ELEVATIONS (Show		DF, RT, GR, etc.)	12. COUNTY OR PARISH	13. STATE		
			Eddy	NM		
Ch	eck Appropriate Box To Indicate	Nature of Notice, Report, or	Other Data			
NOTICE	OF INTENTION TO :	SUBSEC	UBNT REPORT OF :			
TEST WATER SHOT-OFF	PELL OR ALTER CASING	WATER SHOT-OFF	REPAIRING WE			
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CAS	ING		
SHOOT OB ACIDIZE	ABANDON* X	SHOOTING OR ACIDIZING	ABANDONMENT	•		
REPAIR WELL	CHANGE PLANS	(Other)				
(Other)			(Nots: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)			
. DESCRIBE PROPOSED OR COMPL	ETED OPERATIONS (Clearly state all pertin	nent details, and give pertinent dates cations and measured and true vertions	s, including estimated date	of starting any		

See Attached Sheets.

		object 1993 object 1993 objec	Mexico	
18. I hereby certify that the foregoing is true and correct SIGNED	TITLE _	Vice-President	DATE _	1/13/93
(This space for Federa or State office) APPROVED BY (CONDITIONS OF APPROVAL, IF ANY:	TITLE -		DATE _	1:21 93

*See Instructions on Reverse Side

SUNDRY NOTICE

Carper Johnson A-2

Casing Record: (See attached well data sheet) Well History: Fish in hole. (See data sheet) Proposal:

- Circulate hole with salt gel from 2937'. (9# per gal)
- 2. Spot 50 sx plug 2937'-2637'. (Tag)
- 3. Perforate casing at 2000', pump 50 sx plug and leave top of plug at 1900'. (Tag)
- Perforate casing at 1035', pump 50 sx plug and leave top of plug at 935'. (Tag)
- 5. Spot 15 sx surface plug in 7" and 7"x8 1/2" annulus.
- 6. Install dry hole marker, clean location and close road.

Note: Alternative Plan: Pull 7" from 2000' and spot plug in open hole.

Discussed with Shannon Shaw, BLM, 1-8-93.

-+	 + +		LSF LOC API FII	S NAME <u>Car</u> . H 35-	oer John 16s-31e Kson-0-G	<u>"A" #2</u> FILE # <u>000900-02</u> <u>son A</u> Fed. LC <u>029438A</u> <u>1980 fnl 660 fel</u> <u>STATUS S</u> <u>R-SA</u> <u>GAS</u>
-+ +-	_		DRI	ILL AND CO	APLETE	
::			Ele SPU	ev. 4090	DF	<u>il & Gas</u> KB COMP. DATE <u>11-26-38</u> BBTD
			TO	?s:		
CASING	HOLE		WT. GRADE	DEPTH SET	sks	TOC
	+	10"	+== 	425	+ - 	++
		8 1/2		985	50	
	∔	7	2.0	3463	100	
Vell W <u>or</u>	<u>k 12-5</u>	BWPD 7 Cleaned c d out open	out from	3775-4012	12-27	-57 Sot pupp is sh
Eand.600	WORK A	<u>ell_w/15000</u> balls <u>.5-</u> ND_WORKOVES	<u>)gals</u> <u>1 to</u> 12-5 R	<u>.1# Adomi</u> 58 <u>cleaned</u>	<u>out</u> fra	<u>& 1.5#/gal 20-40</u> c <u>sand from 3930-4023.</u>
would no 3057. I fish @ 2 hours co WELL INV	f not s 937 G.L	Tbg. tight hoot off. . Ran 1000 We were mi 8-8-85 We	@ 3035. Pulled 1 0' 4 1/4	Collar @ Cods tag f. wash pipe	<u>qo to 3</u> 3029' - ish tall waw too	in two. Overshot (4' 057'. 1 3/8 + 1 5/8" try rod to go below ey out of hole, top of th mill, milled for two (fell over top of fish
ROD	s <u>8-8</u>	-85 1-5/83	(4' sub,	64 5/8 roo	ls, 53_3	/4 rods - 2-3/4x8' subs
PUM						
ANC	HOR			SI	N	
PAC	KER					
						ID#
MOT	'OR			II	D#	
WEL	LHEAD _			ME:	CER #	
REMARKS: drill co	<u>to 294</u> llars o	<u>9). Ran st</u> vershot lat	tring of	2 7/8 EUE	<u>N.80 re</u>	nted tbgJohnson jars- 1/2 hrs. pulling 125000

jars. Ran tbg rods hung well back on production 30 foot off fish