UNIT DISTATES November 1983) Elimetry 9 331 DEPARTMENT OF THE INTER		English Bureau No. 1994 of Expires August 31, 1985 5. LEASE DESIGNATION AND SERIAL NO.
SUNDRY NOTICES AND REPORTS (LC-056302A
(Do not use this form for proposals to drill or to deepen or plug l Use "APPLICATION FOR PERMIT" for such p	back to a different reservoir. roposals.)	N/A
OIL	MELLINEU	7. UNIT AGREEMENT NAME N/A
WELL X WELL OTHER 2. NAME OF OPERATOR	JAN 2 5 1993	8. FARM OR LEASE NAME
SDX RESOURCES, INC.	JAN D O 100	Kennedy Johnson
3. ADDRESS OF OPERATOR	0. C. 0.	9. WBLL NO.
P. O. Box 5061 Midland, TX 79704- 4. LOCATION OF WELL (Report location clearly and in accordance with any	State requirements	10. FIELD AND POOL, OR WILDCAT
See also space 17 below.) At surface	oute requirements.	Grayburg Jackson
Unit L Sec. 35 T16S R31E / CG / FG /	A . T	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
1980 FSL & CO	altal	Sec. 35 T16S R31E
14. PERMIT NO. 15. BLEVATIONS (Show whether DF	, KT, GR, etc.)	Eddy NM
16. Check Appropriate Box To Indicate N		
NOTICE OF INTENTION TO:	SUBBEQU	ENT REPORT OF:
TEST WATER SHUT-OFF PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT SHOOT OR ACIDIZE ABANDON® X	FRACTURE TREATMENT SHOOTING OR ACIDIZING	ALTERING CASING ABANDONMENT®
REPAIR WELL X CHANGE PLANS	(Other)	
(Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinen	Completion or Recomple	of multiple completion on Well etion Report and Log form.)
Plan to re-activate well, test casing for state/federal requirements on or before M		
8. I hereby certify that the coregoins is true and correct SIGNED 11TLE Vi		

*See Instructions on Reverse Side

KENNEDY JOHNSON A-#3 L, Sec. 35, T16S, R31E Eddy County, New Mexico LC 056302A

Casing: 12 1/2" set at 56'.

7", 20# & 17#, set at 3453'.

Cemented in 2 stages with 528 sx with 2 stage tool

at 911'.

O.H. - 3453'-4259'.

Plugging Procedure

- 1. Move in, rig up, nipple up BOP and dig workover pit.
- 2. Pull rods and pump. (Calculate depth by rod count.)
- 3. Circulate hole with salt gel.
- 4. Spot 35 sx plug 3553'-3353'.
- 5. Spot 25 sx plug 3000'-2850'.
- 6. Spot 25 sx plug 2000'-1850'.
- 7. Spot 25 sx plug 961'-811'.
- 8. Spot 10 sx surface plug and install dry hole marker.
- 9. Salvage out battery, clean location and move salvage to yard. Abandon road.

WELL DATA SHEET

-+	+ +-			LSI LOO AP: FII OI:	E NAME Ken C. L 35- I# ELD GR-Jac L PUR	nedy Joh 16s-31e kson-Q-G	nson A Fed. 1980 fsl STAT GR-SA GAS	
	: :	•		GL SPI	<u>4034</u> JD DATE 1	DF 0-28-38	Oil Company KB Pipe Set PBTD	11-10-38
				TO	PS: Metex3	598,Pre.	3640,SA3680	,Lov.3791
CASI	NG	HOLE SIZE	CASING	WT. GRADE		SKS	TOC	+
	4		12 1/2	20 & 17	56 3453	E20 to	-6- 7	
	_		btm. 2 sta	age tool	@ 911'.	328 6	sis. Baker	Float Shoe on
	LETION 5 <u>12-1</u>	•	ОН 3630-38	326 170	Ots.			
132 I	obls.	in 17	1/2 hrs.					
			BWPD					
<u>, , , , , , , , , , , , , , , , , , , </u>	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		~~;	/ 1074-6/	1 (2) (1 - 2)	Mark Indiana	ry Card sho	ws: SO 3567- Fl. 157 BOP 24
	<u> </u>	J/ 10 C	hs choke or BWPD	1 / " חרו מ	ost on as	•		
			ND WORKOVE					
DATE	11-22	2-76		3593/ /	nf 2 3/8" -	tha Un		ill in open
DATE			WORK					
WELL	INVEN	TORY:						
	RODS							
	PUMP						·· · · · · · · · · · · · · · · · · · ·	
	ANCHO	OR						
	PACKE							
	PUMPI							
	PUMPING UNITID#ID#							
REMAI								·
								