

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

OCT 15 1974

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

O. C. C.

SUNDRY NOTICES AND REPORTS ON WELLS ARTESIA, OFFICE
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
2. Name of Operator Aztec Oil & Gas Company	5. State Oil & Gas Lease No.
3. Address of Operator P.O. Box 837, Hobbs, New Mexico 88240	7. Unit Agreement Name Robinson Unit
4. Location of Well UNIT LETTER 0, 660 FEET FROM THE South LINE AND 1980 FEET FROM THE West LINE, SECTION 36 TOWNSHIP 16 RANGE 31 NMPM.	8. Farm or Lease Name Robinson Unit Tr. 4-36
	9. Well No. 15
	10. Field and Pool, or Wildcat Malj. Grayb. S.A.
15. Elevation (Show whether DF, RT, GR, etc.) 4065' GR	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is proposed to plug and abandon in the following manner: No casing will be pulled.

1. Set 100' cement plug above perforations 3753-3840' (Overall)
2. Fill casing with mud.
3. Set 100' cement plug at 991' (Top Salt)
4. Set 10' plug at surface with marker
5. Clear, level and clean location.

Expires 10/1/75

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Arthur L. Dyer TITLE District Superintendant DATE 10/7/74

APPROVED BY Joe D. Ramey TITLE Dist. I, Supv. DATE OCT 22 1974
CONDITIONS OF APPROVAL, IF ANY: