P.O. Box 1980, Hebb, NM 8520       P.O. Box 2088         DISTRICT II       Santa Fe, New Mexico 87504-2088         SITE CT III       Santa Fe, New Mexico 87504-2088         DISTRICT III       Santa Fe, New Mexico 87504-2088         SUNDERY NOTICES AND REPORTS ON WELLS       6.3         (DO NOT USE THIS FORM FOR PROPOSALS TO DEPLOY NOT REPENT, FORMAC-101) FOR SUCH PROPOSALS)       7.1         I Type of Well:       Well         Well:       Well:         Well:       Well:         OFFERENT RESERVOR, USE 'APPLICATION FOR PERMIT, O'         1. Type of Well:       Well:         Well:       Well:         Well:       OTHER         Anadarko Petroleum Corporation       D.         J. Address of Operator       Anadarko 70         P.O. Drawer 130, Artesia, NM 88211-013Q.**       G.         Ubit Letter       F: 1980       Feet From The       Northt       Line and 1980         Section       36       Township       165       Range 31E       NMP         III.       Check Appropriate Box to Indicate Nature of Notice, Repoint       Yell Yell       SUBSEF         PERFORM REMEDIAL WORK       PLUG AND ABANDON       COMMENCE DRILLING OP       CASING TEST AND CEMEN         PULL OR ALTER CASING       Chearly state all perin	
P.O. Box 2088       P.O. Box 2088         DISTRICTII       Santa Fe, New Mexico 87504-2088         Sol Driver DD, Antela, NM 85210       Santa Fe, New Mexico 87504-2088         DISTRICTIII       SUNDRY NOTICES AND REPORTS ON WELLS         (DO NOT USE THIS FORM FOR PROPOSALS TO BRILL OR TO DEEPEN OR PLUG BACK TOA         DIFFERENT RESERVOR, USE "APPLICATION FOR PERMIT_OP         (DO NOT USE THIS FORM FOR POPOSALS)         (TOPM C-101) FOR SUCH PROPOSALS)         (DO NOT USE THIS FORM FOR PERPORTS ON WELLS         (DO NOT USE THIS FORM FOR PERPORTS ON WEILS         (DO NOT USE THIS FORM FOR PERPORTS ON SUCH PROPOSALS)         (FORM C-101) FOR SUCH PROPOSALS)         (FORM C-101) FOR SUCH PROPOSALS)         (DO NOT USE THIS FORM FOR PETPOSALS TO BRILL OR TO BERMIT_OP         Nume of Operator         Anadarko PEtroleum Corporation         9.         10. Drawer 130, Artesia, NM 88211-0130.3         10. Elevation (Show where DF, RKB, RT, GR, etc.)         4. Well Loadion         Usit Letter F : 1980         10. Elevation (Show where DF, RKB, RT, GR, etc.)         11. Check Appropriate Box to Indicate Nature of Notice, Repoint         NOTICE OF INTENTION TO:         SUBSET         PULOR ALTER CASING         Check Appropriate Box to Indicate Nature of Notice, Repoint      <	dicate Type of Lease STATE FEE Late Oil & Gas Lease No. G-1306 G-1306 G-1306 G-1306 Methods Line Stern Development "B" State Vell No. 1 Yool name or Wildcat ayburg Jackson Queen, Si Feet From The West Line
DISTRICTI       Santa Fe, New Mexico 87504-2088       5.1         DO. Drawer DD, Artesia, NM 55210       Santa Fe, New Mexico 87504-2088       5.1         DOD NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TOA DIFFERENT RESERVOR. USE 'APPLICATION FOR PERMIT', D       7.1         Type of Well:       OM WELL       OTHER         ON The of Well:       OM WELL       OTHER         Name of Operator       Different RESERVOR USE 'APPLICATION FOR PERMIT', D       8.         Address of Operator       Different Reservors       9.         Name of Operator       Different'       8.         P. O. Drawer 130, Artesia, NM 88211-0130, OFT       9.         Veil Location       Township       16S         Baction       36       Township       1980         Section       36       Township       10S       REARGE 31E         NOTICE OF INTENTION TO:       SUBSET         ERFORM REMEDIAL WORK       PLUG AND ABANDON       REMEDIAL WORK       COMMENCE DRILLING OP         CALL OR ALTER CASING       CHANGE PLANS       COMMENCE DRILLING OP         CALL OR ALTER CASING       CHANGE PLANS       COMMENCE DRILLING OP         DIFFERENT Proposed of Completed Operations (Clearly state all periment details, and give perimenu dates, including work) SEE RULE 1103.       Set packer at 3723'.	STATE K FEE Tate Oil & Gas Lease No. G-1306 ease Name or Unit Agreement Name stern Development "B" State Vell No. 1 Pool name or Wildcat ayburg Jackson Queen, Si Feet From The West Lin
GEOD Rio Brazes Rd, Azsec, NM 87410         SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVORM. USE 'APPLICATION FOR PERMIT_O (FORM C-101) FOR SUCH PROPOSALS)         . Type of Well:       ONE         . Type of Well:       ONE         . Nume of Opentor       Anadarko Petroleum Corporation         . Address of Opentor	G-1306 G-1306 ease Name or Unit Agreement Name stern Development "B" State Vell No. 1 Yool name or Wildcat ayburg Jackson Queen, Si Feet From The West Lin
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUB BACK TO A DIFFERENT RESERVOR. USE 'APPLICATION FOR PERMATY OF THE DIFFERENT RESERVOR. USE 'APPLICATION FOR PERMATY OF THE COMMENCE OF THE ADDRESS OF THE COMMENCE OF THE COMM	stern Development "B" State Vell No. 1 Yool name or Wildcat ayburg Jackson Queen, Si Feet From The West Lin
Type of Well:       ONS       OTHER       Well         OF WILL []       OTHER       OTHER       ON         Address of Operator       Anadarko Petroleum Corporation       JN       R.         Address of Operator       OTHER       JN       R.         Address of Operator       OPERATOR       Section       OPERATOR       Section       OPERATOR       Section       OPERATOR       Section       Image: Secti	"B" State Vell No. 1 Yool name or Wildcat ayburg Jackson Queen,Si Feet From The West Lin
Name of Operator       D.       D.       Address of Operator       D.       Address of Operator       D.       Address of Operator       D.       Address of Operator       D.       D.       D.       D.       Address of Operator       D.	1 bool name or Wildcat ayburg Jackson Queen, S. Feet From The West Lin
Address of Operator       9.         P.O. Drawer 130, Artesia, NM 88211-0130.       Orffet         Well Location       F: 1980         Unit Letter       F: 1980         Section       36         Township       16S         Range       31E         NMP         Section       36         Township       16S         Range       31E         NMP         10. Elevation (Show whether DF, RKB, RT, GR, etc.)         4197'       GL         H.       Check Appropriate Box to Indicate Nature of Notice, Report         NOTICE OF INTENTION TO:       SUBSET         REMEDIAL WORK       PLUG AND ABANDON         CHANGE PLANS       COMMENCE DRILLING OP         CASING TEST AND CEMEN       CASING TEST AND CEMEN         ULL OR ALTER CASING       CHANGE PLANS         DTHER:       OTHER:         Tested Completed Operations (Clearly state all periment details, and give periment dates, including work) SEE RULE 1103.         1. RUPU. TOH with rods and tubing.         2. WIH with 5½" tension packer on 2-3/8" tubing.         chemical water.         3. Set packer at 3723'.       (23' above top perf).         4. Tested casing to 520#. Lost 25# in 15 minutes <t< td=""><td>ayburg Jackson Queen,Si</td></t<>	ayburg Jackson Queen,Si
Unit Letter       F       : 1980       Feet From The       Norht       Line and       . 1980         Section       36       Township       16S       Range       31E       NMPP         10. Elevation (Show whether DF, RKB, RT, GR, etc.)       4197' GL       4197' GL       10.       Elevation (Show whether DF, RKB, RT, GR, etc.)         11.       Check Appropriate Box to Indicate Nature of Notice, Report Algorithm REMEDIAL WORK       PLUG AND ABANDON       REMEDIAL WORK         ERFORM REMEDIAL WORK       PLUG AND ABANDON       REMEDIAL WORK       COMMENCE DRILLING OP         Casing TEST AND CHANGE       Change PLANS       COMMENCE DRILLING OP         ULL OR ALTER CASING       CHANGE PLANS       COMMENCE DRILLING OP         Casing TEST AND CEMEN       OTHER:       Test         12 Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, including or work) SEE RULE 1103.       Chemical Water.         13.       RUPU.       TOH with rods and tubing.       2.         2.       WIH with 5½" tension packer on 2-3/8" tubing. chemical water.       3.         3.       Set packer at 3723'.       (23' above top perf).         4.       Tested casing to 520#. Lost 25# in 15 minutes         5.       Ran rods back in tubing. Note: Will leave pac in hole.	Feet From The West Lin
Unit Letter       F       : 1980       Feet From The       Norht       Line and       1980         Section       36       Township       16S       Range       31E       NMPP         10       Elevation (Show whether DF, RKB, RT, GR, etc.)       4197' GL       4197' GL       10         11.       Check Appropriate Box to Indicate Nature of Notice, Report NOTICE OF INTENTION TO:       SUBSEC         ERFORM REMEDIAL WORK       PLUG AND ABANDON       REMEDIAL WORK         COMMENCE OF INTENTION TO:       SUBSEC         ERFORM REMEDIAL WORK       PLUG AND ABANDON       REMEDIAL WORK         COMMENCE OF INTENTION TO:       SUBSEC         ERFORM REMEDIAL WORK       PLUG AND ABANDON       REMEDIAL WORK         COMMENCE DRILLING OP       CASING TEST AND CEMEN         OTHER:       Test       Commence Drilling OP         CASING TEST AND CEMEN       OTHER:       Test         12 Describe Proposed or Completed Operations (Clearly state all periment datails, and give periment dates, including or work) SEE RULE 1103.       RUPU.         13.       RUPU.       TOH with rods and tubing.       Chemical water.         3.       Set packer at 3723'.       (23' above top perf).         4.       Tested casing to 520 #.       Lost 25 # in 15 minutes <td< td=""><td></td></td<>	
Section       10. Elevation (Show whether DP, RKB, RT, GR, etc.)         10. Elevation (Show whether DP, RKB, RT, GR, etc.)       4197' GL         1.       Check Appropriate Box to Indicate Nature of Notice, Report         NOTICE OF INTENTION TO:       SUBSED         ERFORM REMEDIAL WORK       PLUG AND ABANDON       REMEDIAL WORK         EMPORARILY ABANDON       CHANGE PLANS       COMMENCE DRILLING OP         ULL OR ALTER CASING       CASING TEST AND CEMEN         THER:       OTHER:       Test         12. Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, including work) SEE RULE 1103.       Clearly state all periment details, and give periment dates, including work) SEE RULE 1103.         12. Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, including work) SEE RULE 1103.       NUT TOH with rods and tubing.         2. WIH with 5½" tension packer on 2-3/8" tubing.       Chemical water.         3. Set packer at 3723'.       (23' above top perf).         4. Tested casing to 520#.       Lost 25# in 15 minutes         5. Ran rods back in tubing.       Note: Will leave pac         6. RDPU.       NOTE:       Test witnessed by NMOCD and chart	- 11
Section       10. Elevation (Show whether DP, RKB, RT, GR, etc.)         10. Elevation (Show whether DP, RKB, RT, GR, etc.)       4197' GL         1.       Check Appropriate Box to Indicate Nature of Notice, Report         NOTICE OF INTENTION TO:       SUBSED         ERFORM REMEDIAL WORK       PLUG AND ABANDON       REMEDIAL WORK         EMPORARILY ABANDON       CHANGE PLANS       COMMENCE DRILLING OP         ULL OR ALTER CASING       CASING TEST AND CEMEN         THER:       OTHER:       Test         12. Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, including work) SEE RULE 1103.       Clearly state all periment details, and give periment dates, including work) SEE RULE 1103.         12. Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, including work) SEE RULE 1103.       NUT TOH with rods and tubing.         2. WIH with 5½" tension packer on 2-3/8" tubing.       Chemical water.         3. Set packer at 3723'.       (23' above top perf).         4. Tested casing to 520#.       Lost 25# in 15 minutes         5. Ran rods back in tubing.       Note: Will leave pac         6. RDPU.       NOTE:       Test witnessed by NMOCD and chart	Eddy County
III.       Check Appropriate Box to Indicate Nature of Notice, Report         NOTICE OF INTENTION TO:       SUBSET         ERFORM REMEDIAL WORK       PLUG AND ABANDON       REMEDIAL WORK         EMPORARILY ABANDON       CHANGE PLANS       COMMENCE DRILLING OP         ULL OR ALTER CASING       CHANGE PLANS       COMMENCE DRILLING OP         OTHER:       OTHER:       Text         12 Describe Proposed or Completed Operations (Clearly state all pertiment details, and give pertiment dates, including work) SEE RULE 1103.       OTHER:       Text         12. RUPU.       TOH with rods and tubing.       Chemical water.       3. Set packer at 3723'. (23' above top perf).       4. Tested casing to 520#. Lost 25# in 15 minutes         5. Ran rods back in tubing.       Note: Will leave pac in hole.       6. RDPU.       NOTE: Test witnessed by NMOCD and chart	
NOTICE OF INTENTION TO:       SUBSET         ERFORM REMEDIAL WORK       PLUG AND ABANDON       REMEDIAL WORK         EMPORARILY ABANDON       CHANGE PLANS       COMMENCE DRILLING OP         ULL OR ALTER CASING       CASING TEST AND CEMEN         OTHER:       OTHER:       Ten         12 Describe Proposed or Completed Operations (Clearly state all periment details, and give pertinent dates, including work) SEE RULE 1103.       1. RUPU. TOH with rods and tubing.         2. WIH with 5½" tension packer on 2-3/8" tubing.       2. WIH with 5½" tension packer on 2-3/8" tubing.         3. Set packer at 3723'. (23' above top perf).       4. Tested casing to 520#. Lost 25# in 15 minutes         5. Ran rods back in tubing. Note: Will leave pac in hole.       6. RDPU.         NOTE:       Test witnessed by NMOCD and chart	
In the little of intrelition term         ERFORM REMEDIAL WORK       PLUG AND ABANDON       REMEDIAL WORK         EMPORARILY ABANDON       CHANGE PLANS       COMMENCE DRILLING OP         ULL OR ALTER CASING       CHANGE PLANS       CASING TEST AND CEMEN         OTHER:       OTHER:       Tel         12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1103.       NULPU. TOH with rods and tubing.         2. WIH with 5½" tension packer on 2-3/8" tubing.       Chemical water.         3. Set packer at 3723'. (23' above top perf).       Set packer at 3723'. Lost 25# in 15 minutes         5. Ran rods back in tubing. Note: Will leave pac in hole.       NOTE: Test witnessed by NMOCD and chart	t, or Other Data QUENT REPORT OF:
EMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP ULL OR ALTER CASING CHANGE PLANS COMMENCE DRILLING OP ULL OR ALTER CASING CHANGE CHANGE PLANS COMMENCE DRILLING OP CASING TEST AND CEMEN OTHER: OTHER: Ter 212 Describe Proposed or Completed Operations (Clearly state all periment datasis, and give pertiment dates, including of work) SEE RULE 1103. 1. RUPU. TOH with rods and tubing. 2. WIH with 5½" tension packer on 2-3/8" tubing. chemical water. 3. Set packer at 3723'. (23' above top perf). 4. Tested casing to 520#. Lost 25# in 15 minutes 5. Ran rods back in tubing. Note: Will leave pac in hole. 6. RDPU. <u>NOTE</u> : Test witnessed by NMOCD and chart	
ULL OR ALTER CASING       CASING TEST AND CEMEN         OTHER:       OTHER:       Test         12 Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, including work) SEE RULE 1103.       OTHER:       Test         12. WIH with 5½" tension packer on 2-3/8" tubing.       Chemical water.       Set packer at 3723'.       (23' above top perf).         4. Tested casing to 520#.       Lost 25# in 15 minutes         5. Ran rods back in tubing.       Note: Will leave pac in hole.         6. RDPU.       NOTE:       Test witnessed by NMOCD and chart	
OTHER: OTHER: OTHER: Text OTHER: OTHER: Text 12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1103. <ol> <li>RUPU. TOH with rods and tubing.</li> <li>WIH with 5½" tension packer on 2-3/8" tubing. chemical water.</li> <li>Set packer at 3723'. (23' above top perf).</li> <li>Tested casing to 520#. Lost 25# in 15 minutes</li> <li>Ran rods back in tubing. Note: Will leave pac in hole.</li> <li>RDPU.</li> </ol> <u>NOTE</u> : Test witnessed by NMOCD and chart	IS PLUG AND ABANDONMENT
<ul> <li>12. Describe Proposed or Completed Operations (Clearly state all periment details, and give pertiment dates, including work) SEE RULE 1103.</li> <li>1. RUPU. TOH with rods and tubing.</li> <li>2. WIH with 5½" tension packer on 2-3/8" tubing. chemical water.</li> <li>3. Set packer at 3723'. (23' above top perf).</li> <li>4. Tested casing to 520#. Lost 25# in 15 minutes</li> <li>5. Ran rods back in tubing. Note: Will leave pac in hole.</li> <li>6. RDPU.</li> </ul>	т јов 🛄
<ul> <li>12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1103.</li> <li>1. RUPU. TOH with rods and tubing.</li> <li>2. WIH with 5½" tension packer on 2-3/8" tubing. chemical water.</li> <li>3. Set packer at 3723'. (23' above top perf).</li> <li>4. Tested casing to 520#. Lost 25# in 15 minutes</li> <li>5. Ran rods back in tubing. Note: Will leave pac in hole.</li> <li>6. RDPU.</li> </ul> NOTE: Test witnessed by NMOCD and chart	porarily Abandon
<pre>work) SEE RULE 1103. 1. RUPU. TOH with rods and tubing. 2. WIH with 5½" tension packer on 2-3/8" tubing. chemical water. 3. Set packer at 3723'. (23' above top perf). 4. Tested casing to 520#. Lost 25# in 15 minutes 5. Ran rods back in tubing. Note: Will leave pac in hole. 6. RDPU. NOTE: Test witnessed by NMOCD and chart</pre>	stimated date of starting any proposed
<ol> <li>WIH with 5½" tension packer on 2-3/8" tubing. chemical water.</li> <li>Set packer at 3723'. (23' above top perf).</li> <li>Tested casing to 520#. Lost 25# in 15 minutes</li> <li>Ran rods back in tubing. Note: Will leave pac in hole.</li> <li>RDPU.</li> <li><u>NOTE</u>: Test witnessed by NMOCD and chart</li> </ol>	
<ol> <li>Set packer at 3723'. (23' above top perf).</li> <li>Tested casing to 520#. Lost 25# in 15 minutes</li> <li>Ran rods back in tubing. Note: Will leave pac in hole.</li> <li>RDPU.</li> <li><u>NOTE</u>: Test witnessed by NMOCD and chart</li> </ol>	Circulated hole with
<ol> <li>Tested casing to 520#. Lost 25# in 15 minutes</li> <li>Ran rods back in tubing. Note: Will leave pac in hole.</li> <li>RDPU.</li> <li><u>NOTE</u>: Test witnessed by NMOCD and chart</li> </ol>	
<ol> <li>S. Ran rods back in tubing. Note: Will leave pac in hole.</li> <li>RDPU.</li> <li><u>NOTE</u>: Test witnessed by NMOCD and chart</li> </ol>	(chart attached).
6. RDPU. <u>NOTE</u> : Test witnessed by NMOCD and chart	ker, tubing, and rods
NOTE: Test witnessed by NMOCD and chart	
	is attached.
	is attached.
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	is attached.
SKONATURE Mich Brasswell MILE Field Fore	
TYPEOR PRINT NAME Mike Braswell	
(This space for State, Use)	

CONDITIONS OF APPROVAL, IF ANY: