	UNITED STATES MENT OF THE INTERI		Express August 5 LEASE DESIGNATION 1 LC-056302A	31, 1985 AND SEBTAL NO. 2	
(Do not use this form for prop	TICES AND REPORTS (onais to drill or to deepen or plus CATION FOR PERMIT—" for such p	represents a different reservoir.	8. IF INDIAN, ALLOTTEE N/A	OR TRIBE NAME	
OIL X GAS OTHER	JA	N 2 5 1993	7. UNIT AGREEMENT NA N/A	ME	
SDX RESOURCES, INC.		O. C. D. WAA COPUSE	8. FARM OR LEASE NAM Kennedy John	^	
ADDEESS OF OPERATOR			9. WBLL NO.		
P. O. Box 5061	704-5061	6			
LOCATION OF WELL (Report location clearly and in accordance with any State requirements."			10. FIELD AND POOL, OR WILDCAT		
See also space 17 below.) At surface			Grayburg Jackson		
Unit M Sec. 35 T16S			11. SBC., T., R., M., OR BLK. AND SURVEY OR AREA		
R31	R31E GGO FSI E GGO FUL			Sec. 35 T16S R31E	
4. PERMIT NO.	15. ELEVATIONS (Show whether DF	, RT, GR, etc.)	12. COUNTY OF PARISH Eddy	13. STATE NM	
6. Check A	ppropriate Box To Indicate N	lature of Notice, Report, or (Other Data		
NOTICE OF INTE	NTION TO :	SUBSEQ	UBNT REPORT OF :		
TEST WATER SHUT-OFF	PELL OB ALTER CASING	WATER SHUT-OFF	EEPAIRING W		
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CA	BING	
SHOOT OR ACIDIZE	ABANDON* X	SHOOTING OR ACIDIZING	ABANDONMEN	T.	
REPAIR WELL X	CHANGE PLANS	(Other)			
(Other)		(NOTE: Report results of multiple completion on Well Completion or Recompletion Beport and Log form.)			
 DESCRIBE PROPOSED OR COMPLETED OF proposed work. If well is direct nent to this work.) * 	FRATIONS (Clearly state all pertinen ionally drilled, give subsurface loca	t details, and give pertinent dates, tions and measured and true vertic	, including estimated date al depths for all markers	of starting any and zones perti-	
	well, test casing for				



18. I hereby certify that the presonal of the and correct SIGNED	TITLE _	Vice-President	DATE	1/13/93
(This space for Federal or State of cerse) APPROVED BY CONDITIONS OF APPROVAL, IF ANT:	V _{TITLE}		DATE _/	1-2193

*See Instructions on Reverse Side

KENNEDY JOHNSON A-#6 M, Sec. 35, T16S, R31E Eddy County, New Mexico LC 056302A

Casing: 13 3/8" set at 33'. 4 1/2", 9.5#, set at 3860'. Cemented with 210 sx.

Plugging Procedure

- 1. Move in, rig up, nipple up BOP and dig workover pit.
- 2. Rig up wire line and run junk basket to 3483'. Set CIBP at 3483' and cap with 35' of cement.
- 3. TIH with work string of 2 3/8" tubing to +/- 3400' and circulate hole with salt gel.
- 4. Spot 25 sx plug 3000'-2850'.
- 5. Perforate casing at 2000' and pump 35 sx plug. Leave top of plug at 1850'.
- 6. Perforate casing at 950' and pump 35 sx plug. Leave top of plug at 800'.
- 7. Spot 10 sx surface plug and install dry hole marker.
- 8. Clean location and close road.

CKJPP.FRM

-+	+ + + + + + +	+ 		WE: LSI LOO AP: FII OII DR: GL SPU TD	E NAME <u>Ken</u> C. <u>M</u> 35- I# ELD <u>GR-Jac</u> L PUR. ILL AND CO IG. OP. <u>Wa</u> 4017 JD DATE <u>1</u> 3860	Johnson nedy Joh 16s-31e kson Q-G kson Q-G D-G D-G DF 2-9-62	<u>nson A</u> Fed. <u>660 fsl</u> STAT R-SA GAS d Associate	s TE <u>12-30-62</u> _3853
CASI	NG .	HOLE SIZE	CASING	WT. GRADE	DEPTH SET	SKS	тос	+
	-	7 7/8	<u>13 3/8</u> <u>4 1/2</u>	9.5	33	30		+ !
	-		<u> </u>		3860	210		
COMPI	LETIO	N						
							90,3533-37 598, & 3670 gals. acid.	with 2 jets • Frac
BOPD	50	E	WPD 20	<u>in</u> 24	ho <u>ur test</u>	BHP		
9-10- jt.	-7 <u>6_Pi</u> _R <u>an_t</u>	<u>illed</u> p tubing,	pump, pulle	d tubing				hole in 28th
BOPD		E		MCFI	PD	BHP		
DATE tbg., derri	<u>1-7&8</u> , pull ick, 1	3-80 Led tbg Laid ro	ds down, R	led pump jts. w/H ligged do	own.	down. I	y valve, pre Laid down tu	<u>ibing out of</u>
<u> </u>								
WELL	INVEN TUBIN	ITORY:						······
	RODS							
	PUMP							
	ANCHO		SN					
	PACKE	R				· · · · · · · · · · · · · · · · · · ·		<u> </u>
	MOTOR	L	UNITID#					
	WELLH	EAD	ID# METER #					
REMAR	uks: _				MET	EK #		