

UNIT STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OFFICE FOR NUNUT
OF COPIES REQUIRED
(Other instructions on re-
verse side)

DEPARTMENT DISTRICT
Modified Form No.
NIXO-3160-4

CISF

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☐ OIL WELL ☒ GAS WELL ☐ OTHER		3a. Area Code & Home No.		5. LEASE DESIGNATION AND SERIAL NO. LC-060543	
2. NAME OF OPERATOR Kennedy Oil Co., Inc.				6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR P. O. Box 47, Mayhill, NM 88339				7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 10 10/5 1980/4 'NESW'		JUN 8 '90 O. C. D. ARTESIA, OFFICE		8. FARM OR LEASE NAME Rowley Federal	
14. PERMIT NO.		15. ELEVATIONS (Show whether DE, RT, GR, etc.)		9. WELL NO. #1	
				10. FIELD AND POOL, OR WILDCAT	
				11. SEC., T., R., W., OR BLK. AND RURBYT OR AREA Sec. 20, T-16S, R-31E	
				12. COUNTY OR PARISH Eddy	
				13. STATE NM	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	☐	WATER SHUT-OFF	☐
FRACURE TREAT	☐	FRACURE TREATMENT	☐
SHOOT OR ACIDIZE	☐	SHOOTING OR ACIDIZING	☐
REPAIR WELL	☐	(Other)	☐
(Other)	☐	(Note: Report results of multiple completion on Well Completion or Reconpletion Report and Log form.)	☐
PULL OR ALTER CASING	☐	REPAIRING WELL	☐
MULTIPLE COMPLETE	☐	ALTERING CASING	☐
ABANDON*	☒	ABANDONMENT*	☐
CHANGE PLANE	☐		

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

1. Pull production equipment. Set 5 1/2" CIBP @ 3300' w/ 35' cement on top.
2. Set 25 sk. cement plug @ 1600'.
3. Set 25 sk. cement plug @ 500'.
4. Set 25 sk. cement plug @ 75' to surface & install P & A marker.

RECEIVED
MAY 31 11 33 AM '90
CARLSON
AREA HEADQUARTERS

18. I hereby certify that the foregoing is true and correct.

SIGNED <i>Rayman M. Malandro</i>	TITLE P & A Supervisor- Baber	DATE 5-30-90
(This space for Federal or State office use)		
APPROVED BY	TITLE	DATE 6 5 90
CONDITIONS OF APPROVAL, IF ANY:		

*See Instructions on Reverse Side