

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Budget Bureau No. 1004-012
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO.

NM 02427

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

west square lake unit

8. FARM OR LEASE NAME

Tract 15

9. WELL NO.

10

10. FIELD AND POOL, OR WILDCAT

Square Lake

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 34- 16s R30e

12. COUNTY OR PARISH

13. STATE

Eddy

NM

1. OIL WELL ☐ GAS WELL ☐ OTHER WIW ☒

2. NAME OF OPERATOR

3. ADDRESS OF OPERATOR
J. Cleo Thompson

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface
P.O. Box 6445 Odessa, Texas 79767
O.C.D. OFFICE

2080' FSL & 660' FWL of Sec 34

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☐

MULTIPLE COMPLETION ☐

ABANDON* ☐

CHANGE PLANS ☐

Plug & Abandon ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other)

REPAIRING WELL ☐


ALTERING CASING ☐

ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

- (1) CIBP @ 2900' w/35' cmt on top.
(2) Perf. @ 2225' Set CR at 2200. Pump 50 sx cmt. (Queens and Beverly Rivers)
(3) Perf. 1240' set CR @ 1220' pump 25 sx. cmt. Set 100' cmt. on top of CR. (base of salt)
(4) Perf. at 420' (50' above salt.) Pump down 4½ csg circulate to surface. Leave 4½' full.
(5) Cut csg. 3' below ground. Set surface marker.



Johnny Robinson was on hand during operation
(State)

Post ID-2
5-8-87
R4A

18. I hereby certify that the foregoing is true and correct

SIGNED

Ernest Pinnell
for Ernest Pinnell

TITLE

Production Foreman
Production Mgr.

DATE

5-2-86

APPROVED BY *Orig. Sgd. David E. Mari*
CONDITIONS OF APPROVAL, IF ANY:

TITLE

AREA MANAGER

CARLEBOO RESOURCE AREA

DATE

4-24-87

*See Instructions on Reverse Side