

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE	✓	
FILE	✓	✓
U.S.G.S.		
LAND OFFICE		
OPERATOR	✓	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E 8560
7. Unit Agreement Name
8. Farm or Lease Name Southern Union State
9. Well No. 1
10. Field and Pool, or Wildcat Wichita River
12. County Eddy

<p><b>SUNDRY NOTICES AND REPORTS ON WELLS RECEIVED</b></p> <p>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</p>	
1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- AUG - 3 '90	
2. Name of Operator Remuda Operating Company ✓	
3. Address of Operator 301 N. Colorado, Ste 150, Midland, Tx. 79701	ARTESIA OFFICE
4. Location of Well UNIT LETTER J, 2310 FEET FROM THE South LINE AND 2310 FEET FROM THE East LINE, SECTION 13 TOWNSHIP 16S RANGE 31E NMPM.	
15. Elevation (Show whether DF, RT, CR, etc.) 4387	

<p>16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data</p> <p>NOTICE OF INTENTION TO:</p> <p>PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input checked="" type="checkbox"/> REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/></p> <p>TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/></p> <p>PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/></p>		<p>SUBSEQUENT REPORT OF:</p>
---	--	------------------------------

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spot 20 sx plug @ 3430 & tag, pull 4 1/2 casing and spot 35 sx @ cutoff & tag, spot 100' plug @ ~~2150-2250~~, 100' plug @ ~~1200-1300~~, 50 sx plug @ 8 5/8 set @ 433', 10 sx plug @ top. ~~2250-2350~~ 1335-1435

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <u>Neil Lister</u>	TITLE <u>Agent</u>	DATE <u>8/1/90</u>
APPROVED BY <u>Danell Moore</u>	TITLE <u>Geologist</u>	DATE <u>8/21/90</u>
CONDITIONS OF APPROVAL, IF ANY:		