NO. OF COPIES RECLIVED		. Form C-103
DISTRIBUTION		Supersedes Old C+102 and C+103
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
FILE	RECENVED	Sa. Indicate Type of Lease
U.S.G.S.	K Las instantion of the	State X Fee
OPERATOR	ana e. A	5. State Oil & Gas Lease No.
	. MAR 2 1971	NM2-K-3630
SUNDR SUNDR (DO NOT USE THIS FORM FOR PRO USE "APPLICATI	Y NOTICES AND REPORTS ON WELLS POSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT REBERVOIR. ION FOR PERMIT	
1.	ARTESIA, UVPILE	7. Unit Agreement Name
WELL X WELL	OTHER.	
2. Name of Operator		8. Farm or Lease Name Aid State
INEXCO OIL COMPANY 3. Address of Operator	/	9. Well No.
	., Midland, Texas 79701	
4. Location of Well	and a general sector of the	10. Field and Pool, or Wildcat
UNIT LETTERA	660 PEET FROM THE N LINE AND 660 PEET	WILDCAT
	24 176 285	
THE LINE, SECTION	N 24 TOWNSHIP RANGE 28E	имрм. (////////////////////////////////////
, , , , , , , , , , , , , , , , , , ,	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	3715.5 Gr.	Eddy
16. Check A	Appropriate Box To Indicate Nature of Notice, Report o	
NOTICE OF IN	· · -	JENT REPORT OF:
TEMPORARILY ABANDON	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
PULL OR ALTER CASING	CHANGE PLANS	
	OTHER	
-		
OTHER		
OTHER	erations (Clearly state all pertinent details, and give pertinent dates, incl	uding estimated date of starting any proposed
OTHER 17. Describe Proposed or Completed Ope work) SEE RULE 1103.	erations (Clearly state all pertinent details, and give pertinent dates, incl	luding estimated date of starting any proposed
work) SEE RULE 1708.		
On 1-20-71 with verb	al permission we set 100' plugs @ 8600-8700,	
work) SEE RULE 1708.	al permission we set 100' plugs @ 8600-8700,	
0n 1-20-71 with verb 5900-6000, 3600-3700	al permission we set 100' plugs @ 8600-8700, , 1950-2050.	8300-8400, 7000-7100,
0n 1-20-71 with verb 5900-6000, 3600-3700	al permission we set 100' plugs @ 8600-8700, , 1950-2050. casing, set plug in top of stub plug at base	8300-8400, 7000-7100,
Work) SEE RULE 1703. 0n 1-20-71 with verb 5900-6000, 3600-3700 We will pull 8-5/8" set plug at surface	al permission we set 100' plugs @ 8600-8700, , 1950-2050. casing, set plug in top of stub plug at base with marker.	8300-8400, 7000-7100, of surface pipe &
Work) SEE RULE 1703. On 1-20-71 with verb 5900-6000, 3600-3700 We will pull 8-5/8" set plug at surface However, Pennzoil, 1	al permission we set 100' plugs @ 8600-8700, , 1950-2050. casing, set plug in top of stub plug at base with marker. nc. wishes to re-enter this well at this time	8300-8400, 7000-7100, of surface pipe & e to test the Morrow
On 1-20-71 with verb 5900-6000, 3600-3700 We will pull 8-5/8" set plug at surface However, Pennzoil, 1 horizon. They wish	al permission we set 100' plugs @ 8600-8700, , 1950-2050. casing, set plug in top of stub plug at base with marker. nc. wishes to re-enter this well at this time to re-enter the well with the 8-5/8" casing a	8300-8400, 7000-7100, of surface pipe & e to test the Morrow as is and they will
On 1-20-71 with verb 5900-6000, 3600-3700 We will pull 8-5/8" set plug at surface However, Pennzoil, 1 horizon. They wish then accept the resp	al permission we set 100' plugs @ 8600-8700, , 1950-2050. casing, set plug in top of stub plug at base with marker. nc. wishes to re-enter this well at this time to re-enter the well with the 8-5/8" casing a ponsibility of plugging this well as per New N	8300-8400, 7000-7100, of surface pipe & e to test the Morrow as is and they will
On 1-20-71 with verb 5900-6000, 3600-3700 We will pull 8-5/8" set plug at surface However, Pennzoil, 1 horizon. They wish	al permission we set 100' plugs @ 8600-8700, , 1950-2050. casing, set plug in top of stub plug at base with marker. nc. wishes to re-enter this well at this time to re-enter the well with the 8-5/8" casing a ponsibility of plugging this well as per New N	8300-8400, 7000-7100, of surface pipe & e to test the Morrow as is and they will
On 1-20-71 with verb 5900-6000, 3600-3700 We will pull 8-5/8" set plug at surface However, Pennzoil, 1 horizon. They wish then accept the resp	al permission we set 100' plugs @ 8600-8700, , 1950-2050. casing, set plug in top of stub plug at base with marker. nc. wishes to re-enter this well at this time to re-enter the well with the 8-5/8" casing a ponsibility of plugging this well as per New N	8300-8400, 7000-7100, of surface pipe & e to test the Morrow as is and they will
On 1-20-71 with verb 5900-6000, 3600-3700 We will pull 8-5/8" set plug at surface However, Pennzoil, 1 horizon. They wish then accept the resp	al permission we set 100' plugs @ 8600-8700, , 1950-2050. casing, set plug in top of stub plug at base with marker. nc. wishes to re-enter this well at this time to re-enter the well with the 8-5/8" casing a ponsibility of plugging this well as per New N	8300-8400, 7000-7100, of surface pipe & e to test the Morrow as is and they will
On 1-20-71 with verb 5900-6000, 3600-3700 We will pull 8-5/8" set plug at surface However, Pennzoil, 1 horizon. They wish then accept the resp	al permission we set 100' plugs @ 8600-8700, , 1950-2050. casing, set plug in top of stub plug at base with marker. nc. wishes to re-enter this well at this time to re-enter the well with the 8-5/8" casing a ponsibility of plugging this well as per New N	8300-8400, 7000-7100, of surface pipe & e to test the Morrow as is and they will
On 1-20-71 with verb 5900-6000, 3600-3700 We will pull 8-5/8" set plug at surface However, Pennzoil, 1 horizon. They wish then accept the resp	al permission we set 100' plugs @ 8600-8700, , 1950-2050. casing, set plug in top of stub plug at base with marker. nc. wishes to re-enter this well at this time to re-enter the well with the 8-5/8" casing a ponsibility of plugging this well as per New N	8300-8400, 7000-7100, of surface pipe & e to test the Morrow as is and they will
On 1-20-71 with verb 5900-6000, 3600-3700 We will pull 8-5/8" set plug at surface However, Pennzoil, 1 horizon. They wish then accept the resp	al permission we set 100' plugs @ 8600-8700, , 1950-2050. casing, set plug in top of stub plug at base with marker. nc. wishes to re-enter this well at this time to re-enter the well with the 8-5/8" casing a ponsibility of plugging this well as per New N	8300-8400, 7000-7100, of surface pipe & e to test the Morrow as is and they will
On 1-20-71 with verb 5900-6000, 3600-3700 We will pull 8-5/8" set plug at surface However, Pennzoil, 1 horizon. They wish then accept the resp	al permission we set 100' plugs @ 8600-8700, , 1950-2050. casing, set plug in top of stub plug at base with marker. nc. wishes to re-enter this well at this time to re-enter the well with the 8-5/8" casing a ponsibility of plugging this well as per New N	8300-8400, 7000-7100, of surface pipe & e to test the Morrow as is and they will
<pre>On 1-20-71 with verb 5900-6000, 3600-3700 We will pull 8-5/8" set plug at surface However, Pennzoil, 1 horizon. They wish then accept the resp Commission instructi</pre>	al permission we set 100' plugs @ 8600-8700, , 1950-2050. casing, set plug in top of stub plug at base with marker. nc. wishes to re-enter this well at this time to re-enter the well with the 8-5/8" casing a ponsibility of plugging this well as per New N	8300-8400, 7000-7100, of surface pipe & e to test the Morrow as is and they will
<pre>On 1-20-71 with verb 5900-6000, 3600-3700 We will pull 8-5/8" set plug at surface However, Pennzoil, 1 horizon. They wish then accept the resp Commission instructi</pre>	wal permission we set 100' plugs @ 8600-8700, , 1950-2050. casing, set plug in top of stub plug at base with marker. nc. wishes to re-enter this well at this time to re-enter the well with the 8-5/8" casing a consibility of plugging this well as per New M ons.	8300-8400, 7000-7100, of surface pipe & e to test the Morrow as is and they will Mexico Oil Conservation
<pre>On 1-20-71 with verb 5900-6000, 3600-3700 We will pull 8-5/8" set plug at surface However, Pennzoil, 1 horizon. They wish then accept the resp Commission instructi</pre>	Pal permission we set 100' plugs @ 8600-8700, , 1950-2050. casing, set plug in top of stub plug at base with marker. nc. wishes to re-enter this well at this time to re-enter the well with the 8-5/8" casing a ponsibility of plugging this well as per New M ons.	8300-8400, 7000-7100, of surface pipe & e to test the Morrow as is and they will
<pre>On 1-20-71 with verb 5900-6000, 3600-3700 We will pull 8-5/8" set plug at surface However, Pennzoil, 1 horizon. They wish then accept the resp Commission instructi</pre>	wal permission we set 100' plugs @ 8600-8700, , 1950-2050. casing, set plug in top of stub plug at base with marker. nc. wishes to re-enter this well at this time to re-enter the well with the 8-5/8" casing a consibility of plugging this well as per New M ons.	8300-8400, 7000-7100, of surface pipe & e to test the Morrow as is and they will Mexico Oil Conservation
<pre>On 1-20-71 with verb 5900-6000, 3600-3700 We will pull 8-5/8" set plug at surface However, Pennzoil, 1 horizon. They wish then accept the resp Commission instructi</pre>	wal permission we set 100' plugs @ 8600-8700, , 1950-2050. casing, set plug in top of stub plug at base with marker. nc. wishes to re-enter this well at this time to re-enter the well with the 8-5/8" casing a consibility of plugging this well as per New M ons.	8300-8400, 7000-7100, of surface pipe & e to test the Morrow as is and they will Mexico Oil Conservation
<pre>On 1-20-71 with verb 5900-6000, 3600-3700 We will pull 8-5/8" set plug at surface However, Pennzoil, 1 horizon. They wish then accept the resp Commission instructi</pre>	And permission we set 100' plugs @ 8600-8700, , 1950-2050. casing, set plug in top of stub plug at base with marker. nc. wishes to re-enter this well at this time to re-enter the well with the 8'-5/8'' casing a consibility of plugging this well as per New N ons. And the set of my knowledge and bellef. Manager, Prod. & Drlg.	8300-8400, 7000-7100, of surface pipe & e to test the Morrow as is and they will Mexico Oil Conservation