

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	<input checked="" type="checkbox"/>
LAND OFFICE	<input checked="" type="checkbox"/>
OPERATOR	<input checked="" type="checkbox"/>

OIL CONSERVATION DIVISION
P.O. BOX 280
SANTA FE, NEW MEXICO 87501

FEB 04 1983

O. C. D.

Form C-103
Revised 10-1-79

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Pennzoil Company	8. Farm or Lease Name Aid State <i>Camp</i>
3. Address of Operator P.O. Drawer 1828, Midland, Texas 79702	9. Well No. 1
4. Location of Well UNIT LETTER <u>A</u> <u>660</u> FEET FROM THE <u>North</u> <u>660</u> FEET FROM THE <u>East</u> <u>24</u> LINE, SECTION <u>17-S</u> TOWNSHIP <u>28-E</u> RANGE <u>28-E</u> N.M.P.M.	10. Field and Pool, or Wildcat Aid Morrow Gas
15. Elevation (Show whether DF, RT, GR, etc.) 3715 GR	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Estimated date to commence following procedure is 2-15-83.

- 1) Set C.I.B.P. at 7,150' and dump 35' of cement on top to temporarily abandon the Morrow zone.
- 2) Peforate 5-1/2" production casing over the following intervals:
7005' - 7108', 7042' - 7048' and 7060' - 7063'.
- 3) Stimulate intervals with acid and swab back load.
- 4) Put well on beam lift and test.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Bruce Smith TITLE Petroleum Engineer DATE 1-26-83

APPROVED BY _____ TITLE Original Signed By Leslie A. Clements DATE FEB 10 1983
Supervisor District II