

rams bop. Leak to flange between manifold cross and wing value off manifold cross (pipe

rack side) with no pressure being applied. Tightened.