Form 3160-5 (August 1999)		-	CD-Artes	-	FORM APPROVED CS	
	DEPARINT OF THE INTERIOF				OMB No. 1004-0135	
	BUREAU OF	LAND MANAGEMEN	1T		xpires November 30, 2000	
			WELLS	5. Lease Seria	il No.	
		S AND REPORTS ON		NM - 0219	603	
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.					ottee or Tribe Name	
u						
				7. If Unit or C	A/Agreement Name and/or N	
SUBMIT	IN TRIPLICATE - C	Other Instructions	on reverse side			
1. Type of Well	<b>—</b>		71819-121-23	8. Well Name	and No.	
Oil Well	X Gas Well	Other	11819202125 233	FEDERAL	BZ COM #12	
2. Name of Operator	. (	3b. Phone No. (inclui	12 100	9. API Well		
Yates Petroleum Co	orporation /			30-015-21		
Ba Address		3b. Phone No. (inclu	de atéa code	E211	Pool, or Explc ratory Area	
105 S. 4th Street - A		000 740 1471	ARTESIA		REEK/ STRAWN PERM	
E-Location of Weil (Foolage, Se	<del>:C.,-I.,R.,-M.,</del> -OF-SUFVEY-DeSCF	(ption)		S 11. County or	Parish State	
SECTION 21-T17S-R25E	1980' FSL & 1980' FV	VI	- <sup>12</sup> %			
	1900 I SE & 1900 I W	* 🗅	2388.73			
12 CHECK A	PPROPRIATE BOX(E	S) TO INDICATE NAT	URE OF NOTICE, REPORT			
TYPE OF SUMISSION		<i>,</i>	TYPE OF ACTION			
Notice of Intent	Acidize	Deepen	Production (Start/Resume)	Water Shut-O	f	
					•	
X Subsequent Report	Alter Casing	Fracture Treat	Reclamation	Well Integrity		
			Recomplete	Other		
Final Abandonment Notice	Casing Repair	New Construction				
Final Abandonment Notice	Casing Repair	Plug and Abandon	X Temporarily Abandon	<u> </u>		
<ol> <li>Describe Proposed or Completed directionally or recomplete horizor or provide the Bond No. on file wit</li> </ol>	Change Plans Convert to Injection Operation (clearly state all pertine taily, give subsurface locations ar h BLM/BIA. Required subsequent ew interval, a Form 3160-4 shall b	Plug and Abandon Plug Back Int details, including estimated st ad measured and true vertical de t reports shall be filed within 30 c re filed once testing has been co	Temporarily Abandon Water Disposal tarting date of any proposed work and app epths of all pertinent markers and zones. Jays following completion of the involved of mpleted. Final Abandonment Notices sha	Attach the Bond under whi operations. If the operation	ch the work will be performed as results in a multiple	
<ol> <li>Describe Proposed or Completed directionally or recomplete horizor or provide the Bond No. on file wit completion or recompletion in a ne reclamation, have been completed 5-29-02- SITP slight blow Set down @ top of sliding 5-30-02- RU wireline; TIH wireline; Set CIBP @ 736 5-31-02- TIH w/ tubing op 500 psi for 30 minutes. La</li></ol>	Change Plans Convert to Injection Operation (clearly state all pertine thally, give subsurface locations ar h BLM/BIA. Required subsequent ewinterval, a Form 3160-4 shall b d, and the operator has determined ; casing valve was open. I seleeve @ 7327'. Tubing w/ strip gun. TOH, pump 4' cap w/ 35' cement (66) en ended to 6250'. Tester aid down tubing. Cap well;	Plug and Abandon Plug Back Int details, including estimated st and measured and true vertical de the reports shall be filed within 30 do the filed once testing has been co d that the site is ready for final in ND tree; NU BOP. Packet free @ 7015'; some mov down tubing. Work tubin 30'). Cap w/ 35' cement d casing to 500 psi. Disp ; top out w/ KCL. RD. Te	X Temporarily Abandon Water Disposal tarting date of any proposed work and app epths of all pertinent markers and zones tays following completion of the involved of mpleted. Final Abandonment Notices sha specition.) er would not release; no travel in rement to 7200'. Shut in ng & releasedpacker jarring dow (6342'), cap w/ 35'cement. Shut blaced hole w/ 2% KCL w/ 1 GP' st witnessed by Paul Shultz. Te	Attach the Bond under whi operations. If the operation all be filed only after all req n tool. RU wireline; n vn. TOH, sliding slee t in. T corrosion inhibitor	ch the work will be performed as results in a nultiple uirements, including run free point. eve opened RU . Tested & chart Velf is T/A.	
<ol> <li>Describe Proposed or Completed directionally or recomplete horizor or provide the Bond No. on file wit completion or recompletion in a ne reclamation, have been completed 5-29-02- SITP slight blow Set down @ top of sliding 5-30-02- RU wireline; TIH wireline; Set CIBP @ 736 5-31-02- TIH w/ tubing op 500 psi for 30 minutes. La</li></ol>	Change Plans Convert to Injection Operation (clearly state all pertine thally, give subsurface locations ar h BLM/BIA. Required subsequent ewinterval, a Form 3160-4 shall b d, and the operator has determined ; casing valve was open. I seleeve @ 7327'. Tubing w/ strip gun. TOH, pump 4' cap w/ 35' cement (66) en ended to 6250'. Tester aid down tubing. Cap well;	Plug and Abandon Plug Back Ind details, including estimated st and measured and true vertical de treports shall be filed within 30 c the filed once testing has been co d that the site is ready for final in ND tree; NU BOP. Packe free @ 7015'; some mov down tubing. Work tubin 30'). Cap w/ 35' cement d casing to 500 psi. Disp ; top out w/ KCL. RD. Te	Temporarily Abandon     Water Disposal     tarting date of any proposed work and app epths of all pertinent markers and zones.     days following completion of the involved o mpleted. Final Abandonment Notices sha specition.) er would not release; no travel in rement to 7200'. Shut in. ng & releasedpacker jarring dow (6342'), cap w/ 35'cement. Shut laced hole w/ 2% KCL w/ 1 GP st witnessed by Paul Shultz. Te	Attach the Bond under whi operations. If the operation all be filed only after all req n tool. RU wireline; n vn. TOH, sliding slee t in. T corrosion inhibitor	ch the work will be performed as results in a multiple uirements, including run free point. eve opened RU	
<ul> <li>13. Describe Proposed or Completed directionally or recomplete horizor or provide the Bond No. on file wit completion or recompletion in a nereclamation, have been completed</li> <li>5-29-02- SITP slight blow Set down @ top of sliding</li> <li>5-30-02- RU wireline; TIH wireline; Set CIBP @ 736</li> <li>5-31-02- TIH w/ tubing op</li> <li>500 psi for 30 minutes. Later and the second se</li></ul>	Change Plans Convert to Injection Operation (clearly state all pertine tially, give subsurface locations ar h BLM/BIA. Required subsequent winterval, a Form 3160-4 shall b d, and the operator has determined ; casing valve was open. I g sleeve @ 7327'. Tubing w/ strip gun. TOH, pump t4' cap w/ 35' cement (66) een ended to 6250'. Tested aid down tubing. Cap well;	Plug and Abandon Plug Back Int details, including estimated st and measured and true vertical de the reports shall be filed within 30 do the filed once testing has been co d that the site is ready for final in ND tree; NU BOP. Packet free @ 7015'; some mov down tubing. Work tubin 30'). Cap w/ 35' cement d casing to 500 psi. Disp ; top out w/ KCL. RD. Te	Temporarily Abandon     Water Disposal     tarting date of any proposed work and app epths of all pertinent markers and zones.     days following completion of the involved o mpleted. Final Abandonment Notices sha specition.) er would not release; no travel in rement to 7200'. Shut in. ng & releasedpacker jarring dow (6342'), cap w/ 35'cement. Shut laced hole w/ 2% KCL w/ 1 GP st witnessed by Paul Shultz. Te	Attach the Bond under whi operations. If the operation all be filed only after all req n tool. RU wireline; n vn. TOH, sliding slee t in. T corrosion inhibitor	ch the work will be performed as results in a rultiple uirements, including run free point. eve opened RU . Tested & chart /ell 19 T/A.	
<ol> <li>Describe Proposed or Completed directionally or recomplete horizor or provide the Bond No. on file wit completion or recompletion in a ne reclamation, have been completed 5-29-02- SITP slight blow Set down @ top of sliding 5-30-02- RU wireline; TIH wireline; Set CIBP @ 736 5-31-02- TIH w/ tubing op 500 psi for 30 minutes. La</li></ol>	Change Plans Convert to Injection Operation (clearly state all pertine tially, give subsurface locations ar h BLM/BIA. Required subsequent winterval, a Form 3160-4 shall b d, and the operator has determined ; casing valve was open. I g sleeve @ 7327'. Tubing w/ strip gun. TOH, pump t4' cap w/ 35' cement (66) een ended to 6250'. Tested aid down tubing. Cap well;	Plug and Abandon Plug Back Ind details, including estimated st and measured and true vertical de treports shall be filed within 30 c the filed once testing has been co d that the site is ready for final in ND tree; NU BOP. Packe free @ 7015'; some mov down tubing. Work tubin 30'). Cap w/ 35' cement d casing to 500 psi. Disp ; top out w/ KCL. RD. Te	Temporarily Abandon     Water Disposal     tarting date of any proposed work and app epths of all pertinent markers and zones.     days following completion of the involved o mpleted. Final Abandonment Notices sha specition.) er would not release; no travel in rement to 7200'. Shut in. ng & releasedpacker jarring dow (6342'), cap w/ 35'cement. Shut laced hole w/ 2% KCL w/ 1 GP st witnessed by Paul Shultz. Te	Attach the Bond under whi operations. If the operation all be filed only after all req n tool. RU wireline; n vn. TOH, sliding slee t in. T corrosion inhibitor	ch the work will be performed as results in a nultiple uirements, including run free point. eve opened RU . Tested & chart /elf is T/A.	
3. Describe Proposed or Completed directionally or recomplete horizor or provide the Bond No. on file wit completion or recompletion in a ne reclamation, have been completed 5-29-02- SITP slight blow Set down @ top of sliding 5-30-02- RU wireline; TIH wireline; Set CIBP @ 736 5-31-02- TIH w/ tubing op 500 psi for 30 minutes. La	Change Plans Convert to Injection Operation (clearly state all pertine tially, give subsurface locations ar h BLM/BIA. Required subsequent winterval, a Form 3160-4 shall b d, and the operator has determined ; casing valve was open. I g sleeve @ 7327'. Tubing w/ strip gun. TOH, pump t4' cap w/ 35' cement (66) een ended to 6250'. Tested aid down tubing. Cap well;	Plug and Abandon Plug Back Ind details, including estimated st and measured and true vertical de treports shall be filed within 30 c the filed once testing has been co d that the site is ready for final in ND tree; NU BOP. Packe free @ 7015'; some mov down tubing. Work tubin 30'). Cap w/ 35' cement d casing to 500 psi. Disp ; top out w/ KCL. RD. Te	Temporarily Abandon     Water Disposal     tarting date of any proposed work and app epths of all pertinent markers and zones.     days following completion of the involved o mpleted. Final Abandonment Notices sha specition.) er would not release; no travel in rement to 7200'. Shut in. ng & releasedpacker jarring dow (6342'), cap w/ 35'cement. Shut laced hole w/ 2% KCL w/ 1 GP st witnessed by Paul Shultz. Te	Attach the Bond under whi operations. If the operation all be filed only after all req n tool. RU wireline; n vn. TOH, sliding slee t in. T corrosion inhibitor	ch the work will be performed as results in a rultiple uirements, including run free point. eve opened RU . Tested & chart /ell 19 T/A.	
3. Describe Proposed or Completed directionally or recomplete horizor or provide the Bond No. on file wit completion or recompletion in a ne reclamation, have been completed 5-29-02- SITP slight blow Set down @ top of sliding 5-30-02- RU wireline; TIH wireline; Set CIBP @ 736 5-31-02- TIH w/ tubing op 500 psi for 30 minutes. La	Change Plans Convert to Injection Operation (clearly state all pertine tially, give subsurface locations ar h BLM/BIA. Required subsequent winterval, a Form 3160-4 shall b d, and the operator has determined ; casing valve was open. I g sleeve @ 7327'. Tubing w/ strip gun. TOH, pump t4' cap w/ 35' cement (66) een ended to 6250'. Tested aid down tubing. Cap well;	Plug and Abandon Plug Back Ind details, including estimated st and measured and true vertical de treports shall be filed within 30 c the filed once testing has been co d that the site is ready for final in ND tree; NU BOP. Packe free @ 7015'; some mov down tubing. Work tubin 30'). Cap w/ 35' cement d casing to 500 psi. Disp ; top out w/ KCL. RD. Te	Temporarily Abandon     Water Disposal     tarting date of any proposed work and app epths of all pertinent markers and zones.     days following completion of the involved o mpleted. Final Abandonment Notices sha specition.) er would not release; no travel in rement to 7200'. Shut in. ng & releasedpacker jarring dow (6342'), cap w/ 35'cement. Shut laced hole w/ 2% KCL w/ 1 GP st witnessed by Paul Shultz. Te	Attach the Bond under whi operations. If the operation all be filed only after all req n tool. RU wireline; n vn. TOH, sliding slee t in. T corrosion inhibitor	ch the work will be performed as results in a rultiple uirements, including run free point. eve opened RU . Tested & chart /ell 19 T/A.	
3. Describe Proposed or Completed directionally or recomplete horizor or provide the Bond No. on file wit completion or recompletion in a ne reclamation, have been completed 5-29-02- SITP slight blow Set down @ top of sliding 5-30-02- RU wireline; TIH wireline; Set CIBP @ 736 5-31-02- TIH w/ tubing op 500 psi for 30 minutes. La	Change Plans Convert to Injection Operation (clearly state all pertine tially, give subsurface locations ar h BLM/BIA. Required subsequent winterval, a Form 3160-4 shall b d, and the operator has determined ; casing valve was open. I g sleeve @ 7327'. Tubing w/ strip gun. TOH, pump t4' cap w/ 35' cement (66) een ended to 6250'. Tested aid down tubing. Cap well;	Plug and Abandon Plug Back Ind details, including estimated st and measured and true vertical de treports shall be filed within 30 c the filed once testing has been co d that the site is ready for final in ND tree; NU BOP. Packe free @ 7015'; some mov down tubing. Work tubin 30'). Cap w/ 35' cement d casing to 500 psi. Disp ; top out w/ KCL. RD. Te	Temporarily Abandon     Water Disposal     tarting date of any proposed work and app epths of all pertinent markers and zones.     days following completion of the involved o mpleted. Final Abandonment Notices sha specition.) er would not release; no travel in rement to 7200'. Shut in. ng & releasedpacker jarring dow (6342'), cap w/ 35'cement. Shut laced hole w/ 2% KCL w/ 1 GP st witnessed by Paul Shultz. Te	Attach the Bond under whi operations. If the operation all be filed only after all req n tool. RU wireline; n vn. TOH, sliding slee t in. T corrosion inhibitor	ch the work will be performed as results in a rultiple uirements, including run free point. eve opened RU . Tested & chart /ell 19 T/A.	
3. Describe Proposed or Completed directionally or recomplete horizor or provide the Bond No. on file wit completion or recompletion in a ne reclamation, have been completed 5-29-02- SITP slight blow Set down @ top of sliding 5-30-02- RU wireline; TIH wireline; Set CIBP @ 736 5-31-02- TIH w/ tubing op 500 psi for 30 minutes. La TTA Approved For	Change Plans Convert to Injection Operation (clearly state all pertine ntally, give subsurface locations ar h BLM/BIA. Required subsequent winterval, a Form 3160-4 shall b d, and the operator has determined ; casing valve was open. I sleeve @ 7327'. Tubing w/ strip gun. TOH, pump t4' cap w/ 35' cement (66) en ended to 6250'. Tested aid down tubing. Cap well; <u>12</u> <u>30</u> <u>30</u> <u>30</u>	Plug and Abandon Plug Back Ind details, including estimated st and measured and true vertical de treports shall be filed within 30 c the filed once testing has been co d that the site is ready for final in ND tree; NU BOP. Packe free @ 7015'; some mov down tubing. Work tubin 30'). Cap w/ 35' cement d casing to 500 psi. Disp ; top out w/ KCL. RD. Te	Temporarily Abandon     Water Disposal     tarting date of any proposed work and app epths of all pertinent markers and zones.     days following completion of the involved o mpleted. Final Abandonment Notices sha specition.) er would not release; no travel in rement to 7200'. Shut in. ng & releasedpacker jarring dow (6342'), cap w/ 35'cement. Shut laced hole w/ 2% KCL w/ 1 GP st witnessed by Paul Shultz. Te	Attach the Bond under whi operations. If the operation all be filed only after all req n tool. RU wireline; n vn. TOH, sliding slee t in. T corrosion inhibitor est chart attached. W	ch the work will be performed as results in a rultiple uirements, including run free point. eve opened RU Tisted & chart /ell 19 T/A.	
3. Describe Proposed or Completed directionally or recomplete horizor or provide the Bond No. on file wit completion or recompletion in a ne reclamation, have been completed 5-29-02- SITP slight blow Set down @ top of sliding 5-30-02- RU wireline; TIH wireline; Set CIBP @ 736 5-31-02- TIH w/ tubing op 500 psi for 30 minutes. La TTA Approved For Enders	Change Plans Convert to Injection Operation (clearly state all pertinentally, give subsurface locations are hBLM/BIA. Required subsequent winterval, a Form 3160-4 shall b d, and the operator has determined ; casing valve was open. I sleeve @ 7327'. Tubing w/ strip gun. TOH, pump 4' cap w/ 35' cement (66) ien ended to 6250'. Tester aid down tubing. Cap well; 39/03 is true and correct	Plug and Abandon Plug Back Ind details, including estimated st and measured and true vertical de treports shall be filed within 30 c the filed once testing has been co d that the site is ready for final in ND tree; NU BOP. Packe free @ 7015'; some mov down tubing. Work tubin 30'). Cap w/ 35' cement d casing to 500 psi. Disp ; top out w/ KCL. RD. Te	Temporarily Abandon     Water Disposal     tarting date of any proposed work and app     pepts of all pertinent markers and zones.     days following completion of the involved o     mpleted. Final Abandonment Notices sha     specition.)     er would not release; no travel in     rement to 7200'. Shut in.     ng & releasedpacker jarring dow     (6342'), cap w/ 35'cement. Shut     laced hole w/ 2% KCL w/ 1 GP     st witnessed by Paul Shultz. Te	Attach the Bond under whi operations. If the operation all be filed only after all req n tool. RU wireline; n vn. TOH, sliding slee t in. T corrosion inhibitor	ch the work will be performed as results in a multiple uirements, including run free point. eve opened RU Tested & chart /ell 19 T/A.	
<ul> <li>13. Describe Proposed or Completed directionally or recomplete horizor or provide the Bond No. on file wit completion or recompletion in a nereclamation, have been completed 5-29-02- SITP slight blow Set down @ top of sliding 5-30-02- RU wireline; TIH wireline; Set CIBP @ 736 5-31-02- TIH w/ tubing op 500 psi for 30 minutes. La TTA Approved For Ender 5-54</li> <li>TTA Approved For Ender 5-54</li> <li>I hereby certify that the foregoing Name (Printed/Type</li> </ul>	Change Plans Convert to Injection Operation (clearly state all pertinentally, give subsurface locations are hBLM/BIA. Required subsequent winterval, a Form 3160-4 shall b d, and the operator has determined ; casing valve was open. I sleeve @ 7327'. Tubing w/ strip gun. TOH, pump 4' cap w/ 35' cement (66) ien ended to 6250'. Tester aid down tubing. Cap well; 39/03 is true and correct	Plug and Abandon Plug Back Ind details, including estimated st and measured and true vertical de treports shall be filed within 30 c the filed once testing has been co d that the site is ready for final in ND tree; NU BOP. Packe free @ 7015'; some mov down tubing. Work tubin 30'). Cap w/ 35' cement d casing to 500 psi. Disp ; top out w/ KCL. RD. Te	Temporarily Abandon     Water Disposal     tarting date of any proposed work and app potts of all pertinent markers and zones.     Jays following completion of the involved o mpleted. Final Abandonment Notices sha specition.) er would not release; no travel in rement to 7200'. Shut in. ng & releasedpacker jarring dow (6342'), cap w/ 35'cement. Shut blaced hole w/ 2% KCL w/ 1 GP st witnessed by Paul Shultz. Te	Attach the Bond under whi operations. If the operation all be filed only after all req n tool. RU wireline; n vn. TOH, sliding sleet t in. T corrosion inhibitor est chart attached. W	ch the work will be performed as results in a rultiple uirements, including run free point. eve opened RU Tested & chart /ell 19 T/A.	
<ul> <li>3. Describe Proposed or Completed directionally or recomplete horizor or provide the Bond No. on file wit completion or recompletion in a nereclamation, have been completed 5-29-02- SITP slight blow Set down @ top of sliding 5-30-02- RU wireline; TIH wireline; Set CIBP @ 736 5-31-02- TIH w/ tubing op 500 psi for 30 minutes. La TTA Approved For Enclose 5-57</li> <li>I hereby certify that the foregoing Name (Printed/Type: Donna Clack)</li> </ul>	Change Plans Convert to Injection Operation (clearly state all pertinentally, give subsurface locations are hBLM/BIA. Required subsequent winterval, a Form 3160-4 shall b d, and the operator has determined ; casing valve was open. I sleeve @ 7327'. Tubing w/ strip gun. TOH, pump 4' cap w/ 35' cement (66) ien ended to 6250'. Tester aid down tubing. Cap well; 39/03 is true and correct	Plug and Abandon Plug Back Ind details, including estimated st and measured and true vertical de treports shall be filed within 30 c the filed once testing has been co d that the site is ready for final in ND tree; NU BOP. Packe free @ 7015'; some mov down tubing. Work tubin 30'). Cap w/ 35' cement d casing to 500 psi. Disp ; top out w/ KCL. RD. Te	Temporarily Abandon     Water Disposal     Water Disposal     tarting date of any proposed work and app epths of all pertinent markers and zones     days following completion of the involved of mpleted. Final Abandonment Notices sha specifion.) er would not release; no travel in rement to 7200'. Shut in.     ng & releasedpacker jarring dow (6342') cap w/ 35'cement. Shut laced hole w/ 2% KCL w/ 1 GP' st witnessed by Paul Shultz. Te	Attach the Bond under whi operations. If the operation all be filed only after all req n tool. RU wireline; n vn. TOH, sliding sleet t in. T corrosion inhibitor est chart attached. W	ch the work will be performed as results in a rultiple uirements, including run free point. eve opened RU Tested & chart /ell 19 T/A.	
3. Describe Proposed or Completed directionally or recomplete horizor or provide the Bond No. on file wit completion or recompletion in a ne reclamation, have been completed 5-29-02- SITP slight blow Set down @ top of sliding 5-30-02- RU wireline; TIH wireline; Set CIBP @ 736 5-31-02- TIH w/ tubing op 500 psi for 30 minutes. La TTA Approved For Ending 57	Change Plans Convert to Injection Operation (clearly state all pertinentally, give subsurface locations are hBLM/BIA. Required subsequent winterval, a Form 3160-4 shall b d, and the operator has determined ; casing valve was open. I sleeve @ 7327'. Tubing w/ strip gun. TOH, pump 4' cap w/ 35' cement (66) ien ended to 6250'. Tester aid down tubing. Cap well; <u>122</u> <u>304</u> 03 is true and correct	Plug and Abandon Plug Back Ind details, including estimated st and measured and true vertical de treports shall be filed within 30 c the filed once testing has been co d that the site is ready for final in ND tree; NU BOP. Packe free @ 7015'; some mov down tubing. Work tubin 30'). Cap w/ 35' cement d casing to 500 psi. Disp ; top out w/ KCL. RD. Te	Temporarily Abandon     Water Disposal     tarting date of any proposed work and app potts of all pertinent markers and zones.     Jays following completion of the involved o mpleted. Final Abandonment Notices sha specition.) er would not release; no travel in rement to 7200'. Shut in. ng & releasedpacker jarring dow (6342'), cap w/ 35'cement. Shut blaced hole w/ 2% KCL w/ 1 GP st witnessed by Paul Shultz. Te	Attach the Bond under whi operations. If the operation all be filed only after all req n tool. RU wireline; n vn. TOH, sliding sleet t in. T corrosion inhibitor est chart attached. W	co the work will be performed as results in a multiple uirements, including run free point. eve opened RU Tested & chart /ell 19 T/A.	
<ul> <li>13. Describe Proposed or Completed directionally or recomplete horizor or provide the Bond No. on file wit completion or recompletion in a nereclamation, have been completed 5-29-02- SITP slight blow Set down @ top of sliding 5-30-02- RU wireline; TIH wireline; Set CIBP @ 736 5-31-02- TIH w/ tubing op 500 psi for 30 minutes. La TTA Approved For Enclose 5-57</li> <li>I hereby certify that the foregoing Name (Printed/Type: Donna Clack)</li> </ul>	Change Plans Convert to Injection Operation (clearly state all pertinentially, give subsurface locations are h BLM/BIA. Required subsequentiation in the operator has determined and the operator has determined ; casing valve was open. If seve @ 7327'. Tubing in the operator has determined w/ strip gun. TOH, pump is true and correct d)	Plug and Abandon Plug Back Int details, including estimated st and measured and true vertical de treports shall be filed within 30 of the filed once testing has been co d that the site is ready for final in ND tree; NU BOP. Packe free @ 7015'; some mov down tubing. Work tubir 30'). Cap w/ 35' cement d casing to 500 psi. Disp ; top out w/ KCL. RD. Te	Temporarily Abandon     Water Disposal     tarting date of any proposed work and app epths of all pertinent markers and zones     tays following completion of the involved of mpleted. Final Abandonment Notices sha specifion.) er would not release; no travel in rement to 7200'. Shut in.     ng & releasedpacker jarring dow (6342') cap w/ 35'cement. Shut laced hole w/ 2% KCL w/ 1 GP' st witnessed by Paul Shultz. Te	Attach the Bond under whi operations. If the operation all be filed only after all req n tool. RU wireline; n vn. TOH, sliding sleet t in. T corrosion inhibitor est chart attached. W	ch the work will be performed as results in a rultiple uirements, including run free point. eve opened RU Tested & chart /ell 19 T/A.	
<ul> <li>13. Describe Proposed or Completed directionally or recomplete horizor or provide the Bond No. on file will completion or recompletion in a nereclamation, have been completed 5-29-02- SITP slight blow Set down @ top of sliding 5-30-02- RU wireline; TIH wireline; Set CIBP @ 736 5-31-02- TIH w/ tubing op 500 psi for 30 minutes. La TTA Approved For Emistry</li></ul>	Change Plans Convert to Injection Operation (clearly state all pertinentially, give subsurface locations are h BLM/BIA. Required subsequentiation in the operator has determined and the operator has determined ; casing valve was open. If seve @ 7327'. Tubing in the operator has determined w/ strip gun. TOH, pump is true and correct d)	Plug and Abandon Plug Back Int details, including estimated st Interports shall be filed within 30 c Interport with KCL. RD. Te Interports Statement of Comparison of the filed with KCL. RD. Te Interports Statement of Comparison of the filed with the statement of Comparison of Comparison of the filed with the statement of Comparison of Compariso	Temporarily Abandon     Water Disposal     Water Disposal     tarting date of any proposed work and app     poths of all pertinent markers and zones     days following completion of the involved o     mpleted. Final Abandonment Notices sha     specition.)     er would not release; no travel in     rement to 7200'. Shut in.     ng & releasedpacker jarring dow     (6342') cap w/ 35'cement. Shut     blaced hole w/ 2% KCL w/ 1 GP     st witnessed by Paul Shultz. Te	Attach the Bond under whi operations. If the operation all be filed only after all req n tool. RU wireline; n vn. TOH, sliding sleet t in. T corrosion inhibitor est chart attached. W	ch the work will be performed as results in a rultiple uirements, including run free point. eve opened RU Tested & chart /ell 19 T/A.	

