
Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department



OH CONCEDUATION DIVICION

Same Fe, New Mexico 87504-2082 Same Fe, New Mexico 87504-2082 Same Fe, New New Mexico 87504-2082 Same Fe, New New New Mexico 87504-2082 Same Fe, New	P.O. Box 1980, Hobbs, NM 88240		P.O. Box 2088			WELL API NO. 30-015-21769		
SUNDRY NOTICES AND REPORTS ON WELLS** ESTA OSPICE. (DO NOT USE THIS FORM FOR PROPOSALS TO ORILL OR TO DEEPEN OR PULG BACK TO A DIFFERENT RESERVOR. USE "APPLICATION FOR PERMIT" (PORM C-101) FOR SUCH PROPOSALS. 1. Type of Well: ONL ONL ONL ONL ONL ONL ONL ON		rtesis, NM 88210	Santa Fe, New Mexico			5. Indicate Type of Lease		
SUNDRY MOTICES AND REPORTS ON WELL'S TO BEERN OF PLUG BACK TO A DIFFERENT RESERVOR. USE "APPLICATION FOR PERMIT" 1. Type of Well: Comment Co		i., Aziec, NM 87410			•			
CONNOTUSE THIS FORM FOR PROCAUS TO DRILL OR TO DEEPEN OR PLUG SANK TO A DIFFERENT RESERVOR. USE APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS) 1. Type of Well: Will Will Will Will Will Will Will		CUNDRY MOTIC	EC AND DEDODTE	SAL SA/E		<i></i> ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
Cities present Joseph Delication of Delication of Delication of Operator ARCO OIL AND GAS COMPANY 2 Name of Operator ARCO OIL AND GAS COMPANY 3 21 3 Address of Operator BOX 1710, HOBBS, NEW MEXICO 88240 4 Well Location Unit Letter 1 : 1520 Feet From The SOUTH Line and 250 Feet From The EAST Line Socies 33 Township 175 Reage 28E NAMEM EDDY County 10. Elevation (Show whether DP, RKB, RT, GR, etc.) 3663.8 ° CR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANE COMMENCE DPILLING OPPS. PLUG AND ABANDON CHANGE PLUG AND ABANDON CHANGE PLUG AND ABANDON CHANGE PRILLING OPPS. PLUG AND ABANDON CHANGE PRILLING OPPS. PLUG AND ABANDON CHANGE SERULE 1103. 12 Dearbe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent detail, including estimated date of starting any proposed work) SEE RULE 1103. 13 Administrative Supervisor DATE 617/91 14 OT PRANSPORT. CLOSED WELL IN AND PRESSURED UP 7 JTS TBG. POH W/TBG and PKR. RIH w/CIBP AND RUNNING TOOL AND 195 JTS TBG. SDON. 6/12/91 RO. PICKED UP 6 JTS TBG AND ADDED TO TBG STRING OF 195 JTS. RIH w/TOTAL OF 201 JTS & CIBP. SET CIBP. POH w/I JT TBG. R/U KILL TRUCK. CIRCULATE WELL TO TRANSPORT. CLOSED WELL IN AND PRESSURED UP 7 D 5006. HELD FOR 15 MINS. NO LOSS IN PRESSURE. R/D KILL TRUCK. FOH w/TBG AND CIBP RUNNING TOOL. N/D BOP. N/U W/H. LEFT 1 JT TBG ON W/H PLANCE, RDCIL. CIBP SET @ 6170.07'. PRESSURE TEST CHART ATTACHED. TEST WITNESSED BY GARY WILLIAMS OF NMOCD. 1 Inches press for State Media. 1 James D. Cogburn TREPHOREN OF 392-1600	(DO NOT USE T	THIS FORM FOR PROF DIFFERENT RESERV	POSALS TO DRILL OR TO POIR. USE "APPLICATION	DEEPEN FOR PE	OR PLUG BACK TO A	7. Lease Name or	Unit Agreement Nam	: :
ARCO OIL AND GAS COMPANY 1 Address of Operator BOX 1710, HOBBS, NEW MEXICO 88240 4 Well Location Unit Lester I : 1520 Feet From The SOUTH Line and 250 Feet From The EAST Line Section 33 Township 17S Range 28E NAMPM EDDY County 10 Elevation (Show whether DF, RKB, RT, GR, etc.) 3663.8° GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON GHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASHING TEMPORARILY ABANDON GHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASHING TEMPORARILY ABANDON TO THER. TEMPORARILY ABANDON TO THE A	OE X	METT	ОТНЕВ			EMPIRE A	BO UNIT "G"	
S. Pool maces or Wildent SOUTH Line and 250 Feet From The Line Line and 250 Feet From The Line and 250 Feet	1		VΥ			1		
Unit Letter I : 1520 Feet From The SOUTH Line and 250 Feet From The EAST Line Socion 33 Township 175 Reage 28E NATM EDDY County 3663.8' GR 10. Elevation (Now whether DF, RKB, RT, GR, etc.) 10. Elevation (Now whether DF, RKB, RT, GR, etc.) 3663.8' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK	3. Address of Open	rator					/ildcat	
Unit Letter I : 1520 Feet From The SOUTH Line and 250 Feet From The EAST Line Socious 33 Township 17S Range 28E NAPM EDDY County 3663.8' GR 10. Elevation (Show whether DF, RKB, RT, GR, stc.) 3663.8' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT DOTHER: TEMPORARILY ABANDON TO THER: TEMPORARILY ABANDON TO THERE TEMPORARILY ABANDON TO THE SET WITH THE STAND CEMENT JOB OTHER: TEMPORARILY ABANDON TO THE SET WITH THE STAND CEMENT JOB OTHER: TEMPORARILY ABANDON TO THE SET WITH WORLD OF THE STAND CEMENT JOB OTHER STAND CEMENT JOB OTHER SET ON THE STAND CEMENT JOB OTHER SET ON THE STAND CEMENT JOB OTHER SET ON THE WORLD OF THE STAND OF		HOBBS, NEW MI	EXICO 88240			EMPIRE A	BO .	
10. Elevation (Show whether DP, RKB, RT, GR, etc.) 3663.8' GR 3663.8' GR 3663.8' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDON CHANGE PLANS CASING TEST AND CEMENT JOB OTHER: TEMPORARILLY ABANDON TO HADD WELL BORE FOR FIELD BLOW DOWN TO 6401'; PERFS: 6183-6218' 6/11/91 MIRU. DDPU. N/D W/H. N/U BOP. UNSEAT PKR. PICKED UP 7 JTS TBG. POH W/TBG and PKR. RIH W/CIBP AND RUNNING TOOL AND 195 JTS TBG. SDON. 6/12/91 RO. PICKED UP 6 JTS TBG AND ADDED TO TBG STRING OF 195 JTS. RIH W/TOTAL OF 201 JTS & CIBP. SET CIBP. POH W/I JT TBG. R/U KILL TRUCK. CIRCULATE WELL TO TRANSPORT. CLOSED WELL IN AND PRESSURED UP TO 5000#. HELD FOR 15 MINS. NO LOSS IN PRESSURE. R/D KILL TRUCK. POH W/TBG AND CIBP RUNNING TOOL. N/D BOP. N/U W/H. LEFT 1 JT TBG ON W/H FLANGE. RDCL. CIBP SET @ 6170.07'. PRESSURE TEST CHART ATTACHED. TEST WITNESSED BY GARY WILLIAMS OF NMOCD. TELEPHONE NO. 392-1600 TELEPHONE NO. 392-1600	1	I : 1520	Feet From The SO	UTH	Line and250	Feet From	The EAST	Line
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEMPORARILY ABANDON OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. TA & HOLD WELL BORE FOR FIELD BLOW DOWN TD 6401'; PERFS: 6183-6218' 6/11/91 MIRU. DDPU. N/D W/H. N/U BOP. UNSEAT PKR. PICKED UP 7 JTS TBG. POH w/TBG and PKR. RIH w/CIBP AND RUNNING TOOL AND 195 JTS TBG. SDON. 6/12/91 RO. PICKED UP 6 JTS TBG AND ADDED TO TBG STRING OF 195 JTS. RIH w/TOTAL OF 201 JTS & GIBP. SET CIBP. POH w/1 JT TBG. R/U KILL TRUCK. CIRCULATE WELL TO TRANSPORT. CLOSED WELL IN AND PRESSURED UP TO 500 W/H HELD FOR 15 MINS. NO LOSS IN PRESSURE. R/D KILL TRUCK. POH w/TBG AND CIBP RUNNING TOOL. N/D BOP. N/U W/H. LEFT 1 JT TBG ON W/H FLANCE. RDCL. CIBP SET @ 6170.07'. PRESSURE TEST CHART ATTACHED. TEST WITNESSEED BY GARY WILLIAMS OF NMOCD. (That speces for State Jipo) (The speces for State Jipo)	Section	33	104UMD	R	mile.	NMPM	DDY	County
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK					DF, RKB, RT, GR, etc.)			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK	11.	Check A	/////		Nature of Notice, R	eport, or Other	<i>Y////////////////////////////////////</i>	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB CHANGE Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including entimated date of starting any proposed wort). SEE RULE 1103. TA & HOLD WELL BORE FOR FIELD BLOW DOWN TD 6401'; PERFS: 6183-6218' 6/11/91 MIRU. DDPU. N/D W/H. N/U BOP. UNSEAT PKR. PICKED UP 7 JTS TBG. POH w/TBG and PKR. RIH w/CIBP AND RUNNING TOOL AND 195 JTS TBG. SDON. 6/12/91 RO. PICKED UP 6 JTS TBG AND ADDED TO TBG STRING OF 195 JTS. RIH w/TOTAL OF 201 JTS & CIBP. SET CIBP. POH w/1 JT TBG. R/U KILL TRUCK. CIRCULATE WELL TO TRANSPORT. CLOSED WELL IN AND PRESSURED UP TO 500#. HELD FOR 15 MINS. NO LOSS IN PRESSURE. R/D KILL TRUCK. POH w/TBG AND CIBP RUNNING TOOL. N/D BOP. N/U W/H. LEFT 1 JT TBG ON W/H FLANGE. RDCL. CIBP SET @ 6170.07'. PRESSURE TEST CHART ATTACHED. TEST WITNESSED BY GARY WILLIAMS OF NMOCD. Thereby certify that the information above is true and complide to the best of my knowledge and belief. TITLE Administrative Supervisor DATE 6/17/91 TITLE PRINT NAME James D. Cogburn TREPHONE NO. 392-1600	·					•		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB CHANGE Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including entimated date of starting any proposed wort). SEE RULE 1103. TA & HOLD WELL BORE FOR FIELD BLOW DOWN TD 6401'; PERFS: 6183-6218' 6/11/91 MIRU. DDPU. N/D W/H. N/U BOP. UNSEAT PKR. PICKED UP 7 JTS TBG. POH w/TBG and PKR. RIH w/CIBP AND RUNNING TOOL AND 195 JTS TBG. SDON. 6/12/91 RO. PICKED UP 6 JTS TBG AND ADDED TO TBG STRING OF 195 JTS. RIH w/TOTAL OF 201 JTS & CIBP. SET CIBP. POH w/1 JT TBG. R/U KILL TRUCK. CIRCULATE WELL TO TRANSPORT. CLOSED WELL IN AND PRESSURED UP TO 500#. HELD FOR 15 MINS. NO LOSS IN PRESSURE. R/D KILL TRUCK. POH w/TBG AND CIBP RUNNING TOOL. N/D BOP. N/U W/H. LEFT 1 JT TBG ON W/H FLANGE. RDCL. CIBP SET @ 6170.07'. PRESSURE TEST CHART ATTACHED. TEST WITNESSED BY GARY WILLIAMS OF NMOCD. Thereby certify that the information above is true and complide to the best of my knowledge and belief. TITLE Administrative Supervisor DATE 6/17/91 TITLE PRINT NAME James D. Cogburn TREPHONE NO. 392-1600	PERFORM REMED	DIAL WORK	PLUG AND ABANDON		REMEDIAL WORK		ALTERING CASING	,
CASING TEST AND CEMENT JOB OTHER: TEMPORARILY ABANDON TO THAN POPORARILY ABANDON TO THE PROVIDE A TEMPORARILY ABANDON TO THE TEMPORARILY ABANDON TO THAN POPORARILY ABANDON TO THE TEMPORARILY ABANDON TO THE TEMPORARILY ABANDON TO THE TEMPORARILY ABANDON TO THE TEMPORARILY A								_
OTHER: TEMPORARILY ABANDON 12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. TA & HOLD WELL BORE FOR FIELD BLOW DOWN TD 6401'; PERFS: 6183-6218' 6/11/91 MIRU. DDPU. N/D W/H. N/U BOP. UNSEAT PKR. PICKED UP 7 JTS TBG. POH w/TBG and PKR. RIH w/CIBP AND RUNNING TOOL AND 195 JTS TBG. SDON. 6/12/91 RO. PICKED UP 6 JTS TBG AND ADDED TO TBG STRING OF 195 JTS. RIH w/TOTAL OF 201 JTS & CIBP. SET CIBP. POH w/1 JT TBG. R/U KILL TRUCK. CIRCULATE WELL TO TRANSPORT. CLOSED WELL IN AND PRESSURED UP TO 500#. HELD FOR 15 MINS. NO LOSS IN PRESSURE. R/D KILL TRUCK. POH w/TBG AND CIBP RUNNING TOOL. N/D BOP. N/U W/H. LEFT 1 JT TBG ON W/H FLANGE. RDCL. CIBP SET @ 6170.07'. PRESSURE TEST CHART ATTACHED. TEST WITNESSED BY GARY WILLIAMS OF NMOCD. Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE James D. Cogburn TRLEPHONE NO. 392-1600								O.M.E.M.
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including extinated date of starting any proposed work) SEE RULE 1103. TA & HOLD WELL BORE FOR FIELD BLOW DOWN TD 6401'; PERFS: 6183-6218' 6/11/91 MIRU. DDPU. N/D W/H. N/U BOP. UNSEAT PKR. PICKED UP 7 JTS TBG. POH w/TBG and PKR. RIH w/CIBP AND RUNNING TOOL AND 195 JTS TBG. SDON. 6/12/91 RO. PICKED UP 6 JTS TBG AND ADDED TO TBG STRING OF 195 JTS. RIH w/TOTAL OF 201 JTS & CIBP. SET CIBP. POH w/1 JT TBG. R/U KILL TRUCK. CIRCULATE WELL TO TRANSPORT. CLOSED WELL IN AND PRESSURED UP TO 500#. HELD FOR 15 MINS. NO LOSS IN PRESSURE. R/D KILL TRUCK. POH w/TBG AND CIBP RUNNING TOOL. N/D BOP. N/U W/H. LEFT 1 JT TBG ON W/H FLANCE. RDCL. CIBP SET @ 6170.07'. PRESSURE TEST CHART ATTACHED. TEST WITNESSED BY GARY WILLIAMS OF NMOCD. 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE James D. Cogburn TRLEPHONE NO. 392-1600 (This space for State] James D. Cogburn							N	ſΧ
TA & HOLD WELL BORE FOR FIELD BLOW DOWN TD 6401'; PERFS: 6183-6218' 6/11/91 MIRU. DDPU. N/D W/H. N/U BOP. UNSEAT PKR. PICKED UP 7 JTS TBG. POH w/TBG and PKR. RIH w/CIBP AND RUNNING TOOL AND 195 JTS TBG. SDON. 6/12/91 RO. PICKED UP 6 JTS TBG AND ADDED TO TBG STRING OF 195 JTS. RIH w/TOTAL OF 201 JTS & CIBP. SET CIBP. POH w/1 JT TBG. R/U KILL TRUCK. CIRCULATE WELL TO TRANSPORT. CLOSED WELL IN AND PRESSURED UP TO 500#. HELD FOR 15 MINS. NO LOSS IN PRESSURE. R/D KILL TRUCK. POH w/TBG AND CIBP RUNNING TOOL. N/D BOP. N/U w/H. LEFT 1 JT TBG ON W/H FLANGE. RDCL. CIBP SET @ 6170.07'. PRESSURE TEST CHART ATTACHED. TEST WITNESSED BY GARY WILLIAMS OF NMOCD. 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. SHONATURE JAMES D. Cogburn TRIEDHENE NO. 392-1600 (This spaces for State Libe)		1 . 6 . 1 . 1 6			O 111C) 1			
TD 6401'; PERFS: 6183-6218' 6/11/91 MIRU. DDPU. N/D W/H. N/U BOP. UNSEAT PKR. PICKED UP 7 JTS TBG. POH w/TBG and PKR. RIH w/CIBP AND RUNNING TOOL AND 195 JTS TBG. SDON. 6/12/91 RO. PICKED UP 6 JTS TBG AND ADDED TO TBG STRING OF 195 JTS. RIH w/TOTAL OF 201 JTS & CIBP. SET CIBP. POH w/1 JT TBG. R/U KILL TRUCK. CIRCULATE WELL TO TRANSPORT. CLOSED WELL IN AND PRESSURED UP TO 500#. HELD FOR 15 MINS. NO LOSS IN PRESSURE. R/D KILL TRUCK. POH w/TBG AND CIBP RUNNING TOOL. N/D BOP. N/U W/H. LEFT 1 JT TBG ON W/H FLANGE. RDCL. CIBP SET @ 6170.07'. PRESSURE TEST CHART ATTACHED. TEST WITNESSED BY GARY WILLIAMS OF NMOCD. 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. STONATURE MAMMINISTRATIVE Supervisor DATE 6/17/91 THUR Administrative Supervisor DATE 6/17/91 THUR Administrative Supervisor DATE 6/17/91			us (Clearry state all pertinent)	oeiaus, a)	ra give pertinent dates, inclu	ding estimated date of	starting any proposed	
6/11/91 MIRU. DDPU. N/D W/H. N/U BOP. UNSEAT PKR. PICKED UP 7 JTS TBG. POH w/TBG and PKR. RIH w/CIBP AND RUNNING TOOL AND 195 JTS TBG. SDON. 6/12/91 RO. PICKED UP 6 JTS TBG AND ADDED TO TBG STRING OF 195 JTS. RIH w/TOTAL OF 201 JTS & CIBP. SET CIBP. POH w/1 JT TBG. R/U KILL TRUCK. CIRCULATE WELL TO TRANSPORT. CLOSED WELL IN AND PRESSURED UP TO 500#. HELD FOR 15 MINS. NO LOSS IN PRESSURE. R/D KILL TRUCK. POH w/TBG AND CIBP RUNNING TOOL. N/D BOP. N/U W/H. LEFT 1 JT TBG ON W/H FLANGE. RDCL. CIBP SET @ 6170.07'. PRESSURE TEST CHART ATTACHED. TEST WITNESSED BY GARY WILLIAMS OF NMOCD. Thereby certify that the information above is true and complete to the best of my knowledge and belief. TITLE Administrative Supervisor DATE 6/17/91 TYPECR FEINT NAME James D. Cogburn TELEPHONE NO. 392-1600	TA & HOLD	WELL BORE FO	R FIELD BLOW DOW	N				
and PKR. RIH w/CIBP AND RUNNING TOOL AND 195 JTS TBG. SDON. 6/12/91 RO. PICKED UP 6 JTS TBG AND ADDED TO TBG STRING OF 195 JTS. RIH w/TOTAL OF 201 JTS & CIBP. SET CIBP. POH w/1 JT TBG. R/U KILL TRUCK. CIRCULATE WELL TO TRANSPORT. CLOSED WELL IN AND PRESSURED UP TO 500#. HELD FOR 15 MINS. NO LOSS IN PRESSURE. R/D KILL TRUCK. POH w/TBG AND CIBP RUNNING TOOL. N/D BOP. N/U W/H. LEFT 1 JT TBG ON W/H FLANGE. RDCL. CIBP SET @ 6170.07'. PRESSURE TEST CHART ATTACHED. TEST WITNESSED BY GARY WILLIAMS OF NMOCD. The Administrative Supervisor DATE 6/17/91 TYPEOR PRINT NAME James D. Cogburn TELEPHONE NO. 392-1600	TD 6401';	PERFS: 6183-	6218 '					
201 JTS & CIBP. SET CIBP. POH w/1 JT TBG. R/U KILL TRUCK. CIRCULATE WELL TO TRANSPORT. CLOSED WELL IN AND PRESSURED UP TO 500#. HELD FOR 15 MINS. NO LOSS IN PRESSURE. R/D KILL TRUCK. POH w/TBG AND CIBP RUNNING TOOL. N/D BOP. N/U W/H. LEFT 1 JT TBG ON W/H FLANGE. RDCL. CIBP SET @ 6170.07'. PRESSURE TEST CHART ATTACHED. TEST WITNESSED BY GARY WILLIAMS OF NMOCD. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SHONATURE James D. Cogburn THIE Administrative Supervisor DATE 6/17/91 TYPEOR PRINT NAME James D. Cogburn TELEPHONE NO. 392-1600	6/11/91							H w/TBG
TYPE OR FRINT NAME James D. Cogburn TELEPHONE NO. 392-1600 (This space for State Lie)	6/12/91	201 JTS & CI TO TRANSPORT NO LOSS IN P BOP. N/U W/	BP. SET CIBP. . CLOSED WELL I RESSURE. R/D KI H. LEFT 1 JT TB	POH w N AND LL TR G ON	/1 JT TBG. R/U PRESSURED UP TO UCK. POH w/TBG W/H FLANGE. RDO	KILL TRUCK. O 500#. HEI AND CIBP RU CL. CIBP SE	CIRCULATE D FOR 15 MINING TOOL. T @ 6170.07	WELL NS. N/D
TYPE OR FRINT NAME James D. Cogburn TELEPHONE NO. 392-1600 (This space for State Lie)	_							
TYPE OR PRINT NAME James D. Cogburn TELEPHONE NO. 392-1600 (This space for State Lies)	I hereby certify that th	e information above is true as				o Cunomita-	. 6/17/	Ω1
(This space for State Liee)	SIGNATURE	and y		тп	Administrative	e supervisor	DATE	
	TYPEOR PRINT NAME	James D. C	ogburn				TELEPHONE NO. 3	92-1600
		il falling			RED R	Q	DATE U/	21/91

This Approval of Temporary Abandonment Expires

CONDITIONS OF AFFROVAL, IF ANY:

RECEIVED C. Or.