

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPlicate
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

LC-068677

IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐ Plug & Abandon		8. FARM OR LEASE NAME Hinkle Federal	
2. NAME OF OPERATOR McClellan Oil Corporation 505-622-3200		9. WELL NO. #4	
3. ADDRESS OF OPERATOR P.O. Drawer 730 Roswell, NM 88202-0730		10. FIELD AND POOL, OR WILDCAT High Nitro Premier	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See space 17 below.) At surface H - 1980' FNL & 330' FEL		11. SEC., T., R., W., OR BLK. AND SURVEY OR ARMA Sec 9-T16S-R29E	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, OR, etc.) 3704' GR	12. COUNTY OR PARISH Eddy	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☒	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANE ☐	(Other) ☐	(Other) ☐
(Other) P & A		(NOTE: Report results of multiple completion on Well Completion or Reconpletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

8 5/8 csg 362' Circulated Perfs - open hole - 2356'-2358'
7" csg 673' to 1669' Salt - Top 340'
4 1/2 csg 2356', 7" hole 50 sx - Bottom 752'
2 3/8 tbq EUE

1. Set CIBP at 2300' & 35' cmt on top.
2. Circulate hole w/heavy gel H₂O.
3. Cut off csg at 1900'.
4. 1st plug 1950' to 1850' 25 sx Tag
2nd plug 1600' to 700' 25 sx
3rd plug 390' to 290' 30 sx Tag
4th plug 60' to Surface 20sx

Clean location & install dry hole marker.

18. I hereby certify that the foregoing is true and correct

SIGNED Mark Lee

TITLE Drilling Comp. Eng.

DATE 5-24-91

(This space for Federal or State office use)

APPROVED BY Mark Lee

TITLE Drilling Comp. Eng.

DATE 6/12/91

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side