

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II

P.O. Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-015-22487
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E-7842
7. Lease Name or Unit Agreement Name Empire Abo Unit "E"
8. Well No. 361
9. Pool name or Wildcat Empire Abo

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator ARCO Permian	
3. Address of Operator P.O. Box 1089 Eunice, NM 88231	
4. Well Location Unit Letter A : 620 Feet From The N Line and 1200 Feet From The E Line Section 34 Township 17S Range 28E NMPM Eddy County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3671.6' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD: 6294' PBD: 6274' PERFS: 6020-6030'

* 255X Min. Plug. * Bring gel between all cement Plugs.

This well has parted csg @ 3475'.

Unsuccessful recompletion attempts have been made.

A RBP was set @ 2861' w/sand on top.

Proposed to sand and pull TBP

RIH w/tbg to 3570 & pmp cmt to squeeze wellbore.

Set cmt plugs as required to abandon well from 3570' uphole.

* CROP set @ 5920' w/35' cement or 255X cement Plug 5920'-5820' TAG

* 100' cement Plug inside + outside 5 1/2" csg. 3475'-3375' TAG

* 100' cement Plug inside + outside 5 1/2" csg. 2180'-2080'

* 100' cement Plug inside + outside 5 1/2" csg. 1200'-1100'

* 100' cement Plug inside + outside 5 1/2" csg. 800'-700' TAG * 30' cement Plug inside + outside 5 1/2" csg. 30' surface.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kellie D. Murrish TITLE Administrative Assistant DATE 08/23/99

TYPE OR PRINT NAME Kellie D. Murrish TELEPHONE NO. 505-394-1649

(This space for State Use)

APPROVED BY Miss S. Stepien TITLE Field Rep. II DATE 8/30/99

CONDITIONS OF APPROVAL, IF ANY:

* Notify N M O.C.D. to witness Plugging Operations.

