Subnit 3 copies to Appropriate District Office		C19 F	Form C-103 Revised 1-1-80	ψ
	State of New Mexico Energy, Minerals and Natural Resources Department			
P.O. 30x 1980, Hobbs NM 88240 DIST RICT II OIL CONSERVATI	ON DIVISION	WELL API NO. 5. Indicate Type of Lease	30-015-22893	
P.O. Drawer DD, Artesia NM 88210 P.O. Box 2	rtesia NM 88210 P.O. Box 2088		FEE	
DISTRICT III Santa Fe, New Mexico 8	37504-2088	State X 6. State Oil & Gas Lease		
1000 Rio Brazos Rd., Aztec NM 87410			B-1111	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR T DIFFERENT RESERVOIR. USE " APPLICATION F (FORM C-101) FOR SUCH PROPOSALS.)	O DEEPER OR PLUG BACK TO C	7. Lease Name or Unit Ag		
1. Type of Well: OIL GAS WELL WELL OTHER	RECEIVED OCD - ARTESIA	LUCAS STOR	E KT STATE COM	
2. Name of Operator Yates Petroleum Corporation		8. Well No.	1	
3. Ad tress of Operator 105 South 4th., Artesia, NM 88	210	9. Pool Name or Wildcat UNDESIC	SNATED ABO	
4. Well Location Unit Letter G : 1980 Feet From The NORTH	Line and 1980 Fee	t From The	EAST Line	
Seption 22 Township T17S Range R28E	NMPM	EDDY	COUNTY	
10. Elevation (Show whether DF, RKB 3592'				
11. Check Appropriate Box to Indicate Nature of N	Notice, Report, or Other Data			
NOTICE OF INTENTION TO:	SUBSEQUENT R	EPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON		ALTERING CASING		
TEMPORARILY ABANDON CHANGE PLANS	COMMENCE DRILLING OPNS.	PLUG AND ABANDON	MENT	
отнек T/A for future use as SWD	OTHER	and a stand of the stand of t	yana mara sayaya baranga sayaya baranga sayaya	

12. Describe Proposed or Completed Operations (Clearly state all pertient details, and give pertinenet dates, including estimated date of starting any proposed work) SEE RULE 1103.

Yates Petroleum Corporation respectfully requests permission to change this well from a SWD back to a producing well. We also request to temporarily abandon for future use as a SWD as follows:

MIRU WSU - Install BOP & other safety equipment as needed. POH w/ tubing & packer. TIH to see if A RH RBP is set @ 6704'. POH, lay down tubing. RU wireline to run 5-1/2" CIBP; set CIBP @ 6610', dump 35' of cement on top of CIBP. Load casing w/ 2% KCL water & NU wellhead. Notify the OCD 24 hrs in advance so they can witness pressure test. Will pressure test casing to 900 psi for 30 minutes using a pump w/ a chart recorder.

Thereby certify that the information above a true and complete to the best of my knowledge and be	elief.		A 1.64	
SIGNATURE ACTIVAL LACK	TITLE	Operations Techician	DATE	3/19/02
TYPE CR PRINT NAME DONNA CLACK.	······	- A A	TELEPHONE NO.	505-748-1471
(This space for State Use)	A			~~~
APPRO /ED BY	8110	LO Ser BATE M	ND 967	UUZ
CONDITIONS OF APPROVAL, IF ANY		M		