- 9. Well Site Layout: <u>(See Drilling Plat)</u>
- 10. Plans for Restoration of the Surface: If well is plugged, all pits will be closed, anchors cut off below ground level, marker set and surface soil bladed back across location. Caliche is close to surface and to rip the location would probably leave it in good condition. Save ranch road as is.
- 11. Other Information: Location area has native grass and mosquite. Light top soil in places.
- 12. Lessee's or Operator's Representative:

MorOilCo, Inc.
William N. Morgan
P.O. Drawer I
Artesia, New Mexico 88210
Business Phone:748-2194

Home Phone: _____748-2325

13. Certification:

I hereby certify that I, or persons under my direct supervision, have inspected the proposed drillsite and access route: that I am familiar with the conditions which presently exist: that the statements made in this plan are, to the best of my knowledge, true and correct: and, that the work associated with the operations proposed herein will be performed by <u>MorOilCo, Inc.</u> and its contractors and sub-contractors in convormity with this plan and the terms and conditions under which it is approved.

5-2-80

Date

William n

Company Representative /

President

Title