

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

LG-4079

7. Lease Name or Unit Agreement Name

Cal-Mon St

8. Well No.

1

9. Pool name or Wildcat

High Lonesome *ON*

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

JAN 05 '89

2. Name of Operator

McClellan Oil Corporation

O. C. D.

3. Address of Operator

P.O. Drawer 730, Roswell, NM 88202

ARTESIA, OFFICE

4. Well Location

Unit Letter D : 990 Feet From The North Line and 421 Feet From The West Line

Section 19 Township 16S Range 29E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3850 G.L.

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to plug and abandon:

1. Set 25 sx cement plug inside 5 1/2" casing across perfs (1629-1643) *Tag*
2. Free point & shoot off casing, estimated 1000 feet.
3. Set 25 sx cement plug 50 feet "in and out" of the 5 1/2" casing stub. *Tag*
4. Set 25 sx cement plug from 195' to 295' in and out of the 8 5/8" shoe. *Tag*
5. Set 10 sx plug wt surface. Install dry hole marker.

Clean and level location.

mud between plugs

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Paul Ragsdale

TITLE

Operations Manager

DATE 01/04/89

TYPE OR PRINT NAME

TELEPHONE NO.

(This space for State Use) * As noted above

APPROVED BY

Johnny Robinson

TITLE

OIL AND GAS INSPECTOR

DATE

JAN 26 1989

CONDITIONS OF APPROVAL, IF ANY:

Plugging