

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO.  
30-015-31220

Indicate Type of Lease  
STATE ☐ FEE ☒

State Oil & Gas Lease No.

Lease Name or Unit Agreement Name  
Logan Draw 19 Federal Com

Well No.  
1

Pool name or Wildcat  
Logan Draw; Morrow (Gas)

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

Type of Well:  
OIL WELL ☐ GAS WELL ☐ OTHER P&A'd ☐

Name of Operator  
Nearburg Producing Company

Address of Operator  
3300 N A St., Bldg 2, Suite 120, Midland, TX 79705

Well Location  
Unit Letter P : 810 Feet From The South Line and 740 Feet From The East Line  
Section 19 Township 17S Range 27E NMPM Eddy County

Elevation (Show whether DF, RKB, RT, GR, etc.)  
3341' GR

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ANBANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Nearburg Producing Company requests to plug and abandon the above referenced well.

- 1.) Set CIBP @ 7500'. Cap w/35' cmt or 25 sx plug.
- 2.) Load hole w/ mud.
- 3.) Cut casing @ 6500', pull casing.
- 4.) Set 35 sx 100' plug 50' in and 50' out of stub. WOC tag.
- 5.) Set 50 sx plug from 6105' to 5996'. (Top of Wolfcamp 6115') 5780' to 5680'
- 6.) Set 50 sx plug from 4800' to 4650'. (Top Abo 4750') 4680' to 4580'
- 7.) Set 50 sx plug from 2700' to 2551'. (Top Glorieta 2650') 2630' to 2530'
- 8.) Set 50 sx plug from 1585' to 1416'. (8-5/8" stub @ 1534') 1499'
- 9.) Set 30' suface plug.
- 10.) Install dry hole marker.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kim Stewart TITLE Regulatory Analyst DATE 07-12-01

TYPE OR PRINT NAME Kim Stewart TELEPHONE NO. 915/686-8235

(This space for State Use)

APPROVED BY [Signature] TITLE Field Rep ID DATE 15 August 2001

CONDITIONS OF APPROVAL, IF ANY: