Submit 3 Copies to Appropriate District Office

State of New Mexico E::وربيع, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT

<u>DISTRICT |</u> P.O. Box 1980, Hobbs, NM 88240

DISTRICT II P.O. Drawer DD, Artesia, NM 88210 OIL CONSERVATION DIVISION

2040 Pacheco & 500 Santa Fe, NMA 87505

10

WELL API NO. 30-015-31552

sindicate Type of Lease

STATE

FFF

			74.0	8 70 223	1.75 g		SIVIER	
<u>DISTRICT III</u> 1000 Rio Brazos Rd., Aztec, NM 87410		To Och Edito		7 수 ((2) (2) (2)	₅State Oil & Gas Leas	e No.		
SUN			1.0					
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"						7Lease Name or Unit Agreement Name		
DIFFE	AID 24P State							
(FORM C-101) FOR SUCH PROPOSALS.)								
1Type of Well:	GAS						-	
METT X	GAS WELL		OTHER					
2Name of Operator						₃Well No.		
SDX Resources, Inc.						23		
3Address of Operator	₃Pool name or Wildcat							
PO Box 5061, Midland	d, TX 79704	4				Empire, Yeso		
4Well Location								
Unit Letter K	1860	Feet From The	South	Line and	1650	Feet From The	West	Line
Section	24	Township	178	Range	28E	NMPM	Eddy	County
₁₀Elevation (Show whether DF, RKB, RT, GR, etc.							9.1	
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data								
NOTICE OF INTENTION TO: SUBS						SEQUENT REPORT OF:		

REMEDIAL WORK

COMMENCE DRILLING OPNS.

CASING TEST AND CEMENT JOB

OTHER: Re-complete

OTHER: OTHER:

12Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed

PLUG AND ABANDON

CHANGE PLANS

MIRU & TOH w/rods & pump. NU BOP. TOH w/2-7/8" tbg. Set CIBP @ 3730'.

Circ hole clean w/2% KCL, test csg, BP & BOP to 1000#. TOH.

3117, 34, 42, 63, 86, 97 (35 holes).

PERFORM REMEDIAL WORK

TEMPORARILY ABANDON

PULL OR ALTER CASING

work) SEE RULE 1103.

TIH w/PPI tool w/14' spacing & spot acid across all perfs. Break down perfs in 23 settings w/1/2 bbl of acid per setting. Pull tool to appx 2530', fish valves, rev annulus clean & set tool. Acidize all perfs w/remaining acid @ 3-4 bpm w/50 balls. Total acid including spot, PPI & ball out = 4500 gal 15% NEFE.

Flow back acid & swab test zone.

Frac well w/60000 gal Viking 25 frac w/95000# 16/30 & 35000# 12/20 brady sd pumped @ 45 bpm: 1-5 ppg.

Clean out well w/2% KCL to PBTD & put well on pump.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.							
SIGNATURE Bennie (Ituater	тітье Regulatory Tech	DATE 08-19-02					
TYPE OR PRINT NAME BONNIE Atwater		TELEPHONE NO. 915/685-1761					

TITLE

(This space for State Use)

APPROVED BY

Original Signed by Tim W. Gum District II Supervisor

ALTERING CASING

PLUG AND ANBANDONMENT

DATE

2 6 2002