

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
B-7597

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Kewanee Oil Company	8. Farm or Lease Name State "C"
3. Address of Operator P. O. Box 3786, Odessa, Texas 79760	9. Well No. 1
4. Location of Well UNIT LETTER H, 1980 FEET FROM THE North LINE AND 660 FEET FROM THE East LINE, SECTION 2 TOWNSHIP 17S RANGE 29E NMPM.	10. Field and Pool, or Wildcat Square Lake G-SA
15. Elevation (Show whether DF, RT, GR, etc.) 3662' GR	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to pull 4-1/2" casing and plug and abandon.

Propose to spot cement plug from 2400' to 2640' to cover perforations at 2478-86' and 2612-30'. Shoot 4-1/2" casing at 2100'. Fill hole with mud-laden fluid, spot cement plug from 295' to 395', 50' inside surface casing and 50' below surface casing seat, and spot 10' cement plug at surface. Weld on permanent marker at wellhead.

Propose to commence work on or about 4-28-69.

RECEIVED

APR 22 1969

O. C. C.
ARTERIA, OFFICE

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Eric C. Newman TITLE Division Engineer DATE 4-21-69

APPROVED BY W. A. Grussett TITLE OIL AND GAS INSPECTOR DATE APR 25 1969

CONDITIONS OF APPROVAL, IF ANY: spot a 25 sack plug at top of Queen at 1920' or at 4 1/2" cas. stub if it comes above 1920' + a 25 sack plug at base of salt @ 925'