

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

811 South First, Artesia, NM 87210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-10:
Revised March 25, 1991

WELL API NO.
30-015-2892

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
B11662

7. Lease Name or Unit Agreement Name:
Cave Pool Unit

8. Well No.
3

9. Pool name or Wildcat
Greyburg, Jackson, SA, QN

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Marks and Garner Production Co. Ltd. /

3. Address of Operator

P.O. Box 70 Lovington NM 88260

4. Well Location

Unit Letter A : 985 feet from the North line and 987 feet from the East line

Section 04

Township 17S Range 29E

NMPM

County Eddy

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

3590 GR

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐


OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Go in hole with 2" tubing and set CIBP @ 2354'. Spot 10 sxs cement plug on top of CIBP. Circulate hole with 10# brine and 25 sxs of salt gel. Come out and wait 24hr. Go in and tag plug. come out and shot 4 1/2" casing @ 1750'. Come out of hole with casing. Go in and spot 50' cement plug in and out. Come out and wait 24hr. Go in and tag plug. Come up and spot 100' cement plug @ 890'. Come out and wait 24hr. Go in and tag plug come up to 890' and spot 100' cement - 290-390 - TAG plug. Come up and spot 20 sxs plug @ surface and set dry hole marker.

Perf. & squeeze cmt outside
8' 7 1/2'

Notify OCD 24 hrs. prior to any work done



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE _____ TITLE Agent DATE 12-17-01

Type or print name Devin Garner

(This space for State use)

Telephone No. (505) 396-5326

APPROVED BY _____ TITLE _____ DATE 1-2-02

Conditions of approval, if any: