Set C.I.B.P. & 3 sacks at 2284 & shot pipe at 1765. Coul Squeezed 25 sacks & tagged at 1387. Shot pipe at 900 & p 35 sacks. Tagged plug at 630. Set 35 sacks at 250 & tagg pea gravel & 10 sacks cotton seed hulls & 15 sacks cemen Circulated to top & set marker. Hole was loaded with mud laden fluid. Cement was Portlan P+A 5-26-76	ulled out & set ed at 620. Ran 500# t. Tagged at 120.
Squeezed 25 sacks & tagged at 1387. Shot pipe at 900 & p 35 sacks. Tagged plug at 630. Set 35 sacks at 250 & tagg pea gravel & 10 sacks cotton seed hulls & 15 sacks cemen Circulated to top & set marker. Hole was loaded with mud laden fluid. Cement was Portlan P+1 5-26-76	ulled out & set ed at 620. Ran 500# t. Tagged at 120.
Squeezed 25 sacks & tagged at 1387. Shot pipe at 900 & p 35 sacks. Tagged plug at 630. Set 35 sacks at 250 & tagg pea gravel & 10 sacks cotton seed hulls & 15 sacks cemen Circulated to top & set marker. Hole was loaded with mud laden fluid. Cement was Portlan	ulled out & set ed at 620. Ran 500# t. Tagged at 120.
Squeezed 25 sacks & tagged at 1387. Shot pipe at 900 & p 35 sacks. Tagged plug at 630. Set 35 sacks at 250 & tagg pea gravel & 10 sacks cotton seed hulls & 15 sacks cemen Circulated to top & set marker.	ulled out & set ed at 620. Ran 500# t. Tagged at 120.
Squeezed 25 sacks & tagged at 1387. Shot pipe at 900 & p 35 sacks. Tagged plug at 630. Set 35 sacks at 250 & tagg pea gravel & 10 sacks cotton seed hulls & 15 sacks cemen	ulled out & set ed at 620. Ran 500#
Squeezed 25 sacks & tagged at 1387. Shot pipe at 900 & p 35 sacks. Tagged plug at 630. Set 35 sacks at 250 & tagg	ulled out & set ed at 620. Ran 500#
Squeezed 25 sacks & tagged at 1387. Shot pipe at 900 & p	ulled out & set
	•
	•
Set C.T.B.P. & 3 sacks at 228/ & shot nine at 1765 Coul	
•	dnit recover
Open hole from 2334 to 2391.	
8 5/8 surf. set at 207 & circulated. 5 1/2 set at2334 wi	th 200 sacks.
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1 fo3.	estimated date of starting any proposed
OTHER	<u> </u>
CHANGE PLANS CASING TEST AND CEMENT JOB	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPOPAPILY ABANDON COMMENCE DRILLING OPNS.	ALTERING CASING PLUG AND ABANDONMENT
	REPURT OF:
Check Appropriate Box To Indicate Nature of Notice, Report or Oth NOTICE OF INTENTION TO:	
3648 DF	12. County Eddy
THE LINE, SECTION TOWNSHIP RANGE NMPM. 15. Elevation (Show whether DF, RT, CR, etc.)	
W 5 17 29	
UNIT LETTER K . 1650 FEET FROM THE S LINE AND 1650 FEET FROM	CAVE
Box 648 Artesia, N. Mex. 88210	1 24 10, Field and Pool, or Wildeat
JEM Resources Inc. 3. Address of Operator	CAVE POOL 9. Well No.
2. Where of Operator	8. Farm or Lease Farm
1. 0it (AS (7. Unit Agreement Home
SUNDRY NOTICES AND REPORTS ON WELLS (BU NOT USE THIS FORM A IN BURDONAL TO DELLE A PLOG DATE OF THE SERVICE TO SERVICE AND A DIFFERENT RESERVOIR.	
CONTRACTOR OF THE PROPERTY OF	5. State Oil & Gas Leann No. E-10163
LAND OFFICE OPERATOR	State X Fee
U.S.G.S.	5a. Indicate Type of Lease
SANTA FE NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
HO. OF COPIES MECCIVIO DISTRIBUTION	Form C-103 Supersedes Old

CONDITIONS OF APPROVAL, IF ANYI